



Addendum to Recall Campaign #90

04V-114

DATE: April 30, 2004

MODELS


AFFECTED: 2000-2004 Winnebago and Itasca P-series models covered under Recall Campaign 90 – Addition of LP Gas Tank Mounting Cradle Brackets

SUBJECT: Alternate LP Tank Straps

PLEASE FORWARD THIS INFORMATION TO YOUR RV SERVICE MANAGER.

We have become aware of possible variations on some LP gas tanks being fitted with new LP gas tank mounting cradles and straps under Recall Campaign 90. This condition may exist on vehicles equipped with diesel generators.

Due to a variation in tank component locations there may be insufficient clearance between the guard shield (1) and the nearest tank fixture (2) for the proper installation of the 1 1/2" cradle strap (3) supplied in the recall kit, as shown in the photo.



To remedy this condition Manchester, the tank manufacturer, is supplying a 3/4" narrower strap for installation at this location. The narrower strap should be used only in the location as shown in the photo, and only when necessary.

If you need to install a narrow strap, contact Winnebago Part Sales, at 800-556-9670.

Steven R. Evenson
Director of Parts and Service

IMPORTANT THAT ALL PARTS AND SERVICE PERSONNEL READ AND INITIAL

PARTS MANAGER		SERVICE MANAGER		SERVICE PERSONNEL			PARTS PERSONNEL			PAGE	
										1 OF 1	