



U.S. Department  
of Transportation  
  
National Highway  
Traffic Safety  
Administration

400 Seventh Street, SW  
Washington, DC 20590

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION  
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04V-316 by the  
National Highway Traffic Safety Administration

Part 573 Report Date: June 23, 2004

Date Faxed: July 09, 2004

MANUFACTURER: American Suzuki Motor Corp.

MANUFACTURER CONTACT: Kenneth M. Bush, Regulations Manager  
Government Relations Department

FAX: 714-996-9789

SUBJECT: 15 Suzuki 2004 GSX-600FK4 motorcycles are being recalled for fuel leakage from the fuel gauge gasket due to misalignment of the gasket at the time of assembly.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

As stated in your report, dealers and owners will be notified by telephone.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during June 2004. Therefore, the first quarterly report will be due by July 30, 2004.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [Patricia.Wallace@nhtsa.dot.gov](mailto:Patricia.Wallace@nhtsa.dot.gov)  
Recall Management Division