

Safety Recall Quarterly Report Information

Report Date: January 16, 2001

Calendar Quarter: 1

Safety Recall Quarterly Report from October 2000 through December 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW Tie-Rod Ball Sockets

1. NHTSA Safety Recall Campaign No. 00V-246.892¹⁰²
- Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 00KW3
2. (a) The date notification to purchasers began: 10/6/00
- (b) The date notification to purchasers was completed: 10/6/00
3. The total number of items¹ involved: 4826
 The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale: 142
 Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
 Do not include this number in 4(a) or 4(b).
4. (a) Total number inspected & remedied: 831
 Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
- (b) Total number inspected & NOT REQUIRING REMEDY: 852
 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
5. Items Determined to be Unreachable
- Total number exported: 0
- Total number stolen: 0
- Total number scrapped: 0
- Total number unable to notify: 0
- Total number otherwise unreachable: 0
- Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: January 15, 2001

Calendar Quarter: 1

Safety Recall Quarterly Report from October 2000 through December 2000

Manufacturer: PACCAR Inc (Peterbilt)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: 20-EDL Model Ball Sockets

1. NHTSA Safety Recall Campaign No. 00V-246¹⁰²602

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 800-G

2. (a) The date notification to purchasers began: 10/2/00

(b) The date notification to purchasers was completed: 10/2/00

3. The total number of items¹ involved: 1550

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 454

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify:

Total number otherwise unreachable: 3

Describe other:

¹ Items shall refer to the vehicles, parts or equipment or items involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: April 20, 2001

Calendar Quarter: 2

Safety Recall Quarterly Report from January 2001 through March 2001

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW Tie-Rod Ball Sockets

1. NHTSA Safety Recall Campaign No.

¹⁰²
00V-246.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

00KW3

2. (a) The date notification to purchasers began:

10/6/00

(b) The date notification to purchasers was completed:

10/6/00

3. The total number of items¹ involved:

4826

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

213

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied:

1469

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

1385

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported:

0

Total number stolen:

0

Total number scrapped:

0

Total number unable to notify:

0

Total number otherwise unreachable:

0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reported

Safety Recall Quarterly Report Information

Report Date: April 23, 2001

Calendar Quarter: 2

Safety Recall Quarterly Report from January 2001 through March 2001

Manufacturer: PACCAR Inc (Peterbilt)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW 20-EDL Model Ball Sockets

- | | | |
|----|--|--------------------|
| 1. | NHTSA Safety Recall Campaign No. | <u>00V-246-002</u> |
| | Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: | <u>800-G</u> |
| 2. | (a) The date notification to purchasers began: | <u>10/2/00</u> |
| | (b) The date notification to purchasers was completed: | <u>10/2/00</u> |
| 3. | The total number of items ¹ involved: | <u>1497 **</u> |
| | The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer). | |
| | Number of Items Returned from Inventory or Remedied Prior to Sale: | <u>0</u> |
| | Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. | |
| | Do not include this number in 4(a) or 4(b). | |
| 4. | (a) Total number inspected & remedied: | <u>836 **</u> |
| | Total number of items which were inspected and/or otherwise repaired or remedied (cumulative). | |
| | (b) Total number inspected & NOT REQUIRING REMEDY: | <u>0</u> |
| | Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work. | |
| 5. | Items Determined to be Unreachable | |
| | Total number exported: | <u>0</u> |
| | Total number stolen: | <u>0</u> |
| | Total number scrapped: | <u>0</u> |
| | Total number unable to notify: | <u>0</u> |
| | Total number otherwise unreachable: | <u>3</u> |

Describe other: ** Numbers may be lower than previous report due to removal of Canadian vehicles.

¹ Items shall refer to the vehicles, parts or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: July 17, 2001

Calendar Quarter: 3

Safety Recall Quarterly Report from April 2001 through June 2001

Manufacturer: PACCAR, Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW Tie-Rod Ball Sockets

1. NHTSA Safety Recall Campaign No. 00V-246,002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

00KW3

2. (a) The date notification to purchasers began: 10/6/00

(b) The date notification to purchasers was completed: 10/6/00

3. The total number of items¹ involved: 4826

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 213

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 1692
Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 1564
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or items involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: July 20, 2001

Calendar Quarter: 3

Safety Recall Quarterly Report from April 2001 through June 2001

Manufacturer: PACCAR Inc (Peterbilt)

Report Author: Kenneth R. Brownstein Phone (425) 468-7355

Recall Subject: TRW 20-EDL Model Ball Sockets

- | | | |
|----|---|-------------------|
| 1. | NHTSA Safety Recall Campaign No. | <u>00V-246-02</u> |
| | Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: | <u>800-G</u> |
| 2. | (a) The date notification to purchasers began: | <u>10/2/00</u> |
| | (b) The date notification to purchasers was completed: | <u>10/2/00</u> |
| 3. | The total number of items ¹ involved:
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer). | <u>1497</u> |
| | Number of Items Returned from Inventory or Remedied Prior to Sale:
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
Do not include this number in 4(a) or 4(b). | <u>0</u> |
| 4. | (a) Total number inspected & remedied:
Total number of items which were inspected and/or otherwise repaired or remedied (cumulative). | <u>953</u> |
| | (b) Total number inspected & NOT REQUIRING REMEDY:
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work. | <u>82</u> |
| 5. | Items Determined to be Unreachable | |
| | Total number exported: | <u>0</u> |
| | Total number stolen: | <u>0</u> |
| | Total number scrapped: | <u>0</u> |
| | Total number unable to notify: | <u>0</u> |
| | Total number otherwise unreachable: | <u>3</u> |
| | Describe other: | |

¹ Items shall refer to the vehicles, items or equipment or firm involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: October 19, 2001

Calendar Quarter: 4

Safety Recall Quarterly Report from July 2001 through September 2001

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW Tie-Rod Ball Sockets

- | | | |
|----|---|--------------------|
| 1. | NHTSA Safety Recall Campaign No. | <u>00V-246-002</u> |
| | Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: | <u>00KW3</u> |
| 2. | (a) The date notification to purchasers began: | <u>08/28/00</u> |
| | (b) The date notification to purchasers was completed: | <u>10/6/00</u> |
| 3. | The total number of items ¹ involved:
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer). | <u>4826</u> |
| | Number of Items Returned from Inventory or Remedied Prior to Sale:
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
Do not include this number in 4(a) or 4(b). | <u>217</u> |
| 4. | (a) Total number inspected & remedied:
Total number of items which were inspected and/or otherwise repaired or remedied (cumulative). | <u>1780</u> |
| | (b) Total number inspected & NOT REQUIRING REMEDY:
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work. | <u>1650</u> |
| 5. | Items Determined to be Unreachable | |
| | Total number exported: | <u>0</u> |
| | Total number stolen: | <u>0</u> |
| | Total number scrapped: | <u>0</u> |
| | Total number unable to notify: | <u>0</u> |
| | Total number otherwise unreachable: | <u>0</u> |
| | Describe other: _____ | |

¹ Items shall refer to the vehicles, parts or equipment or items involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: October 22, 2001

Calendar Quarter: 4

Safety Recall Quarterly Report from July 2001 through September 2001

Manufacturer: PACCAR Inc (Peterbilt)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW 20-EDL Model Ball Sockets

- | | | |
|----|---|-------------------|
| 1. | NHTSA Safety Recall Campaign No. | <u>00V-246-02</u> |
| | Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: | <u>800-G</u> |
| 2. | (a) The date notification to purchasers began: | <u>10/2/00</u> |
| | (b) The date notification to purchasers was completed: | <u>10/2/00</u> |
| 3. | The total number of items ¹ involved: | <u>1497</u> |
| | <small>The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).</small> | |
| | Number of Items Returned from Inventory or Remedied Prior to Sale: | <u>0</u> |
| | <small>Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.</small> | |
| | <small>Do not include this number in 4(a) or 4(b).</small> | |
| 4. | (a) Total number inspected & remedied: | <u>1027</u> |
| | <small>Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).</small> | |
| | (b) Total number inspected & NOT REQUIRING REMEDY: | <u>211</u> |
| | <small>Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.</small> | |
| 5. | Items Determined to be Unreachable | |
| | Total number exported: | <u>0</u> |
| | Total number stolen: | <u>0</u> |
| | Total number scrapped: | <u>0</u> |
| | Total number unable to notify: | <u>0</u> |
| | Total number otherwise unreachable: | <u>20</u> |
| | Describe other: | |

¹ Items shall refer to the vehicles, buses or equipment or fleet involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: April 11, 2002

Calendar Quarter: 6

Safety Recall Quarterly Report from January 2002 through March 2002

Manufacturer: FACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW Tie-Rod Ball Sockets

1. NHTSA Safety Recall Campaign No.

00V-246-002¹⁰²

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

00KW3

2. (a) The date notification to purchasers began:

10/6/00

(b) The date notification to purchasers was completed:

10/6/00

3. The total number of items¹ involved:

4826

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

218

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied:

1913

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY:

1778

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported:

0

Total number stolen:

0

Total number scrapped:

0

Total number unable to notify:

0

Total number otherwise unreachable:

0

Describe other: _____

¹ Items refer to the vehicles, parts or equipment or items involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: April 8, 2002

Calendar Quarter: 6

Safety Recall Quarterly Report from January 2002 through March 2002

Manufacturer: PACCAR Inc (Peterbilt)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: TRW 20-EDL Modal Ball Sockets

- | | | |
|----|---|--------------------|
| 1. | NHTSA Safety Recall Campaign No. | <u>00V-246,002</u> |
| | Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: | <u>800-G</u> |
| 2. | (a) The date notification to purchasers began: | <u>10/2/00</u> |
| | (b) The date notification to purchasers was completed: | <u>10/2/00</u> |
| 3. | The total number of items ¹ involved:
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer). | <u>1497</u> |
| | Number of Items Returned from Inventory or Remedied Prior to Sale:
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
Do not include this number in 4(a) or 4(b). | <u>0</u> |
| 4. | (a) Total number inspected & remedied:
Total number of items which were inspected and/or otherwise repaired or remedied (cumulative). | <u>1077</u> |
| | (b) Total number inspected & NOT REQUIRING REMEDY:
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work. | <u>291</u> |
| 5. | Items Determined to be Unreachable | |
| | Total number exported: | <u>0</u> |
| | Total number stolen: | <u>0</u> |
| | Total number scrapped: | <u>0</u> |
| | Total number unable to notify: | <u>0</u> |
| | Total number otherwise unreachable: | <u>20</u> |
| | Describe other: | |

¹ Items shall refer to the vehicles, units or equipment or fleet involved in the safety recall on which you are reporting.