



Foretravel, Inc.

1221 N. Spillings Drive
Wesley, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

January 11, 2001

Mr. Kenneth N. Weinstein, Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
400 7th Street, SW
Washington, D.C. 20590

Re.: NHTSA Safety Recall Campaign Number: ^{001-246.310}~~80E-047~~

Dear Mr. Weinstein:

Pursuant per 49 CFR Part 573.6 is the Vehicle Safety Quarterly Report Information for the aforementioned NHTSA Safety Recall.

If you have any questions whatsoever, please feel free to contact me at: (800) 955-6226; Extension #254. Also, my FAX number is: (936) 564-8935.

Sincerely,

Michael C. Packard
Director of Warranty and Service

Enclosure



Foretravel, Inc.

1277 N. Williams Drive
Weslaco, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION

Required per 49 CFR Part 573.6
NHTSA ASSIGNED RECALL # 00E047

Report Date: January 11, 2001 Calendar Quarter: 4th - 2000 (1st Report)

Safety Recall Quarterly Report from October 1, 2000 through December 31, 2000

Manufacturer: Foretravel, Incorporated

Report Author: Michael C. Packard Phone: (936) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.

1. NHTSA Safety Recall Campaign Number: ~~00E-047~~ *Gov-246. J10*
2. (a) The date notification to purchasers began: November 13, 2000
(b) The date notification of purchasers was completed: November 20, 2000
3. The Total Number of Vehicles Involved: 76
4. (a) Total Number Inspected and Remedied: 12
(b) Total Number Inspected and NOT REQUIRING REMEDY: 14
5. Vehicles Determined to be Unreachable: 0

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: N/A



Foretravel, Inc.

1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

April 24, 2001

**Mr. Kenneth N. Weinstein, Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
400 7th Street, SW
Washington, D.C. 20590**

Re.: NHTSA Safety Recall Campaign Number: 00E-047

Dear Mr. Weinstein:

**Pursuant per 49 CFR Part 573.6 is the Vehicle Safety Quarterly Report Information
for the aforementioned 00E-047 NHTSA Safety Recall.**

**If you have any questions whatsoever, please feel free to contact me at: (800) 955-
6226; Extension #254. Also, my FAX number is: (936) 564-8935.**

Sincerely,

**Michael C. Packard
Director of Warranty and Service**

Enclosures



Foretravel, inc.

1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION
Required per 49 CFR Part 573.6

Report Date: April 24, 2001 Calendar Quarter: 1st—2001—(2nd Report)

Safety Recall Quarterly Report from January 1, 2001 through March 31, 2001

Manufacturer: Foretravel Incorporated

Report Author: Michael C. Packard Phone: (936) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.

1. NHTSA Safety Recall Campaign Number: 00E-047-00V-246.310

2. (a) The date notification to purchasers began: November 13, 2000

(b) The date notification of purchasers was completed: November 20, 2000

3. The Total Number of Vehicles Involved: 76

4. (a) Total Number Inspected and Remedied: 15

(b) Total Number Inspected and NOT REQUIRING REMEDY: 31

5. Vehicles Determined to be Unreachable:

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Unreachable: 0

Describe Other: N/A



Foretravel, Inc.

1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION
Required per 49 CFR Part 573.6

Report Date: June 24, 2001 Calendar Quarter: 2nd—2001—(3rd Report)

Safety Recall Quarterly Report from April 1, 2001 through June 30, 2001

Manufacturer: Foretravel Incorporated

Report Author: Michael C. Packard Phone: (936) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.

- 1. NHTSA Safety Recall Campaign Number: 00E-047**
- 2. (a) The date notification to purchasers began: November 13, 2000**
(b) The date notification of purchasers was completed: November 20, 2000
- 3. The Total Number of Vehicles Involved: 76**
- 4. (a) Total Number Inspected and Remedied: 16**
(b) Total Number Inspected and NOT REQUIRING REMEDY: 52

5. Vehicles Determined to be Unreachable:

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Unreachable: 0

Describe Other: N/A

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION
Required per 49 CFR Part 573.6

Report Date: October 8, 2001 Calendar Quarter: 3rd—2001—(4th Report)

Safety Recall Quarterly Report from July 1, 2001 through September 30, 2001

Manufacturer: Foretravel Incorporated

Report Author: Michael C. Packard Phone: (936) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.

1. **NHTSA Safety Recall Campaign Number: 00E-047—TRW
00V-246—Foretravel
310**
2. (a) **The date notification to purchasers began: November 13, 2000**

(b) **The date notification of purchasers was completed: November 20, 2000**
3. **The Total Number of Vehicles involved: 113**
4. (a) **Total Number Inspected and Remedied: 16**

(b) **Total Number Inspected and NOT REQUIRING REMEDY: 57**
5. **Vehicles Determined to be Unreachable:**

Total Number Exported: 0

Total Number Stolen: 0

Foretravel, Inc.

1221 NW Stallings Drive
Harcodoches, Texas 75964
936.564.8387 Fax 936.564.0301
www.foretravel.com

Total Number Scrapped: 0

Total Number Unable to Notify: 1

Total Number Unreachable: 0

Describe Other: N/A

M O T O R H O M E S O F D I S T I N C T I O N



1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION
Required per 49 CFR Part 573.6

Report Date: January 14, 2002 Calendar Quarter: 4th—2001—(5th Report)

Safety Recall Quarterly Report from October 1, 2001 through December 31, 2001

Manufacturer: Foretravel Incorporated

Report Author: Michael C. Packard Phone: (936) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.


1. **NHTSA Safety Recall Campaign Number: 00E-047-TRW
00V-246-Foretravel
310**
2. (a) **The date notification to purchasers began: November 13, 2000**

(b) **The date notification of purchasers was completed: November 20, 2000**
3. **The Total Number of Vehicles Involved: 113**
4. (a) **Total Number Inspected and Remedied: 16**

(b) **Total Number Inspected and NOT REQUIRING REMEDY: 78**
5. **Vehicles Determined to be Unreachable:**

Total Number Exported: 0

Total Number Stolen: 0



Foretravel, Inc.

1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

Total Number Scrapped: 0

Total Number Unable to Notify: 1

Total Number Unreachable: 0

Describe Other: N/A

M O T O R H O M E S O F D I S T I N C T I O N



1221 NW Stallings Drive
Nacogdoches, Texas 79964
936.564.8367 Fax 936.564.0391
www.foretravel.com

VEHICLE SAFETY RECALL QUARTERLY REPORT INFORMATION
Required per 49 CFR Part 573.6

Report Date: April 11, 2002 Calendar Quarter: 1st--2002--(6th Report)

Safety Recall Quarterly Report from January 1, 2002 through March 31, 2002

Manufacturer: Foretravel Incorporated

Report Author: Michael C. Peckard Phone: (836) 564-8367; Extension #254

Recall Subject: Foretravel motorhomes equipped with TRW Commercial Steering Systems (TRW 2-EDL) model ball-sockets supplied to ArvinMeritor, the company that assembles and supplies the front axle assemblies for the Foretravel Class "A" motorhomes. The defect is that on some applications, the ball-socket assemblies may separate due to premature wear.

- 1. NHTSA Safety Recall Campaign Number: 00E-047-TRW
00V-246-Foretravel**
- 2. (a) The date notification to purchasers began: November 13, 2000**
(b) The date notification of purchasers was completed: November 20, 2000
- 3. The Total Number of Vehicles Involved: 113**
- 4. (a) Total Number Inspected and Remedied: 16**
(b) Total Number Inspected and NOT REQUIRING REMEDY: 81
- 5. Vehicles Determined to be Unreachable:**
Total Number Exported: 0
Total Number Stolen: 0



1221 NW Stallings Drive
Nacogdoches, Texas 75964
936.564.8367 Fax 936.564.0391
www.foretravel.com

Total Number Scrapped: 0

Total Number Unable to Notify: 1

Total Number Unreachable: 0

Describe Other: N/A

M O T O R H O M E S O F D I S T I N C T I O N