

View Message

Sent On 08 03 2004 Expires On 08 13 2004
From MOTORCYCLE SERVICE NATIONAL
Subject 2003/2004 CBR600RR REAR BRAKE LINKAGE

August 3, 2004

Dear Honda Dealer:

SAFETY RECALL NOTICE
RE: 2003/2004 CBR600RR Rear Brake Linkage

AFFECTED UNITS:
All 2003 and 2004 Model Year Honda CBR600RR

American Honda is conducting an important SAFETY RECALL on all 2003 and 2004 Honda CBR600RR. The recall procedure will replace parts of the Rear Brake Linkage. Under certain circumstances the pushrod and/or the tie rod bushing in the rear brake master cylinder can become corroded thereby effecting rear brake function. No failures have been reported in the US market.

Effective immediately, YOU MUST NOT SELL any affected CBR600RR in your inventory until the required repair has been completed. Please make sure ALL DEPARTMENTS in your dealership, Parts, Sales, and Service, are made aware of this action. Any sale of an affected motorcycle after receiving this notice and prior to the required repair is a violation of Federal law.

The instructions and procedures necessary to repair the affected CBR600RRs currently in your inventory will be available on *IN* beginning Friday the 6th of August. Parts as required to perform repairs will be automatically shipped to your dealership using our sales records, later this week.

If you have recently sold a CBR600RR, please submit the warranty registration information. If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Thank you for your cooperation.
American Honda Motor Co., Inc.

Robert E. Clever
Senior Manager – Service
Motorcycle Division

Bulletin #04-0461

© 2000–2004, American Honda Motor Co., Inc. All Rights Reserved.

View Message

Sent On

08	08	2004
----	----	------

 Expires On


08	15	2004
----	----	------

From

MOTORCYCLE SALES NATIONAL

Subject

SAFETY RECALL: 2003-2004 CBR800RR REAR BRAKE LINKAGE SERVICE BU



1700 S. ...

August 6, 2004

Today a new **SAFETY RECALL Service Bulletin** for the 2003/2004 CBR800RR Rear Brake Linkage is posted on the Interactive Network (IN).

The bulletin describes the procedures to inspect and replace the rear brake linkage. Three printed copies and your Dealer Responsibility Report will be mailed to you next week.

Please be sure all personnel in your dealership are aware of this important **CBR800RR SAFETY RECALL**.

[Click here for Service Bulletin CBR800RR #1](#)

Sincerely,
American Honda Motor Co., Inc.

Douglas T. McIntyre
Manager,
Motorcycle Service Education.

Bulletin Number: 04-0488

© 2000-2004, American Honda Motor Co., Inc. All Rights Reserved.

August 2004

Dear Honda Dealer:

RE: SAFETY RECALL – 2003-2004 CBR600RR Rear Brake Linkage

DEALER RESPONSIBILITY REPORT (Service Bulletin CBR600RR #1)

The enclosed Campaign Responsibility Report for the 2003-2004 CBR600RR shows the VINs that were either sold by your dealership or are still in your inventory. All sold units that have been warranty-registered with American Honda show the customer's most current name and address.

Please review the report to ensure that any CBR600RR listed is in your inventory, or contact the customer so an appointment can be made to have the replacement completed. For your information, the report codes in the "UNIT STAT" column mean:

02 = In your inventory; perform the Repair as necessary.

FX = Repair has been performed.

NR = Customer mailing returned as undeliverable. If you have an alternate means of contacting the customer, please do so.

blank = Customer already notified; no action necessary.

- For each unit shown in your inventory (code 02), but already sold, notify the owner and arrange to perform the Repair.
- Reminder: If you have not yet warranty-registered a sold unit, please do so now.

If you have completed any repairs for which you have not yet submitted warranty claims, please do so as quickly as possible. This is necessary for our tracking purposes. If you have any questions, please contact your District Service Manager.

Regards,

American Honda Motor Co., Inc.



Silvio Carrara
Vice President – Service
Motorcycle Division

Bulletin Number	Page	File Behind Dealer Guide Bulletin Tab
04-0469	1 of 1	Service

View Message

Sent On 08 30 2004 Expires On 09 06 2004
From MOTORCYCLE SERVICE NATIONAL
Subject 2003/2004 CBR600RR REAR BRAKE LINKAGE

August 30, 2004

Dear Honda Dealer:

**SAFETY RECALL NOTICE
RE: 2003/2004 CBR600RR Rear Brake Linkage**

**AFFECTED UNITS:
All 2003 and 2004 Model Year Honda CBR600RR**

American Honda is conducting an important SAFETY RECALL on all 2003 and 2004 Honda CBR600RRs. The recall procedure will replace parts of the Rear Brake Linkage. Under certain circumstances, the pushrod and/or the tie rod bushing in the rear brake master cylinder can become corroded thereby affecting the rear brake function. There have been no reported failures in the US market to date.

To continue repairs on the affected CBR600RRs in your inventory, a second shipment of parts has been shipped to your dealership according to our sales records for this model. These parts will arrive on beginning Tuesday August 31st.

As a reminder the Service Bulletin for this action is currently in your dealership and also available on *IN*. If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

**Thank you for your cooperation.
American Honda Motor Co., Inc.**

**Robert E. Clever
Senior Manager – Service
Motorcycle Division**

Bulletin #04-0532

© 2000–2004, American Honda Motor Co., Inc. All Rights Reserved.