



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

SEP 24 2004

400 Seventh Street, S.W.
Washington, D.C. 20590

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04V-469 by the
National Highway Traffic Safety Administration

Part 573 Report Date: September 17, 2004

Date Faxed: September 24, 2004

MANUFACTURER: IC CORPORATION

MANUFACTURER CONTACT: ROBERT L. DOUGLAS

FAX: 501-505-2185

SUBJECT: 1,220 MY 2001-2005 AMTRAN/IC CORPORATION CE, FE, AND RE SCHOOL BUSES EQUIPPED WITH SURE-LOK WHEELCHAIR TIE-DOWN SECUREMENT ASSEMBLIES P/N 8625-13. THE SPROCKET TEETH OF THE RETRACTOR ASSEMBLY MAY BE OUT OF ALIGNMENT CAUSING THE LOAD PAWL NOT TO FULLY SEAT IN THE SPROCKET TEETH.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

NOTIFICATION TO PURCHASERS

It is our understanding that Sure-Lok is notifying IC's customers and will be providing quarterly status reports for this recall. Therefore, it will not be necessary for IC to submit quarterly status reports as long as Sure-Lok's campaign is successful.

If you have any questions, please call:

Kelly Schuler, Safety Defect Analyst or George Person, Chief
at (202) 366-5227 or by FAX (202) 366-7882
Recall Management Division
kschuler@nhtsa.dot.gov



DOT AUTO SAFETY HOTLINE
888-DASH-2-DOT
888-327-4236