



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh Street, SW
Washington, DC 20590

**ACKNOWLEDGEMENT FAX SHEET OF RECEIPT OF DEFECT
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04V-475 by the
National Highway Traffic Safety Administration

Part 573 Report Date: **September 27, 2004**

Date Faxed/E-Mailed: **October 6, 2004**

MANUFACTURER: **Yamaha Motor Corporation**

MANUFACTURER CONTACT: **Russell D. Jura, Senior Vice President and General Counsel**

FAX: **714-761-7836**

SUBJECT: **3,620 Yamaha 2005 XT225T/C, XV250T/C and YW50T motorcycles and scooters. The rear brake shoe material on the metal brake shoe could separate due to improper adhesive curing.**

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

I have reviewed your proposed owner letter and it meets the requirements of Part 577.

Please let me know the date when the actual mailing takes place and, as usual, provide this office with final copies of all documents relating to the recall.

NOTE: We will need a date of when Yamaha became aware of the problem and the beginning and ending manufacturing dates for the motorcycles/scooters involved or should we use the August-September 2004 date.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. The recall is expected to begin during October 2004. Therefore, the first quarterly report will be due by January 30, 2005.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at Patricia.Wallace@nhtsa.dot.gov
Recall Management Division