

Country
State

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, September 26, 2001 6:12 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 Update.

To: All Service and Parts Managers

Ref: Auxiliary/Cooling Fan Recall Campaign 01V-206 Update.

Here is the latest news concerning the above recall:

· The final version of Service Information Bulletin 64 07 01 has been posted on BMWTIS.NET today.

· All vehicles that previously had the recall performed (with the old part numbers) will receive new customer letters. E46 vehicles that have had the part number 17 11 7 510 617 installed are not subject to any further recall actions. All other vehicle VIN ranges are being expanded.

· The first mailing of recall letters will occur by the end of this week. The centers will be notified via a separate DCS message.

· All initial automatic parts shipments of new part numbers have been processed. Orders from these shipments should arrive at your centers by end of this week. If you are not sure how many fans were shipped to your center please call the PCG at 1-800-272-0202.

· Currently, center may order additional fans using the vehicle VIN. If the VIN is within the original customer VIN mailings the order will be released automatically. If the VIN is outside the customer VIN mailing ranges the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

· When the new customer mailing occurs we will inform you of the VIN's involved and immediately switch to the new customer mailed VIN's for automatic release of orders placed by the centers. If the VIN is outside the customer VIN mailing list the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order. AT THAT TIME, WE WILL NO LONGER AUTOMATICALLY RELEASE ORDERS FOR CUSTOMER MAILINGS THAT OCCURRED PRIOR TO THIS WEEK.

· Remember, there is only one week left on TECH6 (ends October 5, 2001) to return your old stock of Auxiliary/Cooling Fans.

Thank you for your cooperation.

Aftersales Logistics.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	LX	Market Area

Scully, William ZU-A-21

From: Parts Logistics [PRTSLOG@dealers.bmwna.com]
Sent: Thursday, September 27, 2001 8:02 AM
To: DCS 2000 Server
Subject: Auxiliary Fans

To: All Service and Parts Managers

Ref: Auxiliary/Cooling Fan Recall Campaign 01V-206 Update.

Here is the latest news concerning the above recall:

- The final version of Service Information Bulletin 64 07 01 has been posted on BMWFIS.NET today.
- All vehicles that previously had the recall performed (with the old part numbers) will receive new customer letters. E46 vehicles that have had the part number 17 11 7 510 617 installed are not subject to any further recall actions. All other vehicle VIN ranges are being expanded.
- The first mailing of recall letters will occur by the end of this week. The centers will be notified via a separate DCS message.
- All initial automatic parts shipments of new part numbers have been processed. Orders from these shipments should arrive at your centers by end of this week. If you are not sure how many fans were shipped to your center please call the PCG at 1-800-272-0202.
- Currently, center may order additional fans using the vehicle VIN. If the VIN is within the original customer VIN mailings the order will be released automatically. If the VIN is outside the customer VIN mailing ranges the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.
- When the new customer mailing occurs we will inform you of the VIN's involved and immediately switch to the new customer mailed VIN's for automatic release of orders placed by the centers. If the VIN is outside the customer VIN mailing list the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order. **AT THAT TIME, WE WILL NO LONGER AUTOMATICALLY RELEASE ORDERS FOR CUSTOMER MAILINGS THAT OCCURRED PRIOR TO THIS WEEK.**
- Remember, there is only one week left on TECH6 (ends October 5, 2001) to return your old stock of Auxiliary/Cooling Fans.

Thank you for your cooperation.

Aftersales Logistics.

Distribution:

Department	X	All Departments
Title	M	All Managers
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, September 28, 2001 4:11 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 Update

To: All Service & Parts Managers

Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update

As per the DCS message from September 26, 2001, we will be providing to you the customer mailed letter VIN listing. These VIN's will be activated for automatic release of center-entered orders on Monday October 1, 2001.

Only VIN specific center-entered orders from within the list will be automatically released. VIN ranges published prior to this will no longer receive automatic allocation. This means that if you have an existing VIN specific order for the old VIN ranges you must call the PCG for release. If the VIN is outside the customer VIN mailing listing, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

This VIN listing may also be found on EMWTIS.NET as an attachment to Service information Bulletin 64 07 01 and Parts Bulletin 64 01 01. As new VIN customer letter mailings occur we will revise this bulletin and inform the centers via DCS message.

Please read this bulletin carefully. We encourage you to access it through EMWTIS.NET as soon as possible. This will give you the information much sooner than waiting for the paper version to be mailed to your center.

We appreciate your patience and cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, September 20, 2001 12:50 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

To: All Parts and Service managers
Re: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

Today your Service Department will receive an ADVANCE SERVICE INFORMATION notifying you that Recall Campaign 01V-206, Engine Auxiliary/Cooling Fan will be revised. As a result, new part numbers have been issued and these new numbers supercede those used in the current campaign. Below is a listing of the new part numbers:

Series	-----	Old Part Number	-----	New Part Number
E46	-----	17 11 7 516 813	-----	17 11 7 510 617
E38	-----	64 54 6 919 053	-----	64 54 6 921 383
E39	-----	64 54 6 919 057	-----	64 54 6 921 395
E52	-----	64 54 6 919 053	-----	64 54 6 921 383
E53	-----	64 54 6 919 051	-----	64 54 6 921 381

An initial shipment of the new part numbers will be sent to each center, with the exception of the E46, for which you have already been ordering the new part number. We will stagger shipments of the new numbers for the E38/E52, E39, and E53, due to the initial limited parts supply. Please only use these new fans to repair: in stock vehicles before they are retailed, vehicle for which customers present recall notification letters, and vehicles with fan failures.

After the initial inventory of the new fans is depleted, centers should only place orders using the new part numbers, for vehicles that are off the road due to a fan failure, or if a customer presents a recall notification letter. All orders must be placed as VIN specific single-line orders. These orders must coincide with the VIN ranges that have been previously issued. Centers will be notified once new VIN ranges are issued. Fax orders, non-VIN specific orders, and multiple quantity orders will not be accepted. Anything other than VIN specific orders will be cancelled.

DO NOT ORDER THE PARTS FOR STOCKING PURPOSES. These parts will not be accepted for return via AFA, 90-day return, or obsolescence.

PLEASE PLACE ORDERS FOR VEHICLES OUTSIDE THE SPECIFIC VIN RANGES AND THEN CONTACT THE PARTS CONSULTANT GROUP AT 1-800-272-0202, TO GET THE PARTS RELEASED.

Effective immediately do not use any of the old part numbers in any vehicles. These parts may be returned to your facing PDC using the standard return section of the dealer return system, using the return reason code Tech6.

We realize that this situation has not been easy on you and our customers, and we will make every attempt to improve the situation.

Thank you for your cooperation.

Aftersales Logistics

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, September 20, 2001 1:24 PM
To: DCS 2000 Server
Subject: TECH6 - Return of Auxiliary/Cooling Fans

Importance: High

To: All Parts Managers,

Subject: TECH6 - Return of Auxiliary/Cooling Fans

Due to design revisions on the recall fans, please return all inventory of the following part numbers:

17 11 7 516 813
64 54 6 919 053
64 54 6 919 057
64 54 6 919 051

These auxiliary/cooling fans should be returned to your facing Part Distribution Center (PDC) using the standard return section of the Dealer Return System (DRS) using the return reason code TECH6.

Only these part numbers should be returned under this code. A delivery note number is not required, but the delivery note field must be filled in (all zeros can be used). Please do not attempt to submit multiple return types with a TECH6 return.

TECH6 IS VALID FROM SEPTEMBER 20, 2001 THROUGH OCTOBER 5, 2001 (TWO WEEKS ONLY). THESE PARTS WILL BE RETURNED TO THE VENDOR FOR REVISION AND RESALE.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Friday, September 21, 2001 4:17 PM
To: DCS 2000 Server
Subject: Recall Campaign 01V-206

Please note that SI 64 07 01 has been posted on BMWIS.NET this morning. This bulletin contains very important information on Recall Campaign 01V-206, Engine Auxiliary/Cooling Fan-E46, E38,E39,E52,E53. Please ensure that your entire Service Dept. staff is familiar with the contents of that bulletin.

Distribution:

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, September 21, 2001 3:33 PM
To: DCS 2000 Server
Subject: Parts Locator: 99 0 0 001 690

From: Dan Thomas, BMW of the Tri-State, Cincinnati, Ohio

Re: Part Search

Am looking for two (2) of p/n 99 00 0 001 690, K1200LT "T" shirt, XLG. If available, please call me at 1-800-601-5941. Thank you.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	B	Bike
Dealer Number		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Monday, September 24, 2001 9:28 AM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

To: All Parts and Service managers
Re: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

Today your Service Department will receive an ADVANCE SERVICE INFORMATION notifying you that Recall Campaign 01V-206, Engine Auxiliary/Cooling Fan will be revised. As a result, new part numbers have been issued and these new numbers supersede those used in the current campaign. Below is a listing of the new part numbers:

Series	-----	Old Part Number	-----	New Part Number
E46	-----	17 11 7 516 813	-----	17 11 7 510 617
E38	-----	64 54 6 919 053	-----	64 54 6 921 383
E39	-----	64 54 6 919 057	-----	64 54 6 921 395
E52	-----	64 54 6 919 053	-----	64 54 6 921 383
E53	-----	64 54 6 919 051	-----	64 54 6 921 381

An initial shipment of the new part numbers will be sent to each center, with the exception of the E46, for which you have already been ordering the new part number. We will stagger shipments of the new numbers for the E38/E52, E39, and E53, due to the initial limited parts supply. Please only use these new fans to repair: in stock vehicles before they are retailed, vehicle for which customers present recall notification letters, and vehicles with fan failures.

After the initial inventory of the new fans is depleted, centers should only place orders using the new part numbers, for vehicles that are off the road due to a fan failure, or if a customer presents a recall notification letter. All orders must be placed as VIN specific single-line orders. These orders must coincide with the VIN ranges that have been previously issued. Centers will be notified once new VIN ranges are issued. Fax orders, non-VIN specific orders, and multiple quantity orders will not be accepted. Anything other than VIN specific orders will be cancelled.

DO NOT ORDER THE PARTS FOR STOCKING PURPOSES. These parts will not be accepted for return via AFA, 90-day return, or obsolescence.

PLEASE PLACE ORDERS FOR VEHICLES OUTSIDE THE SPECIFIC VIN RANGES AND THEN CONTACT THE PARTS CONSULTANT GROUP AT 1-800-272-0202, TO GET THE PARTS RELEASED.

Effective immediately do not use any of the old part numbers in any vehicles. These parts may be returned to your facing PDC using the standard return section of the dealer return system, using the return reason code Tech6.

We realize that this situation has not been easy on you and our customers, and we will make every attempt to improve the situation.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
FDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Monday, September 24, 2001 10:25 AM
To: DCS 2000 Server
Subject: TECH6 - Return of Auxiliary/Cooling Fans- Third Posting

To: All Parts Managers,

Subject: TECH6 - Return of Auxiliary/Cooling Fans - Third Posting

Due to design revisions on the recall fans, please return all inventory of the following part numbers:

17 11 7 516 813
64 54 6 919 053
64 54 6 919 057
64 54 6 919 051

These auxiliary/cooling fans should be returned to your facing Part Distribution Center (PDC) using the standard return section of the Dealer Return System (DRS) using the return reason code TECH6.

Only these part numbers should be returned under this code. A delivery note number is not required, but the delivery note field must be filled in (all zeros can be used). Please do not attempt to submit multiple return types with a TECH6 return.

TECH6 IS VALID FROM SEPTEMBER 20, 2001 THROUGH OCTOBER 5, 2001 (TWO WEEKS ONLY). THESE PARTS WILL BE RETURNED TO THE VENDOR FOR REVISION AND RESALE.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	KX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

number is not required, but the delivery note field must be filled in (all zeros can be used). Please do not attempt to submit multiple return types with a TECH6 return.

TECH6 IS VALID FROM SEPTEMBER 20, 2001 THROUGH OCTOBER 5, 2001 (TWO WEEKS ONLY). THESE PARTS WILL BE RETURNED TO THE VENDOR FOR REVISION AND RESALE.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	AUTO
Dealer Number		
Division	UK	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Monday, September 24, 2001 9:29 AM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

To: All Parts and Service managers
Re: Auxiliary/Cooling Fan Recall Affecting E46, E38, E39, E52 & E53

Today your Service Department will receive an ADVANCE SERVICE INFORMATION notifying you that Recall Campaign 01V-206, Engine Auxiliary/Cooling Fan will be revised. As a result, new part numbers have been issued and these new numbers supercede those used in the current campaign. Below is a listing of the new part numbers:

Series	-----	Old Part Number	-----	New Part Number
E46	-----	17 11 7 516 813	-----	17 11 7 510 617
E38	-----	64 54 6 919 053	-----	64 54 6 921 383
E39	-----	64 54 6 919 057	-----	64 54 6 921 395
E52	-----	64 54 6 919 053	-----	64 54 6 921 383
E53	-----	64 54 6 919 051	-----	64 54 6 921 381

An initial shipment of the new part numbers will be sent to each center, with the exception of the E46, for which you have already been ordering the new part number. We will stagger shipments of the new numbers for the E38/E52, E39, and E53, due to the initial limited parts supply. Please only use these new fans to repair: in stock vehicles before they are retailed, vehicle for which customers present recall notification letters, and vehicles with fan failures.

After the initial inventory of the new fans is depleted, centers should only place orders using the new part numbers, for vehicles that are off the road due to a fan failure, or if a customer presents a recall notification letter. All orders must be placed as VIN specific single-line orders.

These orders must coincide with the VIN ranges that have been previously issued. Centers will be notified once new VIN ranges are issued. Fax orders, non-VIN specific orders, and multiple quantity orders will not be accepted. Anything other than VIN specific orders will be cancelled.

DO NOT ORDER THE PARTS FOR STOCKING PURPOSES. These parts will not be accepted for return via AFA, 90-day return, or obsolescence.

PLEASE PLACE ORDERS FOR VEHICLES OUTSIDE THE SPECIFIC VIN RANGES AND THEN CONTACT THE PARTS CONSULTANT GROUP AT 1-800-272-0202, TO GET THE PARTS RELEASED.

Effective immediately do not use any of the old part numbers in any vehicles. These parts may be returned to your facing PDC using the standard return section of the dealer return system, using the return reason code Tech6.

We realize that this situation has not been easy on you and our customers, and we will make every attempt to improve the situation.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Monday, September 24, 2001 9:16 AM
To: DCS 2000 Server
Subject: Coded parts orders transmitted to BMW AG via DCS Friday, September 21, 2001

From: Walter Ford, Parts Logistics

Following is a list of coded parts orders transmitted to BMW AG via DCS on Friday, September 21, 2001:

Turn-around time for orders filled in Tennessee: 24 to 48 hours. All others: 5 to 7 working days.

04251-32320002723-FM21337	TENN	20721-32310002737-FM01189	TENN
56000-32320002723-AU39720	TENN		
04251-32320002738-DB67967	TENN	21234-32320002723-ET07620	TENN
56568-51218199915-EH00456			
04355-51248166688-DM02900		21295-32310002737-FL05907	TENN
56770-51218199916-EF35621			
04444-32320002738-DE87581	TENN	21295-51218199915-FL05907	

Scully, William ZU-A-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Thursday, November 29, 2001 4:26 PM
To: DCS 2000 Server
Subject: Status Update on Recall 01V-206, Auxiliary Fan, SIB 64 07 01

To: All BMW Center Parts and Service Managers

Re: Status Update on Recall 01V-206, Auxiliary Fan, SIB 64 07 01

An additional 12,000 Recall Notification letters were mailed today to owners of X5 & 7 series vehicles.

This completes the mailings to all vehicles affected by this recall campaign.

An updated version of SI 64 07 01 will be loaded onto bmwtis.net on Friday, 11/30.

Orders for replacement fans for the Z8, 3, 5, X5, & 7 series vehicles are not restricted.

Thank you again for your cooperation.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Wednesday, November 14, 2001 4:04 PM
To: DCS 2000 Server
Subject: Status Update on Recall 01V-206, Auxillary Fan, SIB 64 07 01

To: All BMW Center Parts and Service Managers

Re: Status Update on Recall 01V-206, Auxiliary Fan, SIB 64 07 01

An additional 35,000 Recall Notification letters were mailed yesterday to owners of X5, 3, 5, & 7 series vehicles. This completes the mailings to the 3 & 5 series vehicles. 28 mailings were completed previously.

The chassis number ranges for the Z8, 3, 5 and 7 series vehicles can be found in SIB 64 07 01. Orders for replacement fans for the Z8, 3, 5, & 7 series vehicles are not restricted.

Restrictions still apply to the X5 auxiliary fans (P/N 64 54 6 921 381). Chassis number specific, center-entered orders are still required. If the chassis number of the vehicle is on the list of notified vehicles attached to SIB 64 07 01, the part will be released automatically. If the chassis number is not on this list, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

Thank you for your cooperation.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		
Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Country
State

Scully, William ZU-A-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Thursday, December 06, 2001 12:39 PM
To: DCS 2000 Server
Subject: Auxiliary Fan Recall 01V-206-SI Bulletin 64 07 01

To: All BMW Center Parts and Service Managers

Re: Auxiliary Fan Recall Campaign 01V-206, Service Information Bulletin 64 07 01

With the mailing of the customer notification letters being completed, we ask that you contact your customers that have not yet scheduled the repair, encouraging them to have the repairs made immediately. Please maximize your workshop capacity to accommodate these customers without delay. We now have sufficient quantities of replacement fans in inventory at our Parts Distribution Centers to support these activities, and all order restrictions have been removed.

An easy way to determine which customers of yours still need this campaign to be performed (as of the first of the month) is to utilize the "Campaign Information" report in the DCS Warranty Composite. This will provide you with a listing of the chassis numbers of the vehicles sold by your center that have not had this campaign performed.

Claim submission immediately upon completing the recall is also requested permitting a more accurate database for a second mailing of the recall and to permit scrapping of the replaced fans upon receipt of the credit note.

Thank you again for your cooperation.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Friday, July 27, 2001 5:13 PM
To: DCS 2000 Server
Subject: Engine Auxiliary/Cooling Fan Recall 01V-206

Importance: High

Re: Engine Auxiliary/Cooling Fan Recall 01V-206

As mentioned in our DCS message dated 7-25-2001, the range of vehicles affected by the recall campaign to replace the engine auxiliary/cooling fan has been expanded.

Depending on the vehicle type and/or its production date, the checking procedure will be different. Because of this, two separate Service Information Bulletins have been prepared which reflect these differences.

A DCS vehicle history report must be performed on each affected vehicle to determine its appropriate checking procedure/SIB.

These two Service Information Bulletins are now available on the TIS website; they describe the appropriate repair procedure for the vehicle being repaired:

SIB 64 06 01 (new) covers the checking/repair procedure for:

E39 (5 Series) vehicles produced 01/16/2001 - 06/18/2001
E53 (X5) vehicles produced 05/01/2001 - 06/18/2001

The checking procedure on these vehicles requires the auxiliary fan to be removed and its production date checked.

These checks/repairs will be claimed for via Campaign Entry using a new Defect Code, 00 64 33 01 00.

SIB 64 05 01 (revised) reflects the expanded ranges of affected vehicles as follows:

E46 (3 Series) vehicles produced 02/01/2001 - 05/14/2001 (previously 02/01/2001 - 04/30/01) manual transmission vehicles only

E52 (Z8) vehicles produced 01/01/2001 - 05/31/2001 (previously 01/01/2001 - 04/30/2001)

The range of E38 (7 Series) vehicles affected by this campaign remains the same (11/01/2000 - 01/08/2001).

The range of E53 (X5) vehicles which require the checking procedure as described in this SIB remains the same (12/18/2000 - 04/30/2001)

The checking procedure on these vehicles requires that only the part number of the installed auxiliary fan be checked, and the fan replaced if necessary.

Distribution:

Scully, William V4-ZU-S-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Monday, July 30, 2001 3:17 PM
To: DCS 2000 Server
Subject: Engine Auxillary/Cooling Fan Recall

01V-206

Re: Engine Auxiliary/Cooling Fan Recall

Customer Notification Letters are being mailed today to the owners of all 7 Series vehicles affected by this recall (approx. 2600 vehicles).

VIN specific orders placed for vehicles within the indicated ranges will be released automatically.

No other action is required by the center to order parts for these vehicles.

The chassis number ranges for these vehicles are:

DD74561 to DD74648

DE35040 to DE35041

DN85210 to DN85835

DP25926 to DP27906

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
FDC		
Country		
State		

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
FDC		
Country		
State		

State

Scully, William V4-ZU-S-21

From: National Automotive Sales [natsls@dealers.bmwna.com]
Sent: Friday, July 27, 2001 10:30 AM
To: DCS 2000 Server
Subject: September Allocation Report has been Updated.

Please be advised that the September Allocation Report has been updated this morning (July 27) due to a system error that occurred a few days ago. We ask that you reprint the September Allocation report from today if it was printed previously.

We apologize for any inconvenience this may have caused you.

Sincerely,

BMW of North America, LLC
Automotive Sales Department
Woodcliff Lake, NJ

Distribution:

Department	S	Sales Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
FDC		
Country		
State		

Scully, William V4-ZU-S-21

From: DCS Help Desk [DCSHLP@dealers.bmwna.com]
Sent: Friday, July 27, 2001 10:05 AM
To: DCS 2000 Server
Subject: Auxiliary Fan Recall 01V-206

Re: Auxiliary Fan Recall 01V-206

Please be advised that the range of vehicles affected by the recall campaign to replace the auxiliary cooling electric fans has been expanded as follows:

E39 (5 Series) vehicles produced 01/16/2001 - 06/13/2001 (previously not included)
E46 (3 Series) vehicles produced 02/01/2001 - 05/14/2001 (previously 02/01/2001 - 04/30/01) manual transmission vehicles only
E53 (X5) vehicles produced 12/18/2000 - 06/15/2001 (previously 12/18/2000 - 04/30/2001)
E52 (Z8) vehicles produced 01/01/2001 - 05/31/2001 (previously 01/01/2001 - 04/30/2001)

The range of E38 (7 Series) vehicles affected by this campaign remains the same (11/01/2000 - 01/08/2001).

A revised Service Information Bulletin will be issued to reflect these changes.

The part numbers of the replacement fans are:

E46	17 11 7 516 813
E53 X5	64 54 6 919 051
E38	64 54 6 919 053
E52 Z8	64 54 6 919 053
E39	64 54 6 919 057

Owner notification will be conducted on a staggered basis as parts supply allows. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

Ordering Information:

Due to limited supply, there will not be an automatic parts shipment for the fan required for the E39 (P/N 64 54 6 919 057). The only orders that will be accepted for these, along with orders for the other fans, must be VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		
Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
FDC		
Country		
State		

Scully, William V4-ZU-S-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Wednesday, July 25, 2001 4:50 PM
To: DCS 2000 Server
Subject: Auxiliary Fan Recall 01V-206

Re: Auxiliary Fan Recall 01V-206

Please be advised that the range of vehicles affected by the recall campaign to replace the auxiliary cooling electric fans has been expanded as follows:

E39 (5 Series) vehicles produced 01/16/2001 - 06/13/2001 (previously not included)
E46 (3 Series) vehicles produced 02/01/2001 - 05/14/2001 (previously 02/01/2001 - 04/30/01) manual transmission vehicles only
E53 (X5) vehicles produced 12/18/2000 - 06/15/2001 (previously 12/18/2000 - 04/30/2001)
E52 (Z8) vehicles produced 01/01/2001 - 05/31/2001 (previously 01/01/2001 - 04/30/2001)

The range of E38 (7 Series) vehicles affected by this campaign remains the same (11/01/2000 - 01/08/2001).

A revised Service Information Bulletin will be issued to reflect these changes.

The part numbers of the replacement fans are:

E46	17 11 7 516 813
E53 X5	64 54 6 919 051
E38	64 54 6 919 053
E52 Z8	64 54 6 919 053
E39	64 54 6 919 057

Owner notification will be conducted on a staggered basis as parts supply allows. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

Ordering Information:

Due to limited supply, there will not be an automatic parts shipment for the fan required for the E39 (P/N 64 54 6 919 057). The only orders that will be accepted for these, along with orders for the other fans, must be VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Distribution:

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, July 11, 2001 4:04 PM
To: DCS 2000 Server
Subject: INCORRECT AUXILIARY FANS

URGENT!!!!URGENT!!!!URGENT!!!!

To: All BMW centers

Re: Incorrect Auxiliary Fans

Incorrect auxilliary/cooling fans may have been sent to your center. Part numbers 64 50 6 908 030, 64 50 6 908 024, 64 50 6 908 124 SHOULD NOT BE USED UNDER ANY CIRCUMSTANCES. If you have received one of these fans, please return it to your facing PDC using TECH4 as the reason code.

If you have any questions, please call the PCG at 1-800-272-0202.

Thank you

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Tuesday, July 10, 2001 3:54 PM
To: DCS 2000 Server
Subject: Parts Locator: 41 35 7 000 386

From: Brian Flick, Classic BMW, Mentor, Ohio

Re: Part Search

Am looking for one (1) of p/n 41 35 7 000 386, side panel, right. If available, please call me at 440-205-6404 or FAX 440 255 1796. Thank you.

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
DMision UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Tuesday, July 10, 2001 2:50 PM
To: DCS 2000 Server
Subject: Recall Campaign No. 01V-206, ENGINE AUXILIARY/COOLING FAN

BMW of North America, LLC has initiated a recall campaign to inspect and/or replace the Engine/Auxiliary Cooling fan on certain 2001 Model year BMW vehicles. Complete details of the procedures required to perform the recall are contained in Service Information bulletin # 64 05 01.

Customer Mailing - The mailing of customer notification letters will commence this week. Due to part shortages, the mailing will be done by production ranges. Approximately 8500 notices will be mailed this week to E46, E36 and E53 owners. The remaining notices will be sent once additional parts are available.

Distribution:

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
DMision UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country

State

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Tuesday, July 10, 2001 2:46 PM
To: DCS 2000 Server
Subject: Auxliary/Cooling Fan Recall

To: All BMW centers

Re: Auxliary/cooling Fan Recall for E46

On Thursday, July 6th, and again on Monday, July 9th, a DCS message was sent to all centers indicating VIN ranges for E46 vehicle owners that would receive letters notifying them of the Auxliary/cooling Fan Recall.

VIN specific orders placed for vehicles within these indicated ranges will be released automatically. No other action is required by the center for these vehicles.

FOR VEHICLES OUTSIDE THESE VIN RANGES, PLEASE PLACE A VIN SPECIFIC ORDER AND CONTACT THE PCG @ 1-800-272-0202. WE WILL PROCESS THESE ORDERS ONLY WHEN CONTACTED BY THE CENTER.

The first chassis ranges for E46 are as follows:

EE26247 TO EE26381

EN80516 TO EN80589

EV87242 TO EV87456

FT02007 TO FT02195

FV03715 TO FV04147

JR80062 TO JR80196

JU23931 TO JU24231

JW49588 TO JW49856

JY41332 TO JY41521

Below are NEW VIN ranges being notified by mail. In addition to NEW E46 mailings, X5 mailings have begun.

PROCEDURES FOR ACQUIRING FANS FOR X5s OUTSIDE OF THE SPECIFIED VIN RANGES ARE THE SAME AS THE E46. PLACE A VIN SPECIFIC ORDER AND CALL THE PCG FOR THE

RELEASE.

E46

- EE25793 to EE26381
- EN80510 to EN80589
- EV87242 to EV87456
- FT02007 to FT02195
- FV03715 to FV04148
- JR80082 to JR80196
- JU23931 to JU24231
- JW49598 to JW49856
- JY41332 to JY41521

E53/X5

- LH20012 to LH22080
- LM84675 to LM85821

For E38 and E52 Z8, please continue to place a VIN specific order and contact the PCG for a release. Additional VIN range specific mailings are imminent. You will be notified by DCS as soon as these mailings take place.

Thank you

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, July 08, 2001 11:11 AM
To: DCS 2000 Server
Subject: Auxillary/Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

To: All BMW centers

Re: Auxillary/Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

BMW NA will conduct a recall campaign to replace the auxiliary cooling electric fans on certain E46, E38, E53 X5 and E52 Z8 vehicles. The following production ranges are affected: E46 3 series produced from 02/01 through 04/01 with manual transmission; E38 7 series produced from 11/00 through 01/01; E53 X5 produced from 12/00 through 04/01; and E52 Z8 produced from 01/01 through 04/01. Owner notification will be conducted on a staggered basis as parts supply allows.

The part numbers involved are:

E46	17 11 7 516 813
E53 X5	64 54 8 919 051
E38	64 54 8 919 053
E52 Z8	64 54 8 918 053

In conjunction with the notification letters to owners of the affected vehicles, BMW NA will conduct an initial automatic shipment of parts to all centers. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

Ordering Information:

As soon as the automatic parts shipment takes place, all existing back orders will be cancelled. After the automatic parts shipment, the only orders that will be accepted are VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

Aftersales Logistics and Service Engineering

Distribution:

may be a tremendous inconvenience to our customers, please do not make any customer appointments for this complaint until the parts supply situation is improved.

DCS updates will broadcast to keep you up to date on availability and order release status.

As always, we thank you for your cooperation in this difficult matter.

Service Engineering and Aftersales Logistics

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Tuesday, July 03, 2001 11:21 AM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fans for E46, E53 X5, E38, E52 Z8

To: All BMW centers

Re: Auxiliary/Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

BMW NA will conduct a recall campaign to replace the auxiliary cooling electric fans on certain E46, E38, E53 X5 and E52 Z8 vehicles. The following production ranges are affected: E46 3 series produced from 02/01 through 04/01 with manual transmission; E38 7 series produced from 11/00 through 01/01; E53 X5 produced from 12/00 through 04/01; and E52 Z8 produced from 01/01 through 04/01. Owner notification will be conducted on a staggered basis as parts supply allows.

The part numbers involved are:
E46 17 11 7 516 813
E53 X5 84 54 6 919 051

E38 64 54 6 919 053
E52 Z8 64 54 6 919 063

In conjunction with the notification letters to owners of the affected vehicles, BMW NA will conduct an initial automatic shipment of parts to all centers. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

Ordering Information:

As soon as the automatic parts shipment takes place, all existing back orders will be cancelled. After the automatic parts shipment, the only orders that will be accepted are VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

Aftersales Logistics and Service Engineering

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Dealer Number 98603 SOUTH MOTORS BMW
Division
Region
Area
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, June 22, 2001 10:28 AM
To: DCS 2000 Server
Subject: Auxillary Fans for E46, E38, E52, E53

01V-206

To: All Service and Parts Managers

Service Information

BMW NA will conduct a recall campaign consisting of replacement of auxillary/cooling electric fans on certain E46, E38, E53, and E52 vehicles. The following production ranges are affected: E46, 3 series with manual transmission from February 2001 through April 2001; E38, 7 series from November 2000 through December 2000; E53, X5 vehicles from mid December 2000 through April 2001; and E52, Z8 vehicles from January 2001 through April 2001. Owner notification will be conducted on a staggered basis, as parts supply allows. The notification process is expected to begin in July 2001.

Parts Information

Effective immediately please discontinue your use of the following auxillary/cooling electric fans: 64 50 6 908 124 (E53), 64 50 6 908 024 (E52) (E38) and 17 11 7 510 086 (E46). As of Monday June 18, 2001 these auxillary/cooling electric fans may be returned using the standard return section of the dealer return system under TECH4. No invoice information will be required. Please place all new orders for replacement auxillary/cooling electric fans on part numbers: 64 54 6 919 061 (E53), 64 54 6 919 053 (E52) (E38) and 17 11 7 516 813 (E46). All orders for the new auxillary/cooling electric fans must be VIN specific, as inventory supply is limited. We have cancelled (including E46 current backorders) and will continue to cancel all back orders on the new part numbers which are not VIN specific. Please continue ordering these new part numbers using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. If you have any questions, please call 1-800-272-0202.

Thank You,
Service Engineering and Aftersales Logistics

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, June 21, 2001 1:47 PM
To: DCS 2000 Server
Subject: Parts Locator: 61 32 8 048 185

From: Addison, Marty's BMW, Los Angeles, California

Re: Part Search

Am looking for one (1) of p/n 61 32 8 048 185, slide switch. If available, please call me at 310-320-7040 or FAX 310-320-9763. Thank you.

Distribution:

Department P Parts Dept
Title M Manager
ProductType B Bike
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, June 21, 2001 12:46 PM
To: DCS 2000 Server
Subject: Auxiliary Fans for E46, E38, E53, E52

01U-206

To: All Service and Parts Managers

Service Information

BMW NA will conduct a recall campaign consisting of replacement of auxiliary/cooling electric fans on certain E46, E38, E53, and E52 vehicles. The following production ranges are affected: E46, 3 series with manual transmission from February 2001 through April 2001; E38, 7 series from November 2000 through December 2000; E53, X5 vehicles from mid December 2000 through April 2001; and E52, Z8 vehicles from January 2001 through April 2001. Owner notification will be conducted on a staggered basis, as parts supply allows. The notification process is expected to begin in July 2001.

Parts Information

Effective immediately please discontinue your use of the following auxiliary/cooling electric fans; 64 50 6 908 124 (E53), 64 50 6 908 024 (E52) (E38) and 17 11 7 510 086 (E46). As of Monday June 18, 2001 these auxiliary/cooling electric fans may be returned using the standard return section of the dealer return system under TECH4. No Invoice Information will be required. Please place all new orders for replacement auxiliary/cooling electric fans on part numbers; 64 54 6 919 051 (E53), 64 54 6 919 053 (E52)

(E38) and 17 11 7 516 813 (E46). All orders for the new auxiliary/cooling electric fans must be VIN specific, as inventory supply is limited. We have cancelled (including E46 current backorders) and will continue to cancel all back orders on the new part numbers which are not VIN specific. Please continue ordering these new part numbers using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. If you have any questions, please call 1-800-272-0202.

Thank You,
Service Engineering and Aftersales Logistics.

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, June 21, 2001 12:43 PM
To: DCS 2000 Server
Subject: Final Stage Resistor 64 11 8 385 549

01V-206

To: All BMW Parts and Service Departments

Re: Final Stage Resistor 64 11 8 385 549

We currently have a critical shortage of airconditioning blower motor Final Stage Resistor 64 11 8 385 549 used on E39, E46, E53.

We can no longer release these parts based on center request. In most situations the fan speed is fluctuating intermittently. While this may be a tremendous inconvenience to our customers, please do not make any customer appointments for this complaint until the parts supply situation is improved.

Only if you require this critical part for cases where a customer experiences a repeat or a complete failure, please fax your order to 201-930-8424 for verification. Please use the VIN as an order number. We will continue to update you as information becomes available. Please do not

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, June 29, 2001 8:39 AM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fans for E46, E53 X5, E38, E52 X5

01V-206

To: All BMW centers

Re: Auxiliary/Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

BMW NA will conduct a recall campaign to replace the auxiliary cooling electric fans on certain E46, E38, E53 X5 and E52 Z8 vehicles. The following production ranges are affected: E46 3 series produced from 02/01 through 04/01 with manual transmission; E38 7 series produced from 11/00 through 01/01; E53 X5 produced from 12/00 through 04/01; and E52 Z8 produced from 01/01 through 04/01. Owner notification will be conducted on a staggered basis as parts supply allows.

The part numbers involved are:

E46	17 11 7 516 813
E53 X5	84 54 6 919 051
E38	64 54 6 919 053
E52 Z8	84 54 6 919 053

In conjunction with the notification letters to owners of the affected vehicles, BMW NA will conduct an initial automatic shipment of parts to all centers. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

Ordering Information:

As soon as the automatic parts shipment takes place, all existing back orders will be cancelled. After the automatic parts shipment, the only orders that will be accepted are VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

Aftersales Logistics and Service Engineering

Distribution:

Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, June 22, 2001 10:31 AM
To: DCS 2000 Server
Subject: Auxiliary Fans for E46, E38, E52, E53

01V-206

To: Victor Delgado

From: Barry and Bill

To: All Service and Parts Managers

Service Information

BMW NA will conduct a recall campaign consisting of replacement of auxiliary/cooling electric fans on certain E46, E38, E53, and E52 vehicles. The following production ranges are effected: E46, 3 series with manual transmission from February 2001 through April 2001; E38, 7 series from November 2000 through December 2000; E53, X5 vehicles from mid December 2000 through April 2001; and E52, Z8 vehicles from January 2001 through April 2001. Owner notification will be conducted on a staggered basis, as parts supply allows. The notification process is expected to begin in July 2001.

Parts Information

Effective immediately please discontinue your use of the following auxiliary/cooling electric fans; 84 50 8 908 124 (E53), 84 50 8 908 024 (E52) (E38) and 17 11 7 510 086 (E46). As of Monday June 18, 2001 these auxiliary/cooling electric fans may be returned using the standard return section of the dealer return system under TECH4. No invoice information will be required. Please place all new orders for replacement auxiliary/cooling electric fans on part numbers; 84 54 8 919 051 (E53), 84 54 8 919 053 (E52) (E38) and 17 11 7 516 813 (E46). All orders for the new auxiliary/cooling electric fans must be VIN specific, as inventory supply is limited. We have cancelled (including E46 current backorders) and will continue to cancel all back orders on the new part numbers which are not VIN specific. Please continue ordering these new part numbers using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. If you have any questions, please call 1-800-272-0202.

Thank You,
Service Engineering and Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, June 08, 2001 10:21 AM
To: DCS 2000 Server
Subject: E46 Auxiliary Fan

01V-206

To: All BMW centers

Re: E46 Auxiliary Fan 17 11 7 516 813

We have received inventory of E46 Auxiliary Fan 17 11 7 516 813. We have cancelled all back orders on part number 17 11 7 510 086 and placed corresponding orders on the new part number 17 11 7 516 813. All P.O.'s have been maintained in order to simplify tracking your orders. The orders which were VIN specific under the part number 17 11 7 510 086 are now being release as 17 11 7 516 813 . All non VIN specific orders are continuing as back orders on part number 17 11 7 516 813. Please continue ordering this new fan part number using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. All non VIN specific orders will be released when stock availability stabilizes. If you have any questions, please call 1-800-272-0202.

Thank you

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-8-21

01V-206

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, June 20, 2001 9:15 AM
To: DCS 2000 Server
Subject: Auxiliary Fans for E46, E38, E53, E52

To: All Service and Parts Managers

Service Information

BMW NA will conduct a recall campaign consisting of replacement of auxiliary/cooling electric fans on certain E46, E38, E53, and E52 vehicles. The following production ranges are affected: E46, 3 series with manual transmission from February 2001 through April 2001; E38, 7 series from November 2000 through December 2000; E53, X5 vehicles from mid December 2000 through April 2001; and E52, Z8 vehicles from January 2001 through April 2001. Owner notification will be conducted on a staggered basis, as parts supply allows. The notification process is expected to begin in July 2001.

Parts Information

Effective immediately please discontinue your use of the following auxiliary/cooling electric fans; 64 50 6 908 124 (E53), 64 50 6 908 024 (E52) (E38) and 17 11 7 510 086 (E46). As of Monday June 18, 2001 these auxiliary/cooling electric fans may be returned using the standard return section of the dealer return system under TECH4. No invoice information will be required. Please place all new orders for replacement auxiliary/cooling electric fans on part numbers; 64 54 6 919 061 (E53), 64 54 6 919 053 (E52) (E38) and 17 11 7 516 813 (E46). All orders for the new auxiliary/cooling electric fans must be VIN specific, as inventory supply is limited. We have cancelled (including E46 current backorders) and will continue to cancel all back orders on the new part numbers which are not VIN specific. Please continue ordering these new part numbers using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. If you have any questions, please call 1-800-272-0202.

Thank You,
Service Engineering and Aftersales Logistics.

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number

Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, June 28, 2001 8:31 AM
To: DCS 2000 Server
Subject: Auxiliary /Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

01V-206

To: All BMW centers

Re: Auxiliary/Cooling Fan Recall for E46, E53 X5, E38, E52 Z8

BMW NA will conduct a recall campaign to replace the auxiliary cooling electric fans on certain E46, E38, E53 X5 and E52 Z8 vehicles. The following production ranges are affected: E46 3 series produced from 02/01 through 04/01 with manual transmission; E38 7 series produced from 11/00 through 01/01; E53 X5 produced from 12/00 through 04/01; and E52 Z8 produced from 01/01 through 04/01. Owner notification will be conducted on a staggered basis as parts supply allows.

The part numbers involved are:

E46 17 11 7 516 813
E53 X5 64 54 6 919 051
E38 64 54 6 919 053
E52 Z8 64 54 6 919 053

In conjunction with the notification letters to owners of the affected vehicles, BMW NA will conduct an initial automatic shipment of parts to all centers. As more inventory becomes available, additional letters will be sent to customers within specific VIN ranges. In stock vehicles, as well as customer vehicles may be affected and included within these VIN ranges. Centers will be notified of specific VIN range mailings through DCS broadcasts.

Ordering Information:

As soon as the automatic parts shipment takes place, all existing back orders will be cancelled. After the automatic parts shipment, the only orders that will be accepted are VIN specific, single line VOR orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line, VOR orders will be cancelled.

The National Traffic and Motor Vehicle Safety Act requires that vehicles subject to a recall be fixed prior to delivery to a customer. Please ensure that any new vehicle delivered to a consumer has the recall performed prior to delivery.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

Distribution:

Department X All Departments
Title M All Managers
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Tuesday, June 19, 2001 12:53 PM
To: DCS 2000 Server
Subject: auxillary/cooling electric fans on certain E46, E38, E53, and E52 vehicles

01V-206

The following message was posted on the website www.bimmer.org yesterday. We already advised you of the planned recall via DCS dated 6/15/01, which also contained all relevant parts information. We are planning to release Service Information with affected VINs and warranty information as soon as available, within the next two weeks. Please continue to order needed parts VIN specific only, until we advise you of sufficient stock.

Thank you very much for your understanding and cooperation.

Subject: BMW Engine Auxillary/Cooling Fan Recall

I'm with BMW of North America, LLC. In follow up to our posting dated 6/13/2001 concerning auxillary/cooling fans, this message is to inform board participants that BMW will conduct a recall campaign consisting of replacement of the auxillary/cooling fan. The recall will affect certain model 3 series (E46) with manual transmission produced 2/01/01 to 4/30/01, 7 Series (E38) produced 11/01/00 to 1/08/01, X5 (E53) produced 12/18/00 to 4/30/01, and Z8 (E52) produced 1/01/01 to 4/30/01. Notification to owners is scheduled to begin in July 2001. Once you receive the recall letter, please contact your authorized BMW center to schedule an appointment. Bring your letter to your authorized BMW center to have the recall performed. Please be patient since parts supply is limited at this time. As always, please feel free to contact us at (800) 831-1117.

Distribution:

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas

E-mail Orders:

04514-51478172189-06-15-01 46891-51127027049-06-15-01
21294-11009069488-06-15-01 66788-12141427696-EC73888-06-15-01
21294-13547502444-06-15-01 76515-64118378615-LM63296-06-15-01
24024-61138373830-116608893-06-15-01

Distribution:

Department P Parts Dept
Title M Manager
ProductType X All
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, June 15, 2001 2:55 PM
To: DCS 2000 Server
Subject: Auxiliary Fans for E46, E38, E53, E52

01V-206

To: All Service and Parts Managers

Service Information

BMW NA will conduct a recall campaign consisting of replacement of auxiliary/cooling electric fans on certain E46, E38, E53, and E52 vehicles. The following production ranges are affected: E46, 3 series with manual transmission from February 2001 through April 2001; E38, 7 series from November 2000 through December 2000; E53, X5 vehicles from mid December 2000 through April 2001; and E52, Z8 vehicles from January 2001 through April 2001. Owner notification will be conducted on a staggered basis, as parts supply allows. The notification process is expected to begin in July 2001.

Parts Information

Effective immediately please discontinue your use of the following auxiliary/cooling electric fans; 64 50 8 908 124 (E53), 64 50 8 908 024 (E52) (E38) and 17 11 7 510 086 (E46). As of Monday June 18, 2001 these auxiliary/cooling electric fans may be returned using the standard return section of the dealer return system under TECH4. No invoice information will be required. Please place all new orders for replacement auxiliary/cooling electric fans on part numbers; 64 54 8 919 051 (E53), 64 54 8 919 053 (E52) (E38) and 17 11 7 516 813 (E46). All orders for the new auxiliary/cooling electric fans must be VIN specific, as inventory supply is limited. We have cancelled (including E46 current backorders) and will continue to cancel all back orders on the new part numbers which are not VIN specific. Please continue ordering these new part numbers using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. If you have any questions, please call 1-800-272-0202.

Thank You,
Service Engineering and Aftersales Logistics.

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, June 13, 2001 11:27 AM
To: DCS 2000 Server
Subject: Customs Update -06-13-01

Importance: High

From: Walter Ford, Parts Logistics

Re: Customs Update -06-13-01

Released: Shipment from 06-08-01.

Shipment from 06-05-01.

No shipments being held at this time.

Continue to monitor e-mail for further updates.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	X	All
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, June 13, 2001 9:45 AM
To: DCS 2000 Server
Subject: E46 Auxiliary Fan 17 11 7 516 813

01V-206

To: All BMW centers

Re: E46 Auxiliary Fan 17 11 7 516 813

We have received inventory of E46 Auxiliary Fan 17 11 7 516 813. We have cancelled all back orders on part number 17 11 7 510 086 and placed corresponding orders on the new part number 17 11 7 516 813. All P.O.'s have been maintained in order to simplify tracking your orders. The orders which were VIN specific under the part number 17 11 7 510 086 are now being release as 17 11 7 516 813. All non VIN specific orders are continuing as back orders on part number 17 11 7 516 813. Please continue ordering this new fan part number using the VIN as a purchase order. It is no longer necessary to call the Parts Technical Hotline for a release. We will review orders on a regular basis and release those that are VIN SPECIFIC ONLY. All non VIN specific orders will be released when stock availability stabilizes. If you have any questions, please call 1-800-272-0202.

Thank you

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Friday, August 10, 2001 5:55 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan 64 54 6 919 053

To All Parts Managers,
Ref: Auxiliary/Cooling Fan 64 54 6 919 053

As of August 10, 2001, we have released all VIN specific VOR backorders for the auxiliary/cooling fan, for the B38 and B52, part number 64 54 6 919 053. All other backorders have been cancelled. We now have sufficient inventory to support all remaining VIN specific repairs for the recall. Effective immediately you may order this part via any method of ordering you choose. Please be aware stock is still limited and only orders for recall and fan failures should be placed. DO NOT ORDER THE PART FOR STOCKING PURPOSES. This part will not be accepted for return via AFA, 90 day return or obsolescence.

All other auxiliary/cooling fans should continue to be ordered as VIN specific single line orders. These orders must coincide with the VIN ranges being notified at that time. Again, you will be notified which VIN ranges are being contacted. Stock orders, fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line orders will be cancelled.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

AfterSales Logistics

Distribution:

Department P Parts Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
FDC
Country
State

Department W Service Dept
Title M Manager
ProductType A Auto
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
FDC
Country
State

ProductType A Auto
Dealer Number 89138 PEGASUS MOTORCAR COMPANY
Division
Region
Area
PDC
Country
State

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Thursday, August 23, 2001 3:08 PM
To: DCS 2000 Server
Subject: Additional Supplier For E46 Auxiliary/Cooling Fan

To: All Service and Parts Managers,
Ref: Additional Supplier For E46 Auxiliary/Cooling Fan

An additional supplier has been added for the E46 auxiliary/cooling fan. This new part number is from Robert Bosch. The number is 17 11 7 510 617. Both part numbers, 17 11 7 516 813 and 17 11 7 510 617 will be allocated as supply allows. Once supply of the "813" is exhausted we will re-place all remaining orders for the "617". This will be done for you. The new part number should not be ordered for inventory. All orders must continue to be ordered as VIN specific single line orders. These orders must coincide with the VIN ranges, which have been previously issued. Again, you will be notified which VIN ranges are being contacted. Fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific, single line orders will be cancelled.

For vehicles outside of the specified VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

Thank you for your cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		
Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, August 08, 2001 10:01 AM
To: DCS 2000 Server
Subject: Parts Locator: 51 14 1 259 368

From: Addison, Matry's Foreign Motors, Inc., Torrance, California

Re: Part Search

Am looking for two (2) of p/n 51 14 1 259 368, engine emblem. If available, please call me at 310-320-7040 or FAX 310-320-9763. Thank you.

Distribution:

Department P Parts Dept
Title M Manager
ProductType B Bike
Dealer Number
Division UX Market Area
Region XX All Regions
Area XX All Areas
PDC
Country
State

Scully, William V4-ZU-S-21

From: Central Region Aftersales Development [craftals@dealers.bmwna.com]
Sent: Wednesday, August 08, 2001 9:58 AM
To: DCS 2000 Server
Subject: Checking Recall Status of Vehicles Before Retailing Them

ATTN: Service and Sales Departments

Regarding Recall Campaign 01V-206, concerning the front cooling fan for the BMW engine: It is very important that you check your center inventory, to see if any of your cars fall under the recall. This recall has just been expanded to the 5 series. You cannot legally deliver the vehicle to the customer without the recall being preformed. You must run a DCS report on all vehicles prior to the delivery of the vehicle and attached it to the RO. Doing so is in the best interests of your BMW Center, your cusotmers, and BMW. If you have any questions concerning this matter please call the market team.

Thank you for your help on this matter!

Division
Region
Area
PDC
Country
State

Scully, William V4-ZU-S-21

From: Warranty [warranty@dealers.bmwna.com]
Sent: Wednesday, August 15, 2001 9:10 AM
To: DCS 2000 Server
Subject: Recall 001V-206 Auxiliary Fan Inspection/Replacement SI 64 05 01 & 64 06 01

We encourage all centers to submit recall claims immediately so that we can update DCS with recall completion. Recalls should not be performed twice. Be alert to the possibility that the recall has been performed but another center's claim has not yet been received.

Please note the possibility that after an inspection the recall could be completed using a work package for checking only and not replacing the auxiliary fan on each model.

Thank you for your assistance.

The Warranty Department
Robert Ludwig

Distribution:

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

E-mail Orders:

10742-51418410347-123906307-08-27-01
65256-62116914917-LM88214-08-27-01
42111-51910008690-08-27-01
96255-52108267637-08-27-01
55806-12141748264-BE31481-08-27-01

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	X	All
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
EDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Monday, August 27, 2001 4:22 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Affecting E46

To: All Parts and Service managers
Re: Auxiliary/Cooling Fan Recall Affecting E46

Due to parts shortages on E46 auxiliary/cooling fans, part numbers 17 11 7 516 813 and 17 11 7 510 617, centers should only place orders for vehicles that are off the road due to a fan failure or if a customer presents a recall notification letter. All orders must continue to be ordered as VIN specific single line orders. These orders must coincide with the VIN ranges, which have been previously issued. Centers will be notified when new VIN ranges are issued. Fax orders, non-VIN specific orders and multiple quantity orders will not be accepted. Anything other than VIN specific orders will be cancelled. DO NOT ORDER THE PART FOR STOCKING PURPOSES. This part will not be accepted for return via AFA, 90-day return or obsolescence. For vehicles outside of the specific VIN ranges, it will be necessary to contact the Parts Consultant Group at 1-800-272-0202.

The message below is a compilation of DCS messages previously sent on August 23, 2001 and August 10, 2001. This information for auxiliary/cooling fans for the E38, Z8, X5, and E39 is the current status for order placement.

We have released all backorders for the auxiliary/cooling fans for the E38, Z8, X5 & E39, part numbers 64 54 6 919 051, 64 54 6 919 053 & 64 54 6 919 057. Effective immediately, you may order these parts via any method of non-VIN specific ordering you choose. Please be aware stock is still limited and only orders for recall and fan failures should be placed. DO NOT ORDER THE PART FOR STOCKING PURPOSES. This part will not be accepted for return via AFA, 90-day return or obsolescence.

Thank you for your cooperation.

Scully, William ZU-A-21

From: Customer Satisfaction [custsat@dealers.bmwna.com]
Sent: Friday, August 24, 2001 3:59 PM
To: DCS 2000 Server
Cc: 'kerry.dall@bmwna.com'
Subject: Auxiliary Fan survey exemption

We are pleased to inform you that BMW of North America, LLC has approved a process for adjusting CSI surveys affected by the Aux. Fan recall. This new adjustment process will require no additional work on the part of the BMW centers, and will be done retroactively from the beginning of 2001.

How it will work:

The BMW NA Warranty Group will provide iSKY with VINs of vehicles affected by the Auxiliary fan problem. iSKY will add a process to their system which will compare these VINs against surveys taken by those customers. Surveys having an overall Unadjusted score of 90.99 or below will be removed from the center's monthly Adjusted CSI score. Any Mulligans applied to previous Aux. Fan related surveys will be returned to the BMW center for future use. Auxiliary Fan surveys where the center has been graded with an overall unadjusted score of 91 or above will remain as-is.

As you are all aware, the Added Value Program for 2001 is based on (paid on) the Adjusted Rolling Three Month Combined CSI Scores. This action will resolve any downward trend that may cause a center to fall out of CSI score compliance due to the Auxiliary fan problem.

Regards,

The BMW OSCAR TEAM:

Distribution:

Department	X	All Departments
Title	M	All Managers
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	KX	All Regions
Area	KX	All Areas
PDC		
Country		
State		

10731-51117027022-10-03-01

55200-116117704010-DH68739-10-03-01

21617-31126758520-10-03-01

84800-51117027022-10-03-01

22081-51127027049-10-03-01

95242-16117658489-10-03-01

22083-11111310600-10-03-01

96255-13327512019-10-03-01

23480-46637661150-10-03-01

97973-62117650278-10-03-01

24336-51458237204-10-03-01

Distribution:

Department	F	Parts Dept
Title	M	Manager
ProductType	X	All
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, October 03, 2001 1:46 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 Update 10/03/2001

To: All Service & Parts Managers

Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update 10/03/2001

As per the DCS message from September 28, 2001, we will be providing to you the customer mailed letter VIN listing. These VIN's will be activated for automatic release of center-entered orders on Wednesday October 3, 2001 and inclusive of orders placed since October 1, 2001.

Only VIN specific center-entered orders from within the list will be automatically released. VIN ranges published prior to this will no longer receive automatic allocation. This means that if you have an existing VIN specific order for the old VIN ranges you must call the PCG for release. If the VIN is outside the customer VIN mailing listing, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

A MAILING, with NEW, additional VIN numbers, was done on October 2, 2001. A NEW LIST, THAT INCLUDES THE ORIGINAL LIST AND THE NEW, ADDITIONAL VIN NUMBERS, WILL BE PUBLISHED ON BMWVIS.NET as part of the revised Sib 64 07 01 and pib 64 0101.

As new VIN customer letter mailings occur we will revise these bulletins and inform the centers via DCS message.

Please read these bulletins carefully. We encourage you to access them through BMWVIS.NET as soon as possible. This will give you the information much sooner than waiting for the paper version to be mailed to your center.

NOTE R39 PART NUMBER 64 54 6 921 395 IS NO LONGER RESTRICTED AND IS NOW AVAILABLE FOR NORMAL ORDERING ***

04514-63258386965-128207522-10-09-01
24086-65127654887-128707772-10-09-01
10712-63126918592-128207778-JU89141
36760-51161186416-128207526-10-09-01
20626-51718252631-128207524-JN65281
39000-12141430131-128207788-JD31150
20626-51718252631-128207524-JW55062
56000-63178360946-128207774-10-09-01
22007-51711810531-128207782-10-09-01
86302-17111719309-128207780-BJ68067
22007-61311355322-128207782-10-09-01
96644-51418411882-128207776-10-09-01
23069-12141276267-128207528-7960350
96644-51128362634-128207776-10-09-01

E-mail Orders:

04251-41118265558-10-09-01 52800-51190027385-10-09-01
04514-11258265558-10-09-01 76731-12141438878-AV37790-10-09-01

16483-64521386300-10-09-01 86424-65751388907-10-09-01
22083-11111310600-01-09-01

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	X	All
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Tuesday, October 09, 2001 4:28 PM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update October 9 , 2001

To: All Service & Parts Managers,

Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update October 9, 2001

Effective Wednesday October 10, 2001 we will no longer restrict ordering of:

E38/E52 PART NUMBER 64 54 6 921 383
E39 PART NUMBER 64 54 6 921 395
E46 PART NUMBER 17 11 7 510 617

These parts will be available for normal ordering. All backorders for the above part numbers will be automatically released.

DO NOT ORDER PARTS FOR STOCKING PURPOSES.

Part Number 64 54 6 921 361 is still under restrictions and must be ordered as described below.

No additional customer mailings have occurred since the last DCS message of Wednesday October 3, 2001

For the most current listing of customer mailed VIN's please refer to either BMWFIS.NET or Paper versions of Service Information Bulletin 64 07 01, and Parts Bulletin 64 01 01.

As new VIN customer letter mailings for the restricted part occur, we will revise these bulletins and inform the centers via DCS message.

Only VIN specific center-entered orders for the restricted part from within the list will be automatically released. VIN ranges published prior to this will no longer receive automatic allocation. This means that if you have an existing VIN specific order for the old VIN ranges you must call the PCG for release. If the VIN is outside the customer VIN mailing listing, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

Please read these bulletins carefully. We encourage you to access them through BMWFIS.NET as soon as possible. This will give you the information much sooner than waiting for the paper version to be mailed to your center.

We appreciate your patience and cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		
Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, October 10, 2001 11:34 AM
To: DCS 2000 Server
Subject: Customs Update - 10-10-01

Importance: High

From: Walter Ford, Parts Logistics

Re: Customs Update - 10-10-01

No shipments being held at this time.

Continue to monitor e-mail for further updates.

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	X	All
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Scully, William ZU-A-21

From: Parts Supply [PRTSPL@dealers.bmwna.com]
Sent: Wednesday, October 10, 2001 11:15 AM
To: DCS 2000 Server
Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update October 10, 2001

To: All Service & Parts Managers,

Subject: Auxiliary/Cooling Fan Recall Campaign 01V-206 - Update October 10, 2001

Effective Wednesday October 10, 2001 we will no longer restrict ordering of:

E38/E52 PART NUMBER 64 54 6 921 383
E39 PART NUMBER 64 54 6 921 395
E46 PART NUMBER 17 11 7 510 617

These parts will be available for normal ordering. All backorders for the above part numbers will be automatically released.

DO NOT ORDER PARTS FOR STOCKING PURPOSES.

Part Number 64 54 6 921 381 is still under restrictions and must be ordered as described below.

No additional customer mailings have occurred since the last DCS message of Wednesday October 3, 2001

For the most current listing of customer mailed VIN's please refer to either EMWTIS.NET or Paper versions of Service Information Bulletin 64 07 01, and Parts Bulletin 64 01 01.

As new VIN customer letter mailings for the restricted part occur, we will revise these bulletins and inform the centers via DCS message.

Only VIN specific center-entered orders for the restricted part from within the list will be automatically released. VIN ranges published prior to this will no longer receive automatic allocation. This means that if you have an existing VIN specific order for the old VIN ranges you must call the PCG for release. If the VIN is outside the customer VIN mailing listing, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order.

Please read these bulletins carefully. We encourage you to access them through EMWTIS.NET as soon as possible. This will give you the information much sooner than waiting for the paper version to be mailed to your center.

We appreciate your patience and cooperation.

Aftersales Logistics

Distribution:

Department	P	Parts Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

Department	W	Service Dept
Title	M	Manager
ProductType	A	Auto
Dealer Number		
Division	UX	Market Area
Region	XX	All Regions
Area	XX	All Areas
PDC		
Country		
State		

PDC
Country
State

Scully, William ZU-A-21

From: Quality & Service Engineer [QSENG@dealers.bmwna.com]
Sent: Wednesday, October 24, 2001 10:30 AM
To: DCS 2000 Server
Subject: Status Update-Recall 01V-206, Auxiliary Fan, SI 64 07 01

All General Managers, Service Managers, Parts Managers

Re: Status Update on Recall 01V-206, Auxiliary Fan, SI 64 07 01

We are in the process of initiating another mailing to approx. 12,000 customers by the end of this week and plan to have all mailings completed by early November. The VIN ranges are as follows:

GF41114 - GF41541
GX24627 - GX27658
GD50188 - GD50258
GD85767 - GD86219
CE91397 - CE91954
CF11025 - CF14697
GC97644 - GC98534
GM72843 - GM74018
GN91843 - GN91963
BZ99231 - BZ99697
DN87234 - DN89753
DP29468 - DP34405
DE05041
DD74660 - DD74804
DE35040 - DE35043

Please note that all vehicles affected by this recall MUST be repaired prior to customer delivery as stated in SI 64 07 01, dated September 2001.

If customers call and inquire about the recall, please check on DCS whether their vehicle is affected. Then encourage the customer to make an appointment as soon as possible to have the recall performed. Applicable precautions are explained in the customer letter copy attached to SI 64 07 01.

It is important that all customer facing dealer personnel understand that we have sufficient parts in stock to repair all vehicles of customers who have received mailings as well as for unscheduled customer visits concerning this recall. Customers should be assured that BMW is doing everything necessary to repair all affected vehicles as soon as possible and that we will make all reasonable accommodations to meet your parts supply needs.

Effective October 10, 2001 we are no longer restricting parts orders for:
E38/E52, part number 64 54 6 921 383
E39, part number 64 54 6 921 395
E46, part number 17 11 7 510 617

Only VIN specific center-entered orders for Part Number 64 54 6 921 381 from within the list of recalled vehicles attached to SI 64 07 01 or Parts Bulletin 64 01 01 will be automatically released. If the VIN is not on the customer VIN mailing listing, the center must place an order via DCS and call the PCG at 1-800-272-0202, for release of the order. This paragraph refers to part number 64 54 6 921 381 (auxiliary fan for E53 X5 vehicles) only.