

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 5 OF 6**

**BOOK 14 OF 43**

2001 Exped repeat repair_DLR_SUB_CD	2001 Exped repeat repair_REGION_CD
.	NA





















2001 Exped repeat repair_ST_PROV_CD	2001 Exped repeat repair_CPSC_CD_6	Ratings
IA	11001	b
GA	11001	b
FL	11001	b
TX	11001	b
CA	11001	b
TX	11001	b
CA	11001	b
FL	11001	b
OK	11001	b
TX	11001	b
CA	11001	b
PA	12001	b
IN	11001	b
CA	12001	b
LA	11001	b

MS		11001	b
TX		12001	b
AL		11001	b
TX		11001	b
GA		11001	b
TX		11001	b
CA		11001	b
CA		11001	b
CA		11001	b
WA	11000		b
IA	11000		b
TX	11000		b
CA	11000		b
ID	11000		b
MS	11000		b
AZ	11001		b
WI	11001		b

MO	11000	b
SC	11000	b
TX	11000	b
CO	11001	b
MN	11001	b
MO	11001	b
WI	11001	b
NY	11001	b
WI	11001	b
PA	11001	b
CO	11001	b
MN	11001	b
MI	11001	b
MN	11001	b
MN	11001	b
VT	11001	b
MO	11001	b
CO	11001	b
AZ	11001	b
VT	11001	b
WI	11001	b

CO	11001	b
TX	11001	b
FL	11001	b
OH	11001	b
FL	11001	b
NC	11001	b
TX	11001	b
FL	11001	b
NJ	11001	b
VA	11001	b
OH	11001	b
MN	11001	b
NC	12001	b
CA	11001	b
CA	11001	b
NY	11001	b
NY	11001	b
TX	11001	b
CA	11001	b
AZ	11001	b

OH	11001	b
TX	11001	b
MI	11001	b
AR	11001	b
TX	12001	b
TX	12001	b
NE	12001	b
MI	11001	b
AZ	12001	b
TN	11001	b
CA	11001	b
TN	11001	b
OR	12001	b
WA	11001	b
VA	11001	b
MO	11001	b
IL	11001	b
PA	11001	b
DE	11001	b
MN	11001	b
GA	12001	b
FL	11001	b
MI	11001	b

LA	11001	b
WV	11001	b
UT	11001	b
IA	11001	b
FL	12001	b
IA	11001	b
OH	11001	b
KY	12001	b
ME	11001	b
NC	11001	b
PA	11001	b
CA	12001	b
TX	11001	b
MA	11001	b
MA	11001	b
IL	11001	b
MO	11001	b
NY	11001	b
CA	11001	b
MN	12001	b

TX	11001	b
HI	12001	b
OH	11001	b
NJ	11001	b
CA	11001	b
CA	12001	b
OH	12001	b
MT	11001	b
MI	11001	b
CA	12001	b
PA	11001	b
FL	11001	b
TX	11001	b
OH	11001	b
WA	12001	b
MI	11001	b
TN	11001	b
IN	11001	b
MI	11001	b
TX	11001	b
TN	12001	b

TX	11001	b
TX	12001	b
TX	11001	b
TX	11001	b
GA	12001	b
OR	12001	b
MA	11001	b
CA	12001	b
TN	12001	b
NY	11001	b
VA	11001	B
WI	11001	B
MI	11001	B
VA	11001	B
NC	11001	B
WI	11001	B
NY	11001	B
IN	11001	B
NC	11001	B
MI	11001	B
TX	11001	B
TN	11001	B
ON	11001	B

CT	11001	b
CA	11001	b
FL	11001	b
MI	11001	b
GA	11001	b
OK	11001	b
TX	11001	b
MI	11001	b
GA	11001	b
MD	11001	b
TX	11001	b
KY	11001	b
OH	11001	b
NC	11001	b
FL	11001	b
TX	11001	b
AL	11001	b

MI	11001	b
WV	11001	b
TX	11001	b
FL	11001	b
TX	11001	b
MI	11001	b
GA	11001	b
TX	11001	b
CA	11001	b
TN	11001	b
MO	11001	b
OH	11001	b
PA	11001	b
MD	11001	b
OR	11001	b
TX	11001	b
MO	11001	b

MI	11001	b
FL		B
IN		B
MD		B
AZ		B
TX		B
CA		B
NJ		B

2001 Exped repeat repair TECH\_TXT1

WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE

SEATBELT RECEIVER FAILURE SEATBELT RECEIVER FRONT REPLACE

1 VERIFIED CONCERN INSTALLED SOP THE DRIVER SEAT BELT BUCKLE RETESTED OK AT THIS TIME

DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK.

SEAT BELT LATCH BROKEN IN TIME TO REPLACE SEAT BELT LATCH

5328 01 61203 R R DRIVER SEAT ACESS REPLACED DRIVER SEAT BELT BUCKLE BINDING

TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.

BUCKLE HAD A BROKEN & JAMMED PUSH BUTTON REPLACD THE DRIVER SIDE SEAT BUCKLE ASSY,TESTED ALL FUNCTIONS AFTER THE REPAIR,ALL TO SPEC AT THIS TIME

INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.  
REPLACED SEAT BELT BUCKLE

REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH

TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE

HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.

VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK

10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 CASUAL PART 1L7Z 7881203 BAA

CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION

CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.

1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST

10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE  
REPLACED SEAT BELT LATCH

REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD

CC487 REPLACED BOTH SEAT BELT BUCKLES

CC487 REPLACED BOTH SEAT BELT BUCKLES

CC487 REPLACED SEAT BELT BUCKLE

SEATBELT LATCH BAD                      CHECKED SEAT BELT LATCH,REPLACED LEFT FRONT SEAT BELT LATCH ASSY

REPLACED LATCH ON DRIVERS SEAT BELT

SEAT BELT NOT HOLDING AT ALL TIMES REMOVE SEAT BELT AND REPLACE SEAT BELTS WITH NEW FACTORY PARTS 42 828

BUCKLE WONT STAY BUCKLED      SEATBELT ASSEMBLY FRONT REPLACE

DIAGNOSE R AND R SEAT BELT AND R AND R BUCKLE ASSEMBLY

17160 W REMOVE PASSENGER SEAT AND REPLACE BUCKEL WILL NOT STAY LATCHED AT TIMES.

VERIFY AND DIAG., REPL. BELT AND BUCKLE ASY... CLM. SUBMISSION DELAYED DUE TO SOP... NEW DATE IS 10.26.01 AND MILES ARE 14228

BOTH FRONT SEAT BELT BUCKLES WONT STAY BUCKLED REPLACED BUCKLES CLOSED BYWPI

9000 REMOVED BOTH FRONT SEATS IN ORDER TO REPLACE BOTH SEAT BELT BUCKLES. REINSTALL SEATS. BUCKLES TEST OK

INOP REPLACED PASS SEAT BELT BUCKLE

REPLACED LH SEAT BELT BUCKLE

TESTED BOTH FRONT SEAT BELTS, BOTH FAILED, REPLACED BOTH FRONT SEAT BELT BUCKLES...3017

CHECK SEAT BELT OPERATION, REPLACE RIGHT FRT SEAT BELT.

CHECK OUT SEAT BELT OPERATION, REPLACE LEFT SIDE SEAT BELT BUCKLE

3137 ORDERED SEAT BELT BUCKLE REPLACED PASS SEAT BELT

REPLACED BUCKLE

REPLACED PASS SIDE SEAT BELT

REPLACE SEAT BELT LATCH ASSY.

REMOVED RIGHT FRT. SEAT TO REPLACE SEAT BELT BUCKLE ASSEMBLY AS IT WOULD NOT STAY LATCHED AT TIMES

RIGHT FRONT SEAT BELT BAD ADD ON

TAKE SEAT OUT R R GAS CHARGED BUCKEL

REPLACED SEATBELT BUCKLE ASSY

REPLACE THE SEAT BELT BUCKLE ASSY WONT STAY LATCHED

5680 REPLACED DRIVERS SIDE SEATBELT BUCKLE CUSTOMER STATED THAT THE SEAT BELT STILL WOULD NOT STAY LATCHED PROPERLY

1 CHECKED BUCKLE, LATCH FEELS LOOSE. REMOVED SEAT, REPACED BUCKLE. RETESTED, OK.  
REPL RF SEAT BELT ASSY.

SEATBELT LATCH ASSEMBLY WEAK

CHECK OUT REPLACE LEFT FRONT SEAT BELT

1 REPLACED BOTH SEAT BELTS.
13855 INOP 61172A REPLACE PASS. SEAT BELT
BROKEN SEATBELT ASSEMBLY FRONT REPLACE
VERIFIED CUSTOMERS CONCERN SEAT BELT BUCKLE WILL NOT STAY LATCHED R AND R PASSENGER SEAT TO REPLACE SEAT BELT BUCKLE REPLACED AND RECHECK ALL OK AT THIS TIME REPLACED PASS SIDE SEAT BELT
TESTED TO VERIFY.FOUND SEAT BELT WOULD NOT STAY BUCKLED. CK OASIS FOR RECALL, NO RECALL PRESENT.INSPECT SEATBELTS HAVE INTERNAL DEFECT.NEC TO RR SEATBELT.
CUSTOMER STATES DRIVERS SEAT BELT WONT STAY LATCHED
DRIVERS SEAT BELT DOES NOT STAY BUCKLED
DRIVERS SEATBELT WONT STAY LATCHED
CHECK PASSENGER SIDE SEAT BELT WONT STAY LATCHED
REPAIR RIGHT FRONT SEAT BELT WILL NOT STAY LATCHED
RIGHT SIDE SEAT BELT WILL NOFT STAY LATCHED
S40 SEATBELTS WILL NOT STAY LATCHED
CUSTOMER STATES THE DRIVERS SEAT BELT BUCKLE WILL NOT ALWAYS HOLD
CUSTOMER STATES PASSENGERS FRONT SEAT BELT WILL NOT STAY BUCKLED
CUST STATES LEFT SEAT BELT BUCKLE DOESNT ALWAYS HOLD
C S PASS FRNT SEAT BELT BUCKLE OPENS SOP
CUST STATES SEATBELT WONT STAY BUCKLED
CUST STATES DRIVERS SEATBELT WONT STAY BUCKLED AT TIMES SPO IN 341
C S DRIVERS SEAT BELT BUCKLE WILL NOT STAY LOCKED TESTED WITH BUCKLE TESTER AND FAILED

RIGHT FT SEAT BELT WILL NOT STAY BUCKLED

DRIVERS SEAT BELT WILL NOT STAY BUCKLED

L H FRT SEAT BELT WONT STAY BUCKLED  
SEAT BELT DOES NOT HOLD

S40 VEH PASS SEAT BELT WILL NOT HOLD AT ALL TIMES

CUST STATES D.S. SEAT BELT WONT STAY LATCHED  
SEAT BELT WONT STAY LATCHED

R H FRT SEAT BELT BUCKLE WONT STAY BUCKLED

FACTORY WARRANTY CUSTOMER STATES DRIVERS SIDE SEAT BELT WONT STAY LATCHED

S28 STATES THAT THE PASS SEATBELT WILL NOT STAY LATCHED SEE DARWIN

DRIVERS SIDE SEAT BELT WILL NOT STAY BUCKLED

CUSTOMER STATES P 8 FRONT SEAT BLET BUCKLE INOP AT TIMES

RECALL 01S21 PASS SEATBELT DOES NOT HOLD

CUST STATES THE RF SEAT BELT WILL NOT STAY BUCKLED.REPORT.

PASSENGER FRONT SEAT BELT NOT STAYING LATCHED

DRIVERS SEAT BELT WONT STAY LATCHED. PART HERE TO CORRECT.

CUSTOMER STATES L FRT SHOULDER BELT WONT STAY BUCKLED

CUSTOMER STATES DR SIDE BELT WILL NOT STAY CLIPPED

LEFT SEAT BELT WILL NOT STAY BUCKLED

CHECK SEAT BELTS....DR SEAT BELT WILL NOT HOLD... CUST REQUEST CHECK ALL BELTS....

SEAT BELT ON PASS FRONT COMES UNBUCKLED

CHECK BOTH FRONT SEAT BELT BUCKLES DO NOT HOLD PROPERLY

PASS SIDE SEAT BELT WILL NOT LATCH ALL THE TIME.

PLEASE CK THE SEAT BELT LATCH PASSENGER SIDE COMES UNSNAPPED  
CHECK DR SEATBELT WONT HOLD

CUSTOMER STATES THAT THE DRIVERS SEAT BELT KEEPS COMING UN DONE PLEASE CHECK

SEAT BELT WILL NOT STAY LATCHED OWNER REPLACED BUCKLE

CUSTOMER STATES THE PASS SEAT BELT DOES NOT STAY SOP HERE

OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED

PASSENGER SIDE SEAT BELT NOT STAYING BUCKLED

CUSTOMER STATES THE PASS SIDE SEAT BELT WILL NOT STAY LATCHED

CUSTOMER SAYS SEAT BELTS DO NOT ALWAYS STAY BUCKLED  
B SEAT BELT WONT BUCKLE

CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED

CUSTOMER STATES THAT THE PASSENGER AND DRIVERS SIDE SEAT BELT BUCKLES ARE FAILING  
NOT SECURE.CHECK AND ADVISE.

INTERIOR TRIM REPAIR CUST STATES R F SEAT BELT KEEPS COMING LOOSE FROM RECEIVER

THE CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED.

CK PASS SEAT BELT WONT LACTH AND POPS OUT WHEN LATCH

RIGHT FRONT SEAT BELT WILL NOT CLASP AT ALL TIMES.

C S THE DRIVER FRONT SEAT BELT WILL SOMETIMES NOT STAY BUCKLED

CUSTOMER STATES:PASS SEAT BELT WILL NOT STAY BUCKLED

INSTALL SOP SEAT BELTS CUST STATES WONT HOLD

DRIVERS SIDE SEAT BELT BUCKLE DOES NOT STAY BUCKLED SEAT BELTS

S40 CUST STATES THAT THE DRIVERS SEAT BELT WONT STAY LATCHED SOP PARTS ARE IN SEE  
RQ#48984

SEAT BELTS DO NOT STAY COUPLED  
BELT WONT STAY LATCHED

CUSTOMER STATES CHECK SEAT BELTS ONE WONT HOLD JUST HAD RECALL BY AANOTHER DEALER

CUSTOMER REPORTS L F SEAT BELT WILL NOT STAY LATCHED WILL COME OUT OF BUCKLE

DRIVER SEAT BELT WILL NOT STAY CONNECTED TO BUCKLE

DRIVERS SEATBELT WONT STAY LATCHED SOP IN

SEAT BELT BUCKLE WOULD NOT STAY BUCKLED NEEDS REPAIRED/RPLCD

CUSTOMER STATES THAT HE WAS INSTALLING HIS CHILD SEAT AND SEAT BELT WOULD NOT STAY  
LATCHED

CUSTOMER STATES 1 SEAT BELT WILL NOT HOLD RIGHT SIDE

CUSTOMER REQUEST CHECK OPERATION OF FRONT SEATBELTS WONT STAY LATCHED

DRIVER S SEAT BELT WILL NOT STAY LOCKED

S26 DRIVERS SEAT BELT BUCKLE WONT HOLD PROPERLY SOP HERE

CHECK SEAT BELT LATCH. WILL NOT STAY LATCHED

INSTALL SOP SEATBELT RECIEVERS BELTS WONT STAY BUCKLED

RIGHT SEAT BELT DOES NOT STAYED LATCHED.

CUSTOMER STATES DRIVER SEATBELT FAILS WILL NOT STAY BUCKLED.

REPAIR PASS SEAT BELT WONT HOLD  
LEFT SEATBELT WONT HOLD SOP

CUST STATES FRT SEAT BELTS WILL NOT STAY LATCHED

DRIVER NEW SEAT BELT BUCKLE NOT HOLD;INSTALL NEW ONE SOP

THE SEAT BELT BUCKLES DO NOT ALWAYS LOCK THE SEAT BELT.

LEFT SEAT BELT WON T STAY LATCHED

SEAT BELTS COME UNBUCKLED BY THEMSELVES

SEAT BELT ON DRIVER SIDE KEEPS UNBUCKLING PLEASE CK AND REPORT

CHECK PASS FRONT SEATBELT HARD TO LATCH UNLATCH

RH FRONT SEATBELT WILL NOT STAY BUCKLED

PS BUCKLE DISCONNECTS REPLACE BUCKLE

CUST STATES DRIVERS SEATBELT BUCKLE DISCONNECTS BY ITSELF AT TIMES

CHECK CENTER SEAT BELT WILL NOT STAY LATCHED

CUSTOMER STATES DRIVERS SIDE SEAT BELT UNBUCKLES.

CHECKED AND REPLACE BUCKLE

INSP AND REPL RT FRT SEAT BELT RE CK OPERATION OKAY

REPLACED RT SEAT BELT BUCKLE INOP

CHECKED AND REPLACED FRONT SEATBELT LATCH ASSY

REPLACE SEAT BELT ASSEMBLY

MT EQUALS TIME TO REPLACE PASSENGER FRONT SEATBELTBUCKLE

8839 VERIFIED PASS SEAT BELT LATCH STICKING REMOVED SEAT AND REPLACED LATCH

RECHECKED OK

REPLACED FAULTY SEAT BELT

REPLACED RF SEATBELT BUCKLE ASSY.

CHECK OUT DRIVER SEATBELT WILL NOT STAY LATCHED, REPLACE DRIVER SEATBELT BUCKLE (NOT WORKING PROPERLY), RECHECK OK

R & R SEAT BELT BUCKLE

REMOVED PAS FRT SEAT BELT BUCKLE DUE TO NOT STAYING LATCHES

REMOVE AND REPLACE DRIVERS SEATBELT

VERIFY CONCERN,DEACTIVATE AIR BAG SYS,R&R PASSN AGER SIDE BELT BUCKLE,REACTIVATE AIR BAG SYS AN D RETEST OK AT THIS TIME.

1050 61202 W RECALL COMPLETE REPL D S SEAT BUCKLE

REPLACED PASSENGER SIDE FRONT SEATBELT BUCKLE M TIME DUE TO NO APPLICABLE LABOR OP

REPLACED PASS FRT SEAT BELT

42,5461202 INSTALLED NEW SEAT BELT

TESTED AND REIPLACED BOTH SEAT BELTS AND BUCKLES

OK AND REPLACED SEAT BELT BUCKLE ASSY

SPLIT BENCH WITH AIR BAGS

REMOVED AND REPLACED SEATBELT

1 REPLACE SEAT BELT LATCH

WILL NOT HOLD PROPERLY SEATBELT ASSEMBLY FRONT REPLACE

FRONT SEAT BELT BUCKLES DO NOT HOLD CORRECTLY, REPLACED BOTH SEAT BELT BUCKLES WITH SIDE AIR BAGS

CHECK SEATBELT BUCKLE OPERATION REM SEAT TRACK TO GAIN ACCESS REM AND REPL SEATBELT BUCKLE ASSEMBL

R&R DRIVERS SEAT BELT BUCKLE

REPLACE SEAT BELTS WONT HOLD

5880 42 CHECKED OPERATION OF LEFT FRONT SEATBELT BUCKLE, WILL NOT STAY LATCHED. REMOVED LEFT FRONT SEAT TO ACCESS, REPLACED BUCKLE, ASSEMBLED. RETEST PASSED.

REPALCE SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE

BOTH FRONT SEAT BELTS WONT STAY LATCHED

1 VERIFIED CUST COMPLAINT. NECG TO REPLACE LEFT FRONT SEAT BELT BUCKLE. (LATCH NOT HOLDING AT TIMES.)

M TIME USED TO DIAGNOSE AND REPLACE SEAT BELT BUCKLE RIGHT FRONT

VERIFY CONCERN.FOUND BOTH FRONT SEAT BELTS NOT HOLDING. REPLACE SEAT BELT BUCKLES. VERIFY REPAIR.

REPLACED RT FRONT SEAT BELT BUCKLE

REPLACED PASS FRT SEAT BELT

LF SEAT BELT IS BROKEN REPLACED SEAT BELT

REPLACE SEAT BELT

REPLACE FRONT SEAT BELTS

INSPECTED. REPLACED BOTH SEAT BELT BUCKLES.

VERIFY CONCERN. SOP REPLACE SEATBELT.CHECK OPERATION,OK

REPLACED BOTH FRONT SEAT BELT BUCKLE ASSEMBLIES.

12687 SEAT BELT BUCKLE WARR REPLACED DRIVERS SIDE SEAT BELT BUCKLE

TEST AND BOTH SEAT BELTS FAILED REPLACED BOTH LEFT AND RIGHT FRT SEAT BELT BUCKLES

CHECKED AND TESTED. REPLACED BOTH SEAT BELT HALVES.

REPLACED BOTH FRONT SEATBELTS.

SEAT BELT CHECK BOTH FRONT SEATBELT LATCHES WILL NOT STAY LATCHED REPLACED BOTH FRONT SEAT BELT ASSY FINAL TEST PASSED

REMOVE DR SEAT ASSY AND REPL DR SEAT BELT RECIEVER. MT TIME FOR REPAIR.

61203 S40 42 SEAT BELT DOSE NOT HOLD REPLACE DRIVERS SEATBELT LATCH ASSEMBLY

13212 DRIVERS SEAT BELT WONT STAY BUCKLED WARR REPLACED L F SEATBELT BUCKLE

REPLACED RT FRT SEATBELT ASSY.

10881 1.0 HRS TESTED OLD SEATBELT, REPLACED WITH NEW. C P

DIAG REPLACE SEAT BELT BROKEN

REPLACE BUCKLES BOTH SIDES



INSPECT SEAT BELT RETRACTOR AND BUCKLE, R R DRIVERS SEAT PWR. REPLACE SEAT BELT BUCKLE
VERIFIED. REPLACED SEAT BELT BUCKLE ON DRIVERS SEATBELT.
REPLACE SEATBELT PRETENSIONER
REPLACED SEAT BELT ASSEMBLY FOR BUCKLE NOT LATCHING
CHECK OUT REMOVE SEAT REPLACED RIGHT BUCKLE
REPLACED SEAT BELT LATCH
CAUSAL PART 1881202 CKED AND REPLACED BOTH FRONT SEATBELTS CONDITION CODE 07
INSPECT AND REPLACED SEAT BELT BUCKLE
REPLACED RIGHT FRONT SEAT BELT ASSY
5231 . REPLACED LEFT FRONT SEAT BELT BUCKLE, NOT HOLDING 100% OF THE TIME.
13888 R&R R F SEAT & REPLACE SEAT BELT BUCKLE CHECK OPERATION & VERIFIED REPAIR
VERIFIED CUST CONCERN REPLACED DRIVERS SIDE SEAT BELT BUCKLE
DRIVERS SEATBELT WONT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE
6370 2581203 VERIFIED CONCERN. ACCESSED DRIVERS SEAT. REMOVED AND INSTALLED NEW DRIVE

WONT RECOIL	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT	REPLACE
VERIFIED CONCERN, FOUND SEAT BELT UNBUCKLING BY ITSELF. REMOVED AND REPLACED BUCKLE.		
COND. CODE 42, BASE PART NUMBER 2581203. . VERIFY CONCERN. LEFT FRONT SEAT BELT BUCKLE W/		
REPLACED FAULTY SEAT BELT		DM1ACEAL
14928 CC 42 (61202) VERIFIED CONCERN R&I PASSENGER FRONT SEAT FOR ACCESS TO REPLACE SEAT		
INSTALL DRIVER SIDE SEAT BUCKLE BROKE 1		
LATCH BROKE REPLACED		
COND. CODE 42, BASE PART NUMBER 1881202. VERIFY CONCERN. REMOVE RIGHT FRONT SEAT. REPL		
1 REPLACE BUCKLE		
CHECKED AND FOUND SEAT BELT TO BE RELEASING PREMATURELY, REPLACED SEAT BELT BUCKLE A		
BELT WILL NOT STAY BUCKLED REPLACE LEFT BUCKLE		
REPLACED RIGHT FRONT SEAT BLET BUCKLE		
CHECK AND REPLACE BUCKLES		
CONFIRM SEATBELT WILL NOT BUCKLE. REPLACE PASSENGER SIDE SEATBELT. M TIME TO DO REPAIR		
INSPECT FRONT SEAT BELT BUCKLE REPLACE RIGHT SIDE SEAT BELT BUCKLE FAILED SOP PART		
REMOVE SEAT ANC REPLACE BUCKLE		
1 R AND R INNER SEAT BELT BUCKLE ASSEMBLY TO REPLACE		
TECH VER CONCERN FOUND DR SIDE BELT BROKEN, REPLACED RETESTED ALL OK		
DOES NOT OPERATE PROPERLY REPLACE LEFT BUCKLE TEST LEFT AND RT SEATBELT BUCKLES		
840 42 61203 INSPECT AND REPLACE SEAT BELT BUCKLE		
REPLACED RIGHT SEAT BELT BUCKLE		
REPLACE BOTH FRONT SEAT BELTS PER RECALL		
REPLACED PASS. SEATBELT BUCKLE ASSY.		

DOESNT OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE  
REPLACE STICKING LEFT FRONT BUCKLE

CHECKED CUSTOMERS CONCERN WITH THE SEAT BELT CONFIRMED CUSTOMERS CONCERN REMOVE

SUPPLIED CUSTOMER WITH SEAT BELT LATCH UNDER WARRANTY. CUSTOMER INSTALLED

DOES NOT OPERATE PROPERLY R&L PS SEAT REPLACE SEAT BELT BUCKLE REASSEMBEL RETEST

DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED. CHECK AND REPLACE LEFT SEAT BELT BUCKLE

VERIFIED CONCERN AND REPLACED BELT

REMOVED THE RIGHT FRONT SEAT FOR ACCESS TO REMOVE AND REPLACE THE SEAT BELT BUCKLE

CHECK AND REPLACE SEAT BELT BUCKLES  
REPL SEAT BELT BUCKLE ASSY

DID VERIFY CUSTOMERS CONCERN ORDER AND INSTALL A NEW RT FRONT SEAT BELT BUCKLE ASSY

BOTH BUCKLES NOT HOLDING. TEST BOTH FRONT SEAT BELT BUCKLES. BOTH FAILED TEST. REPLACE

REMOVE REPLACE RIGHT FRONT SEATBELT ASSEMBLY

REPLACE THE SEAT BELT ASSEMBLY VERIFY THE SEAT BELT IS WORKING NORMALLY

VERIFIED CONCERN FOUND SEAT BELT ASSEMBLY AND RETRACTOR INOP R AND R SEAT BELT ASSE

SEAT BELT CLASP, INOP. SEATBELT ASSEMBLY FRONT REPLACE

SEATBELT WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE

REPLACED RT FT SEAT BELT BUCKLE WONT LATCH

51 SEATBELT ASSEMBLY FRONT REPLACE

CC 42, CCC S40 INSTALLED SEAT BELT BUCKLE DRIVERS SIDE 605

SEAT BELT BINDING. SOP RO 48864 10 08 01 W 18088 MILES REPLACED D S SEAT BELT BUCKLE. RO 4

DOES NOT OPERATE PROPER SEATBELT ASSEMBLY FRONT REPLACE  
CHECK,REPLACE RIGHT SIDE PRETENSIONER AS PER RECALL

CHECK BELT WITH TOOL DRIVER SIDE FRONT NO GOOD MT TIME IS TO REMOVE ADD ON CONSOLE

DEFECTIVE VERIFY CONCERN. INSTALL SPECIAL ORDERED SEAT BELT BUCKLES (BOTH)

REPLACED DRIVER SIDE SEAT BELT

CK OUT AND R R LEFT FRT SEAT REPLACE SEAT BELT BUCKLE END

SEAT BELT WOULD NOT STAYED BUCKLED REPLACED BUCKLE

10008 W CHECK OUT PASSENGER FRONT SEAT BELT BUCKLE WILL NOT LATCH.REMOVE SEAT AND RE

CONFIRMED CUSTOMER CONCERN, FOUND SEAT BELT NOT LATCHING NEC TO REMOVE AND REPLACI

INSPECTED BELTS WILL NOT LOCK ALL THE TIME. REP LACED BOTH BELT ASSY

BUCKEL JAMED REPLACED WITH NEW BELT

3453 REPL LFRT SEAT BELT BUCKLE

CHECK,REPLACE BUCKLE ASSY,RECHECK,OK

6503 61203 DRIVERS SEAT BELT BUCKLE INTERMITTENT 42 REPLACED DRIVERS SEAT BELT BUCKLE. F

INSTALLED SEAT BELT RF LATCH

BUCKLE HAS INTERNAL FAILURE S40 42 INSPECT REMOVE REPLACE DRIVER SEATBELT BUCKLE.

REPLACED RT FRONT SEAT BELT

REMOVE AND INSTALL LEFT FRONT SEAT TO REPLACE INNER SEAT BELT BUCKLE ASSEMBLY

CHECK OUT BOTH FRT SEAT BELT BUCKLES NOT STAYING LATCHED, REPLACE BOTH FRT SEAT BELT I

6669 INSTALLED NEW SEATBELT BUCKLE



2001 Exped repeat repair\_CUST\_TXT

CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED

C S THE DRIVERS SEAT BELT WILL NOT STAY LATCHED

S25 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE

CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.

OK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN

S26 LT FT SEAT BELT WONT STAY LATCHED

CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE.

WARRANTY REPAIR DRIVER SIDE SEAT BELT BUCKLE WILL NOT HOLD

CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED

S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIV

DRIVER SIDE SEATBELT DOESNT HOLD

CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE

OK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART

RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK

TB0 C S DRIVERS SEAT BELT WONT STAY LATCHED SOP

S28 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED

CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE..

CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO

CK DRIVERS SEAT BELT WONT STAY ATTACHED  
DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED

S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING

S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533

S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533

S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE

CUSTOMER STATES THE DRIVERS SEAT BELT WILL NOT STAY LATCHED

LEFT SEAT BELT WONT HOLD

CUSTOMER STATES SEAT BELT NOT OPERATING PROPERLY

DR SHLDR BELT WONT STAY BUCKLED UP

PASSENGER SEAT BELT WILL NOT HOLD

CK SEATBELT AT R F COMES UNLATCHED AT TIMES

SEAT BELT, FRT. WILL NOT STAY LATCHED

REPAIR BOTH FRONT SEAT BELTS WONT STAY BUCKLED

SEAT BELTS ARE NOT HOLDING ON BOTH THE DRIVERS SIDE AND THE PASS. SIDE, CORRECT FOR

CK PASS SEATBELT WONT STAY CLICKED

SEAT BELT NOT HOLDING

CUST STATES SEAT BELTS DONT STAY LATCHED.

OTHER RESTRAINT TROUBLES THE SEAT BELTS DO NOT STAY ENGAGED

CUSTOMER SAYS DRIVERS SEATBELT WONT STAY LATCHED

PASS SIDE SEAT BELT WONT STAY LATCHED

STATES SEAT BELT BUCKLE DOES NOT HOLD SEATBELT IN PASSENGER SIDE

PASS SIDE SEAT BELT DOESN'T STAY BUCKLED

RIGHT FRONT SEAT BELT WONT STAY LATCHED.

CUSTOMER STATES THE PASSENGER SEAT BELT WONT STAY LATCHED(RECALL PREVIOUSLY PERFO

CHECK PASSENGER FRONT SEAT BELT IT DOESNT HOLD

CK/ADV PASS SIDE SEAT BUCKLE WONT STAY LATCHED 40

PASS SIDE SEATBELT WONT STAY LATCHED. (S25) CUST HAD 01S21 PERFORMED ELSEWHERE AND W

CK RT SEAT BELT DOESNT STAY LATCH

PASSENGER SEAT BELT DOESNT HOLD

CHECK DRIVERS SEAT BELT

CUSTOMER STATES R F SEAT BELT WILL NOT STAY BUCKELED

RF SEATBELT ASSY WILL NOT STAY LATCHED

CUSTOMER STATES DRIVERS SEAT BELT DOESNT STAY LATCHED

CHECK DRIVER SIDE SEAT BELT WONT STAY LATCH

CUSTOMER STATES FRONT SEAT BELT WILL NOT STAY LATCHED BOTH DRIVER AND PASSENGER CHE

PASS SEAT BELT WONT STAY LATCH

CUSTOMER STATES PASSENGER SEATBELT PULLS APART. INSTALL SOP

PASS FRONT SEAT BELT WILL NOT STAY LATCHED POPS OPEN WHILE DRIVING  
C S PASS SIDE SEAT BELT WILL NOT STAY LOCKED

BOTH DRIVER AND PASSENGER SIDE SEAT BELTS WILL NOT STAY BUCKLED

E

RS SEAT BELT BUCKLE FUNCTION TEST PASS.

RETEST.

FRONT STAY BUCKLED. REMOVE DRIVER'S SEAT TO GAIN ACCESS. REPLACE DRIVER'S

RIGHT BELT BUCKLE RIGHT SIDE FRONT FOR NO LATCHING PROPERLY. VERIFIED SEAT BELT LATCHES NOW. TEST

FRONT SEAT BELT BUCKLE RIGHT FRONT SEAT. RECHECK. OK.

ASSEMBLY.

1. CHECK, OK


ED AND REPLACED DRIVERS SEAT BELT


E RECHECK OPERATION OK

--

E AND REINSTALLED THE SEAT.


RECHECK ALL OK NOW HAD TO R AND R RT FRONT SEAT TO REPLACE .

E BOTH SEAT BUCKLES. RETEST OK


SEMBLY AND RETRACTOR B TIME USE TO ACCESS INTERIOR PANEL TO REPLACE


19108 10 17 01 W 18384 MILES


REPLACE CHARGED SEAT BELT BUCKLE. INSTALL PASSENGER FRONT SEAT AND TEST SEAT BELT BUCK

LE SEAT BELT BUCKLE OK NOW


FAILS ON CUSTOMER.


BUCKLES (NOT OPERATING PROPERLY)

--


ON GIVEN

F LOCK

RIGHT FRONT SEATBELT WONT STAY LATCHED

RT FRT SEAT BELT WILL NOT STAY LATCHED

RT SIDE SEAT BUCKLE WONT STAY LATCHED

CUSTOMER STATES THAT THE PASS FRONT SEATBELT LATCH IS NOT HOLDING, SOP  
PASSENGER SIDE SEAT BELT WONT STAY HOOKED

PASSENGER SEATBELT WILL NOT STAY LATCHED SOP

CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT ALWAYS STAY IN HOLDER  
PASSENGER SEAT BELT WILL NOT STAY LATCHED

CUSTOMER STATES RF SEATBELT WILL NOT STAY LATCHED.  
SEAT BELT WONT STAY LATCHED

CS DRIVER SEATBELT WILL NOT STAY LATCHED  
CUST STATES DRIVER SIDE SEAT BELT BUCKLE WONT STAY LATCHED

CHECK FOR PASSENGER SEAT BELT BUCKLE NOT STAYING LATCHED

CUSTOMER STATES: DRIVERS SEATBELT DOES NOT LOCK WHEN BUCKLED, MUST PUSH IN 5 6 TIMES TO LOCK BUCKLE.

CHK AND ADVISE CUST STATES FRONT PASSENGER SIDE SEAT BELT BUCKLE RELEASES BELT, IT DOES NOT STAY BUCKLED. S28

S40 CUSTOMER STATES DRIVERS SEATBELT LOOSE

PASSENGER SEAT BELT BUCKLE WILL NOT STAY BUCKLED PART IN

CUSTOMER REPORTS PASSENGER FRONT SEATBELT WILL NOT HOLD

BOTH FRONT SEAT BELT BUCKLES WILL NOT LATCH

SEAT BELT WILL NOT STAY BUCKLED

SEAT BELT BUCKLE WILL NOT STAY LOCKED

REPLACE SEAT BELT BUCKLES WONT HOLD

PASS SEATBELT WONT HOLD

SOP RIGHT FRONT SEAT BELT WONT STAY BUCKLE

CUSTOMER STATES THE SEAT BELT BUCKLE WILL NOT STAY FASTENED

FRONT SEAT BELT BUCKLES DO NOT HOLD

PASS FRONT SEATBELT BUCKLE WILL NOT STAY LATCHED

DRIVERS SEAT BELT WONT STAY FASTENED

CUSTS AYS FRT SEAT BELTS WONT HOLD

DR SEAT BELT WOULD NOT STAY LATCHED.

RT FRONT SEAT BELT DOESNT STAY LATCHED ERRATIC BUT OFTEN

S26 AT TIMES DRIVERS SEAT BELT LATCH WILL NOT HOLD.

RIGHT FRONT SEAT BELT BUCKLE LOOSE SOP HERE

DRIVER FRONT SEAT BELT IS LOOSE AT ATTACHING POINT ALSO CHECK FEMALE LATCH TO ENSURE PROPER LATCHING

RT FRT SEAT BELT BUCKLE RELEASE BUTTON STICKS

CUSTOMER REPORTS PASSENGER FRONT SEATBELT WILL NOT HOLD

L F SEATBELT BUCKLE WILL NOT STAY LATCHED  
SEAT BELT WONT HOLD

CUSTOMER STATES SEAT BELTS DO NOT STAY LATCHED

CUSTOMER STATE BOTH FRONT SEAT BELT WILL NOT STAY LATCHED RECALL HAS ALREADY BEEN PERFORMED AND PASSED

DRIVERS SIDE SEATBELT WILL NOT STAY LATCHED

CHECK BOTH FRONT SEAT BELTS WILL NOT STAY LATCHED IN BUCKLES.

CK FOR DRIVERS SIDE SEAT BELT, NOT STAYING LATCHED

CUSTOMER REQUEST TO RECHECK BOTH FRT SEAT BELTS AS RELATED TO RECALL; NOT STAYING BUCKLED.

SEAT BELTS WILL NOT STAY LATCHED

SEATBELTS WILL NOT STAY BUCKLED

**BOTH FRONT SEAT BELTS WONT STAY LATCHED**

**CUSTOMER STATES: DR. SIDE SEAT BELT RECIEVER NOT HOLDING**

**CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED**

**DRIVERS SEAT BELT W STAY BUCKLED SOP**

**R F SEATBELT WILL NOT STAY BUCKLED. S.O.P.**

**DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED**

**CUST STATES DRIVERS SIDE SEAT BELT WONT STAY LATCHED**

**FRONT SEATBELT BUCKLE WONT HOLD**