

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
BOOK 37
PART 3 OF 6

4/1/2002	13	7759686	17860	2952	*	NA	WI	11001	b
3/1/2002	7	7214950	5433	3170	*	NA	CO	11001	b
1/28/2002	11	6570581	13355	2478	*	NA	TX	11001	b
12/5/2001	11	5553176	16782	4922	*	NA	FL	11001	b
12/12/2001	7	5718468	8044	2199	*	NA	OH	11001	b
2/25/2002	6	7307822	8796	1625	*	NA	FL	11001	b
8/20/2001	5	3085983	3157	3362	*	NA	NC	11001	b
5/22/2002	7	8852832	11017	2415	*	NA	TX	11001	b
5/16/2002	7	8646244	5428	4985	*	NA	FL	11001	b
5/22/2002	12	8739250	28770	1237	*	NA	NJ	11001	b
5/2/2002	4	8661159	3919	147	*	NA	VA	11001	b
4/2/2002	3	7859321	2687	2070	*	NA	OH	11001	b
3/20/2002	6	7531950	5022	9443	*	NA	MN	11001	b
3/6/2002	4	7361978	6443	964	*	NA	NC	12001	b
3/25/2002	12	7742699	12372	7712	*	NA	CA	11001	b
11/27/2001	7	5732048	6414	10144	*	NA	CA	11001	b
2/11/2002	7	7158707	5231	565	*	NA	NY	11001	b
4/16/2002	10	8008961	13888	3626	*	NA	NY	11001	b
3/6/2002	13	7237518	24697	1596	*	NA	TX	11001	b

2/7/2002	11	6757257	20260	1864	*	NA	CA	11001	b
1/18/2002	4	6400476	6370	3789	*	NA	AZ	11001	b
1/15/2002	4	6407114	1084	7419	*	NA	OH	11001	b
6/16/2002	11	8700087	17509	8466	*	NA	TX	11001	b
1/8/2002	5	6196560	7420	2672	*	NA	MI	11001	b
4/9/2002	10	8044359	10268	6040	*	NA	AR	11001	b
12/26/2001	7	5920781	14928	2413	*	NA	TX	12001	b
12/24/2001	5	5924838	12550	3861	*	NA	TX	12001	b
1/28/2002	5	6692176	6610	7166	*	NA	NE	12001	b
4/8/2002	11	7973966	22554	2672	*	NA	MI	11001	b
1/25/2002	6	6526452	2432	20402	*	NA	AZ	12001	b
3/26/2002	5	7844536	4522	8473	*	NA	TN	11001	b
12/7/2001	4	5702336	5012	7735	*	NA	CA	11001	b
1/22/2002	5	6457416	11459	4143	*	NA	TN	11001	b
2/26/2002	10	8385754	27410	8616	*	NA	OR	12001	b

1/9/2002	5	6667881	9569		1389	*	NA	WA	11001	b
11/28/2001	3	5938782	6802		20238	*	NA	IA	11001	b
11/29/2001	3	5433609	3506		5100	*	NA	MO	11001	b
2/8/2002	1	6863372	306		1894	*	NA	IL	11001	b
11/23/2001	6	5455155	6365		1384	*	NA	PA	11001	b
11/20/2001	2	5488190	2452		1402	*	NA	DE	11001	b
11/16/2001	1	6231069	3289		9420	*	NA	MN	11001	b
1/22/2002	4	7424059	9229		7818	*	NA	GA	12001	b
11/12/2001	1	6545897	2804		4824	*	NA	FL	11001	b
12/4/2001	8	5527371	13842		6218	*	NA	MI	11001	b
12/10/2001	4	5727612	6004		6461	*	NA	LA	11001	b
1/15/2002	8	6337648	6858		2061	*	NA	WV	11001	b
11/14/2001	3	5197617	4810		6420	*	NA	UT	11001	b
1/28/2002	10	6527901	14991		20116	*	NA	IA	11001	b
1/4/2002	14	6119360	24368		3943	*	NA	FL	12001	b
11/14/2001	2	5100362	564		3415	*	NA	IA	11001	b
1/4/2002	8	6311064	12452		2336	*	NA	OH	11001	b
10/26/2001	2	4774392	1765		1940	*	NA	KY	12001	b

1/28/2002	7	8689188	8464	9053	*	NA	ME	11001	b
5/1/2002	12	8638990	17384	903	*	NA	NC	11001	b
10/22/2001	2	4612915	3879	1762	*	NA	PA	11001	b
11/18/2001	4	5497130	2959	5401	*	NA	CA	12001	b
11/28/2001	6	5751885	9888	4556	*	NA	TX	11001	b
10/19/2001	2	4595732	4054	9180	*	NA	MA	11001	b
11/12/2001	3	5984590	5601	9075	*	NA	MA	11001	b
11/2/2001	7	4973462	4192	1876	*	NA	IL	11001	b
11/27/2001	4	5338166	4965	5143	*	NA	MO	11001	b
12/19/2001	3	6861307	2273	638	*	NA	NY	11001	b
10/19/2001	7	4793412	5253	5417	*	NA	CA	11001	b
1/10/2002	10	6523816	24588	9315	*	NA	MN	12001	b
10/8/2001	7	4453900	18098	4583	*	NA	TX	11001	b
10/25/2001	8	4831635	2836	7761	*	NA	HI	12001	b
1/25/2002	10	6539918	7287	2600	*	NA	OH	11001	b
11/29/2001	8	5904110	11325	5998	*	NA	NJ	11001	b
11/28/2001	4	8047348	10707	7828	*	NA	CA	11001	b
12/8/2001	11	5728901	10745	7749	*	NA	CA	12001	b

12/27/2001	8	5950458	16103	2331	*	NA	OH	12001	b
12/4/2001	6	5558816	5766	8316	*	NA	MT	11001	b
10/5/2001	5	4290942	10006	9704	*	NA	MI	11001	b
10/10/2001	5	4425732	11500	7800	*	NA	CA	12001	b
10/10/2001	5	5455154	8112	1394	*	NA	PA	11001	b
1/19/2002	12	6389394	25360	3781	*	NA	FL	11001	b
8/28/2001	2	4082328	3453	8042	*	NA	TX	11001	b
9/7/2001	5	4678936	4914	2800	*	NA	OH	11001	b
11/7/2001	7	4988247	6503	8547	*	NA	WA	12001	b
11/7/2001	3	7854933	2700	151	*	NA	MI	11001	b
10/4/2001	11	4180691	13536	5685	*	NA	TN	11001	b
8/15/2001	1	4945192	4444	1999	*	NA	IN	11001	b
8/29/2001	3	3655611	6007	9640	*	NA	MI	11001	b
2/14/2002	8	6893905	16448	4532	*	NA	TX	11001	b
8/29/2001	3	3347390	6669	389	*	NA	TN	12001	b
10/4/2001	4	4209618	6768	4483	*	NA	TX	11001	b
11/27/2001	4	6988790	9440	2415	*	NA	TX	12001	b

10/23/2001	1	5127560	3321		2415	*	NA	TX	11001	b
4/15/2002	4	8010890	2792		4283	*	NA	TX	11001	b
11/3/2001	6	4941034	15999		402	*	NA	GA	12001	b
8/7/2001	2	3405523	1074		7283	*	NA	OR	12001	b
10/8/2001	4	4928125	8414		8913	*	NA	MA	11001	b
5/10/2002	12	8639394	35624		1864	*	NA	CA	12001	b
8/27/2001	6	3586579	12164		5627	*	NA	TN	12001	b
1/29/2002	8	6632628	14861		3890	*	NA	NY	11001	b
2/7/2002	7	8782667	11773		2013	*	NA	VA	11001	B
4/17/2002	14	8270661	28517		452	*	NA	WI	11001	B
10/8/2001	3	4310129	2216		2964	*	NA	MI	11001	B
11/12/2001	4	5188613	7305		4077	*	NA	VA	11001	B
3/2/2002	13	7210086	18665		1005	*	NA	NC	11001	B
3/6/2002	15	7261100	41491		1763	*	NA	WI	11001	B
4/18/2002	11	8116216	8936		601	*	NA	NY	11001	B
2/13/2002	5	6919657	10070		4791	*	NA	IN	11001	B
3/1/2002	5	7183710	5611		1014	*	NA	NC	11001	B
5/9/2002	12	8641800	31287		2916	*	NA	MI	11001	B
4/8/2002	16	7837214	19783		4532	*	NA	TX	11001	B
3/12/2002	7	7418748	11279		4143	*	NA	TN	11001	B

RO94-011 14402

12/19/2001	6	5829900	8818		B8802	*	NA	ON	11001	B
37242	10	6104529	12457		13109	*	NA	CT	11001	b
37391	12	8755718	29383		10346	*	NA	CA	11001	b
37162	8	4884537	1050		11608	*	NA	FL	11001	b
37189	7	4662111	5050		9668	*	NA	MI	11001	b
37214	7	5287504	6000		10656	*	NA	GA	11001	b
37323	11	7319210	10999		6820	*	NA	OK	11001	b
37096	0	4122221	11		10164	*	NA	TX	11001	b
37229	8	5563745	10892		13901	*	NA	MI	11001	b
37302	9	8521878	9483		12712	*	NA	CA	11001	b
37188	7	4643773	21225		1401	*	NA	MD	11001	b
37383	19	8495137	20336		11467	*	NA	TX	11001	b
37181	9	4564327	20645		11508	*	NA	KY	11001	b
37214	2	8027072	3733		10576	*	NA	OH	11001	b
37389	19	8595671	16445		6743	*	NA	NC	11001	b
37187	8	5350461	14168		45251	*	NA	FL	11001	b
37182	3	4754615	4114		10804	*	NA	TX	11001	b
37180	2	4584256	5660		3902	*	NA	AL	11001	b

RO94-011 14483

37399	9	8840038	6993	10183	*	NA	MI	11001	b
37383	15	8805964	29338	10824	*	NA	WV	11001	b
37303	10	6956917	14842	11442	*	NA	TX	11001	b
37413	19	9051750	26420	11650	*	NA	FL	11001	b
37344	13	7906433	25482	13570	*	NA	TX	11001	b
37176	0	4398111	5	13981	*	NA	MI	11001	b
37214	7	6287504	6000	10656	*	NA	GA	11001	b
37252	12	6002060	17025	11492	*	NA	TX	11001	b
3/1/2002	13	7287639	6733	3072	*	NA	GA	11001	b
4/29/2002	4	8288071	1050	6645	*	NA	TN	11001	b
10/10/2001	7	4556537	8568	7024	*	NA	MO	11001	b
11/19/2001	11	5453993	7619	1058	*	NA	OH	11001	b
9/27/2001	8	3986471	7923	1359	*	NA	PA	11001	b
4/11/2002	12	7939533	12687	68	*	NA	MD	11001	b
11/5/2001	7	5016351	7669	8568	*	NA	OR	11001	b
4/1/2002	5	8247354	18757	2629	*	NA	TX	11001	b
12/11/2001	8	5784398	10416	5089	*	NA	MO	11001	b
10/24/2001	6	7350359	18201	9645	*	NA	MI	11001	b

FD-904-011 14404

11/12/2001		5185658	24793		3019	*	NA	FL		B
2/18/2002		7244043	26208		4745	*	NA	IN		B
2/1/2002		6650488	13212		68	*	NA	MD		B
2/4/2002		6732787	22817		1759	*	NA	AZ		B
11/13/2001		5103392	10681		4617	*	NA	TX		B
12/17/2001		8695105	8187		5464	*	NA	CA		B
3/2/2002		7184132	16713		1237	*	NA	NJ		B

2001 Exped repeat repair TECH TXT1

WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE

SEATBELT RECEIVER FAILURE SEATBELT RECEIVER FRONT
REPLACE

1 VERIFIED CONCERN INSTALLED SOP THE DRIVER SEAT BELT BUCKLE
RETESTED OK AT THIS TIME

DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT
LATCH,RECHECKED OK.

SEAT BELT LATCH BROKEN M TIME TO REPLACE SEAT BELT LATCH

5328 01 61203 R R DRIVER SEAT ACESS REPLACED DRIVER SEAT BELT
BUCKLE BINDING

TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT
SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.

BUCKLE HAD A BROKEN & JAMMED PUSH BUTTON REPLACD THE
DRIVER SIDE SEAT BUCKLE ASSY,TESTED ALL FUNCTIONS AFTER THE
REPAIR,ALL TO SPEC AT THIS TIME

INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.

REPLACED SEAT BELT BUCKLE

REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH

TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE

HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT
BUCKLE ASSEMBLY.

VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED
NEW BUCKLE & RE CK OK

10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 CASUAL PART 1L7Z 7881203 BAA
CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION
CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.
1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST
10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE
REPLACED SEAT BELT LATCH
REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD
CC487 REPLACED BOTH SEAT BELT BUCKLES
CC487 REPLACED BOTH SEAT BELT BUCKLES
CC487 REPLACED SEAT BELT BUCKLE
SEATBELT LATCH BAD CHECKED SEAT BELT LATCH,REPLACED LEFT FRONT SEAT BELT LATCH ASSY
REPLACED LATCH ON DRIVERS SEAT BELT
SEAT BELT NOT HOLDING AT ALL TIMES REMOVE SEAT BELT AND REPLACE SEAT BELTS WITH NEW FACTORY PARTS 42 826
BUCKLE WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE
DIAGNOSE,R AND R SEAT BELT AND R AND R BUCKLE ASSEMBLY
17160 W REMOVE PASSENGER SEAT AND REPLACE BUCKEL. WILL NOT STAY LATCHED AT TIMES.
VERIFY AND DIAG., REPL. BELT AND BUCKLE ASY... CLM. SUBMISSION DELAYED DUE TO SOP... NEW DATE IS 10.26.01 AND MILES ARE 14228

BOTH FRONT SEAT BELT BUCKLES WONT STAY BUCKLED REPLACED BUCKLES CLOSED BYWPI
9000 REMOVED BOTH FRONT SEATS IN ORDER TO REPLACE BOTH SEAT BELT BUCKLES. REINSTALL SEATS. BUCKLES TEST OK
INOP REPLACED PASS SEAT BELT BUCKLE
REPLACED LH SEAT BELT BUCKLE
TESTED BOTH FRONT SEAT BELTS, BOTH FAILED, REPLACED BOTH FRONT SEAT BELT BUCKLES...3017
CHECK SEAT BELT OPERATION, REPLACE RIGHT FRT SEAT BELT.
CHECK OUT SEAT BELT OPERATION, REPLACE LEFT SIDE SEAT BELT BUCKLE
3137 ORDERED SEAT BELT BUCKLE REPLACED PASS SEAT BELT
REPLACED BUCKLE
REPLACED PASS SIDE SEAT BELT
REPLACE SEAT BELT LATCH ASSY.
REMOVED RIGHT FRT. SEAT TO REPLACE SEAT BELT BUCKLE ASSEMBLY AS IT WOULD NOT STAY LATCHED AT TIMES
RIGHT FRONT SEAT BELT BAD ADD ON
TAKE SEAT OUT R R GAS CHARGED BUCKEL.
REPLACED SEATBELT BUCKLE ASY
REPLACE THE SEAT BELT BUCKLE ASSY WONT STAY LATCHED
5690 REPLACED DRIVERS SIDE SEATBELT BUCKLE CUSTOMER STATED THAT THE SEAT BELT STILL WOULD NOT STAY LATCHED PROPERLY
1 CHECKED BUCKLE, LATCH FEELS LOOSE. REMOVED SEAT, REPACED BUCKLE. RETESTED, OK.
REPL RF SEAT BELT ASSY.
SEATBELT LATCH ASSEMBLY WEAK

CHECK OUT REPLACE LEFT FRONT SEAT BELT

1 REPLACED BOTH SEAT BELTS.

13355 INOP 61172A REPLACE PASS. SEAT BELT

BROKEN SEATBELT ASSEMBLY FRONT REPLACE

VERIFIED CUSTOMERS CONCERN SEAT BELT BUCKLE WILL NOT STAY LATCHED R AND R PASSENGER SEAT TO REPLACE SEAT BELT BUCKLE REPLACED AND RECHECK ALL OK AT THIS TIME

REPLACED PASS SIDE SEAT BELT

TESTED TO VERIFY.FOUND SEAT BELT WOULD NOT STAY BUCKLED. CK OASIS FOR RECALL, NO RECALL PRESENT.INSPECT SEATBELTS HAVE INTERNAL DEFECT.NEC TO RR SEATBELT.

CUSTOMER STATES DRIVERS SEAT BELT WONT STAY LATCHED

DRIVERS SEAT BELT DOES NOT STAY BUCKLED

DRIVERS SEATBELT WONT STAY LATCHED

CHECK PASSENGER SIDE SEAT BELT WONT STAY LATCHED

REPAIR RIGHT FRONT SEAT BELT WILL NOT STAY LATCHED

RIGHT SIDE SEAT BELT WILL NOPT STAY LATCHED

S40 SEATBELTS WILL NOT STAY LATCHED

CUSTOMER STATES THE DRIVERS SEAT BELT BUCKLE WILL NOT ALWAYS HOLD

CUSTOMER STATES PASSENGERS FRONT SEAT BELT WILL NOT STAY BUCKLED

CUST STATES LEFT SEAT BELT BUCKLE DOESNT ALWAYS HOLD

C S PASS FRNT SEAT BELT BUCKLE OPENS SOP

CUST STATES SEATBELT WONT STAY BUCKLED

CUST STATES DRIVERS SEATBELT WONT STAY BUCKLED AT TIMES
SPO IN 341

C S DRIVERS SEAT BELT BUCKLE WILL NOT STAY LOCKED TESTED WITH
BUCKLE TESTER AND FAILED

RIGHT FT SEAT BELT WILL NOT STAY BUCKLED

DRIVERS SEAT BELT WILL NOT STAY BUCKLED

L H FRT SEAT BELT WONT STAY BUCKLED

SEAT BELT DOES NOT HOLD

S40 VEH PASS SEAT BELT WILL NOT HOLD AT ALL TIMES

CUST STATES D.S. SEAT BELT WONT STAY LATCHED
SEAT BELT WONT STAY LATCHED

R H FRT SEAT BELT BUCKLE WONT STAY BUCKLED

FACTORY WARRANTY CUSTOMER STATES DRIVERS SIDE SEAT BELT
WONT STAY LATCHED

S26 STATES THAT THE PASS SEATBELT WILL NOT STAY LATCHED SEE
DARWIN

DRIVERS SIDE SEAT BELT WILL NOT STAY BUCKLED

CUSTOMER STATES P S FRONT SEAT BLET BUCKLE INOP AT TIMES

RECALL 01S21 PASS SEATBELT DOES NOT HOLD

CUST STATES THE RF SEAT BELT WILL NOT STAY BUCKLED.REPORT.

PASSENGER FRONT SEAT BELT NOT STAYING LATCHED

DRIVERS SEAT BELT WONT STAY LATCHED. PART HERE TO CORRECT.

CUSTOMER STATES L FRT SHOULDER BELT WONT STAY BUCKLED

CUSTOMER STATES DR SIDE BELT WILL NOT STAY CLIPPED

LEFT SEAT BELT WILL NOT STAY BUCKLED

CHECK SEAT BELTS.....DR SEAT BELT WILL NOT HOLD... CUST REQUEST
CHECK ALL BELTS.....

SEAT BELT ON PASS FRONT COMES UNBUCKLED

CHECK BOTH FRONT SEAT BELT BUCKLES DO NOT HOLD PROPERLY

PASS SIDE SEAT BELT WILL NOT LATCH ALL THE TIME.

PLEASE CK THE SEAT BELT LATCH PASSENGER SIDE COMES
UNSNAPPED

CHECK DR SEATBELT WONT HOLD

CUSTOMER STATES THAT THE DRIVERS SEAT BELT KEEPS COMING UN
DONE PLEASE CHECK

SEAT BELT WILL NOT STAY LATCHED OWNER REPLACED BUCKLE

CUSTOMER STATES THE PASS SEAT BELT DOES NOT STAY SOP HERE

OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED

PASSENGER SIDE SEAT BELT NOT STAYING BUCKLED

CUSTOMER STATES THE PASS SIDE SEAT BELT WILL NOT STAY
LATCHED

CUSTOMER SAYS SEAT BELTS DO NOT ALWAYS STAY BUCKLED
B SEAT BELT WONT BUCKLE
CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED
CUSTOMER STATES THAT THE PASSENGER AND DRIVERS SIDE SEAT BELT BUCKLES ARE FAILING NOT SECURE.CHECK AND ADVISE.
INTERIOR TRIM REPAIR CUST STATES R F SEAT BELT KEEPS COMING LOOSE FROM RECEIVER
THE CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED.
CK PASS SEAT BELT WONT LACTH AND POPS OUT WHEN LATCH
RIGHT FRONT SEAT BELT WILL NOT CLASP AT ALL TIMES.
C S THE DRIVER FRONT SEAT BELT WILL SOMETIMES NOT STAY BUCKLED
CUSTOMER STATES:PASS SEAT BELT WILL NOT STAY BUCKLED
INSTALL SOP SEAT BELTS CUST STATES WONT HOLD
DRIVERS SIDE SEAT BELT BUCKLE DOES NOT STAY BUCKLED SEAT BELTS
S40 CUST STATES THAT THE DRIVERS SEAT BELT WONT STAY LATCHED SOP PARTS ARE IN SEE RO#48864
SEAT BELTS DO NOT STAY COUPLED
BELT WONT STAY LATCHED
CUSTOMER STATES CHECK SEAT BELTS ONE WONT HOLD JUST HAD RECALL BY AANOTHER DEALER
CUSTOMER REPORTS L F SEAT BELT WILL NOT STAY LATCHED WILL COME OUT OF BUCKLE
DRIVER SEAT BELT WILL NOT STAY CONNECTED TO BUCKLE

DRIVERS SEATBELT WONT STAY LATCHED SOP IN

SEAT BELT BUCKLE WOULD NOT STAY BUCKLED NEEDS
REPAIRED/RPLCD

CUSTOMER STATES THAT HE WAS INSTALLING HIS CHILD SEAT AND
SEAT BELT WOULD NOT STAY LATCHED

CUSTOMER STATES 1 SEAT BELT WILL NOT HOLD RIGHT SIDE

CUSTOMER REQUEST CHECK OPERATION OF FRONT SEATBELTS
WONT STAY LATCHED

DRIVER S SEAT BELT WILL NOT STAY LOCKED

S26 DRIVERS SEAT BELT BUCKLE WONT HOLD PROPERLY SOP HERE

CHECK SEAT BELT LATCH. WILL NOT STAY LATCHED

INSTALL SOP SEATBELT RECIEVERS BELTS WONT STAY BUCKLED

RIGHT SEAT BELT DOES NOT STAYED LATCHED.

CUSTOMER STATES DRIVER SEATBELT FAILS WILL NOT STAY
BUCKLED.

REPAIR PASS SEAT BELT WONT HOLD

LEFT SEATBELT WONT HOLD SOP

CUST STATES FRT SEAT BELTS WILL NOT STAY LATCHED

DRIVER NEW SEAT BELT BUCKLE NOT HOLD;INSTALL NEW ONE SOP

THE SEAT BELT BUCKLES DO NOT ALWAYS LOCK THE SEAT BELT.

LEFT SEAT BELT WONT STAY LATCHED

SEAT BELTS COME UNBUCKLED BY THEMSELVES

SEAT BELT ON DRIVER SIDE KEEPS UNBUCKLING PLEASE CK AND REPORT

CHECK PASS FRONT SEATBELT HARD TO LATCH UNLATCH

RH FRONT SEATBELT WILL NOT STAY BUCKLED

PS BUCKLE DISCONNECTS REPLACE BUCKLE

CUST STATES DRIVERS SEATBELT BUCKLE DISCONNECTS BY ITSELF AT TIMES

CHECK CENTER SEAT BELT WILL NOT STAY LATCHED

CUSTOMER STATES DRIVERS SIDE SEAT BELT UNBUCKLES.

CHECKED AND REPLACE BUCKLE

INSP AND REPL RT FRT SEAT BELT RE CK OPERATION OKAY

REPLACED RT SEAT BELT BUCKLE INOP

CHECKED AND REPLACED FRONT SEATBELT LATCH ASSY

REPLACE SEAT BELT ASSEMBLY

MT EQUALS TIME TO REPLACE PASSENGER FRONT SEATBELTBUCKLE.

8938 VERIFIED PASS SEAT BELT LATCH STICKING REMOVED SEAT AND REPLACED LATCH RECHECKED OK

REPLACED FAULTY SEAT BELT

REPLACED RF SEATBELT BUCKLE ASSY.

CHECK OUT DRIVER SEATBELT WILL NOT STAY LATCHED, REPLACE DRIVER SEATBELT BUCKLE (NOT WORKING PROPERLY), RECHECK OK

R & R SEAT BELT BUCKLE

REMOVED PAS FRT SEAT BELT BUCKLE DUE TO NOT STAYING LATCHES

REMOVE AND REPLACE DRIVERS SEATBELT

VERIFY CONCERN,DEACTIVATE AIR BAG SYS,R&R PASSN AGER SIDE BELT BUCKLE,REACTIVATE AIR BAG SYS AN D RETEST OK AT THIS TIME.

1050 61202 W RECALL COMPLETE REPL D S SEAT BUCKLE

REPLACED PASSENGER SIDE FRONT SEATBELT BUCKLE M TIME DUE TO NO APPLICABLE LABOR OP

REPLACED PASS FRT SEAT BELT

42,5461202 INSTALLED NEW SEAT BELT

TESTED AND REJPLACED BOTH SEAT BELTS AND BUCKLES

CK AND REPLACED SEAT BELT BUCKLE ASSY

SPLIT BENCH WITH AIR BAGS

REMOVED AND REPLACED SEATBELT

1 REPLACE SEAT BELT LATCH

WILL NOT HOLD PROPERLY SEATBELT ASSEMBLY FRONT
REPLACE

FRONT SEAT BELT BUCKLES DO NOT HOLD CORRECTLY, REPLACED BOTH SEAT BELT BUCKLES WITH SIDE AIR BAGS

CHECK SEATBELT BUCKLE OPERATION REM SEAT TRACK TO GAIN ACCESS REM AND REPL SEATBELT BUCKLE ASSEMBL

R&R DRIVERS SEAT BELT BUCKLE

REPLACE SEAT BELTS WONT HOLD

5080 42 CHECKED OPERATION OF LEFT FRONT SEATBELT BUCKLE, WILL NOT STAY LATCHED. REMOVED LEFT FRONT SEAT TO ACCESS, REPLACED BUCKLE, ASSEMBLED. RETEST PASSED.

REPALCE SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE

BOTH FRONT SEAT BELTS WONT STAY LATCHED

1 VERIFIED CUST COMPLAINT. NECC TO REPLACE LEFT FRONT SEAT BELT BUCKLE. (LATCH NOT HOLDING AT TIMES.)

M TIME USED TO DIAGNOSE AND REPLACE SEAT BELT BUCKLE RIGHT FRONT

VERIFY CONCERN.FOUND BOTH FRONT SEAT BELTS NOT HOLDING. REPLACE SEAT BELT BUCKLES. VERIFY REPAIR.

REPLACED RT FRONT SEAT BELT BUCKLE

REPLACED PASS FRT SEAT BELT

LF SEAT BELT IS BROKEN REPLACED SEAT BELT

REPLACE SEAT BELT

REPLACE FRONT SEAT BELTS

INSPECTED. REPLACED BOTH SEAT BELT BUCKLES.

VERIFY CONCERN. SOP REPLACE SEATBELT.CHECK OPERATION,OK

REPLACED BOTH FRONT SEAT BELT BUCKLE ASSEMBLIES.

12687 SEAT BELT BUCKLE WARR REPLACED DRIVERS SIDE SEAT BELT BUCKLE

TEST AND BOTH SEAT BELTS FAILED REPLACED BOTH LEFT AND RIGHT FRT SEAT BELT BUCKLES

CHECKED AND TESTED. REPLACED BOTH SEAT BELT HALVES.

REPLACED BOTH FRONT SEATBELTS.

SEAT BELT CHECK BOTH FRONT SEATBELT LATCHES WILL NOT STAY LATCHED REPLACED BOTH FRONT SEAT BELT ASSY FINAL TEST PASSED

REMOVE DR SEAT ASSY AND REPL DR SEAT BELT RECIEVER. MT TIME FOR REPAIR.

81203 S40 42 SEAT BELT DOSE NOT HOLD REPLACE DRIVERS SEATBELT LATCH ASSEMBLY

13212 DRIVERS SEAT BELT WONT STAY BUCKLED WARR REPLACED L F SEATBELT BUCKLE

REPLACED RT FRT SEATBELT ASSY.

10681 1.0 HRS TESTED OLD SEATBELT, REPLACED WITH NEW. C P

DIAG REPLACE SEAT BELT BROKEN

REPLACE BUCKLES BOTH SIDES

2001 Exped repeat repair TECH_TXT2

INSPECT SEAT BELT RETRACTOR AND BUCKLE, R R DRINERS SEAT PWR. REPLACE SEAT BELT BUCKLE.
VERIFIED. REPLACED SEAT BELT BUCKLE ON DRIVERS SEATBELT.
REPLACE SEATBELT PRETENSIONER
REPLACED SEAT BELT ASSEMBLY FOR BUCKLE NOT LATCHING
CHECK OUT REMOVE SEAT REPLACED RIGHT BUCKLE
REPLACED SEAT BELT LATCH
CAUSAL PART 1861202 CKED AND REPLACED BOTH FRONT SEATBELTS CONDITION CODE 07
INSPECT AND REPLACED SEAT BELT BUCKLE
REPLACED RIGHT FRONT SEAT BELT ASSY
6231 . REPLACED LEFT FRONT SEAT BELT BUCKLE, NOT HOLDING 100% OF THE TIME.
13888 R&R R F SEAT & REPLACE SEAT BELT BUCKLE CHECK OPERATION & VERIFIED REPAIR
VERIFIED CUST CONCERN REPLACED DRIVERS SIDE SEAT BELT BUCKLE

ROSA-811 14421

DRIVERS SEATBELT WONT BUCKLE SEATBELT ASSEMBLY FRONT
REPLACE

8370 2581203 VERIFIED CONCERN. ACCESSED DRIVERS SEAT.
REMOVED AND INSTALLED NEW DRIVERS SEAT BELT BUCKLE.
FUNCTION TEST PASS.

WONT RECOIL SEAT BELT ASSEMBLY REAR RIGHT OR LEFT
REPLACE

VERIFIED CONCERN, FOUND SEAT BELT UNBUCKLING BY ITSELF.
REMOVED AND REPLACED BUCKLE. RETEST.

COND. CODE 42, BASE PART NUMBER 2581203. . VERIFY CONCERN.
LEFT FRONT SEAT BELT BUCKLE WONT STAY BUCK LED. REMOVE
DRIVERS SEAT TO GAIN ACCESS. REPLACE DRIVERS

REPLACED FAULTY SEAT BELT
DM1ACEAL

14928 CC 42 (81202) VERIFIED CONCERN R&I PASSENGER FRONT SEAT
FOR ACCESS TO REPLACE SEAT BELT BUCKLE RT SIDE FRT FOR NO
LATCHING PROPERLY, VERIFIED SEAT BELT LATCHES NOW. TECH 8292

INSTALL DRIVER SIDE SEAT BUCKLE BROKE 1

LATCH BROKE REPLACED

COND. CODE 42, BASE PART NUMBER 1881202. VERIFY CONCERN.
REMOVE RIGHT FRONT SEAT. REPLACE SEAT BELT BUCKLE RIGHT
FRONT SEAT. RE CK. OK.

1 REPLACE BUCKLE

CHECKED AND FOUND SEAT BELT TO BE RELEASING PREMATURELY.
REPLACED SEAT BELT BUCKLE ASSEMBLY.

BELT WILL NOT STAY BUCKLED REPLACE LEFT BUCKLE

REPLACED RIGHT FRONT SEAT BLET BUCKLE

CHECK AND REPLACE BUCKLES

CONFIRM SEATBELT WILL NOT BUCKLE. REPLACE PASSENGER SIDE SEATBELT. M TIME TO DO REPAIR. CHECK, OK

INSPECT FRONT SEAT BELT BUCKLE REPLACE RIGHT SIDE SEAT BELT BUCKLE FAILED SOP PART

REMOVE SEAT ANC REPLACE BUCKLE

1 R AND R INNER SEAT BELT BUCKLE ASSEMBLY TO REPLACE

TECH VER CONCERN FOUND DR SIDE BELT BROKEN, REPLACED RETESTED ALL OK

DOES NOT OPERATE PROPERLY REPLACE LEFT BUCKLE TEST LEFT AND RT SEATBELT BUCKLES

S40 42 81203 INSPECT AND REPLACE SEAT BELT BUCKLE

REPLACED RIGHT SEAT BELT BUCKLE

REPLACE BOTH FRONT SEAT BELTS PER RECALL

REPLACED PASS. SEATBELT BUCKLE ASSY.

DOESNT OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE

REPLACE STICKING LEFT FRONT BUCKLE

CHECKED CUSTOMERS CONCERN WITH THE SEAT BELT CONFIRMED CUSTOMERS CONCERN REMOVED AND REPLACED DRIVERS SEAT BELT

SUPPLIED CUSTOMER WITH SEAT BELT LATCH UNDER WARRANTY. CUSTOMER INSTALLED

DOES NOT OPERATE PROPERLY R&I PS SEAT REPLACE SEAT BELT BUCKLE REASSEMBEL RETEST

DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED. CHECK AND REPLACE LEFT SEAT BELT BUCKLE. RECHECK OPERATION OK

VERIFIED CONCERN AND REPLACED BELT

REMOVED THE RIGHT FRONT SEAT FOR ACCESS TO REMO VE AND REPLACE THE SEAZT BELT BUCKLE AND REINST ALLED THE SEAT.

CHECK AND REPLACE SEAT BELT BUCKLES	
REPL SEAT BELT BUCKLE ASSY	
DID VERIFY CUSTOMERS CONCERN ORDER AND INSTALL A NEW RT FRONT SEAT BELT BUCKLE ASSY RECHECK ALL OK NOW HAD TO R AND R RT FRONT SEAT TO REPLACE .	
BOTH BUCKLES NOT HOLDING. TEST BOTH FRONT SEAT BELT BUCKLES. BOTH FAILED TEST. REPLACE BOTH SEAT BUCKLES. RETEST OK.	
REMOVE REPLACE RIGHT FRONT SEATBELT ASSEMBLY	
REPLACE THE SEAT BELT ASSEMBLY VERIFY THE SEAT BELT IS WORKING NOIRMALLY	
VERIFIED CONCERN FOUND SEAT BELT ASSEMBLY AND RETRACTOR INOP R AND R SEAT BELT ASSEMBLY AND RETRACTOR B TIME USE TO ACCESS INTERIOR PANEL TO REPLACE	
SEAT BELT CLASP, INOP.	SEATBELT ASSEMBLY FRONT REPLACE
SEATBELT WONT STAY BUCKLED	SEATBELT ASSEMBLY FRONT REPLACE
REPLACED RT FT SEAT BELT BUCKLE WONT LATCH	
51	SEATBELT ASSEMBLY FRONT REPLACE
CC 42,CCC S40 INSTALLED SEAT BELT BUCKLE DRIVERS SIDE 605	
SEAT BELT BINDING, SOP RO 48864 10 08 01 W 18098 MILES REPLACED D S SEAT BELT BUCKLE. RO 49106 10 17 01 W 19384 MILES	
DOES NOT OPERATE PROPER	SEATBELT ASSEMBLY FRONT REPLACE
CHECK,REPLACE RIGHT SIDE PRETENSIONER AS PER RECALL	
CHECK BELT WITH TOOL DRIVER SIDE FRONT NO GOOD MT TIME IS TO REMOVE ADD ON CONSOLE	
DEFECTIVE	VERIFY CONCERN. INSTALL SPECIAL ORDERED SEAT BELT BUCKLES (BOTH)
REPLACED DRIVER SIDE SEAT BELT	

CK OUT AND R R LEFT FRT SEAT REPLACE SEAT BELT BUCKLE END

SEAT BELT WOULD NOT STAYED BUCKLED REPLACED BUCKLE

10008 W CHECK OUT PASSENGER FRONT SEAT BELT BUCKLE WILL NOT LATCH.REMOVE SEAT AND REPLACE CHARGED SEAT BELT BUCKLE.INSTALL PASSENGER FRONT SEAT AND TEST SEAT BELT BUCKLE,O.K.

CONFIRMED CUSTOMER CONCERN, FOUND SEAT BELT NOT LATCHING NEC TO REMOVE AND REPLACE SEAT BELT BUCKLE OK NOW

INSPECTED BELTS WILL NOT LOCK ALL THE TIME. REP LACED BOTH BELT ASSY

BUCKEL JAMED REPLACED WITH NEW BELT

3453 REPL LFRT SEAT BELT BUCKLE

CHECK,REPLACE BUCKLE ASSY,RECHECK,OK

6503 61203 DRIVERS SEAT BELT BUCKLE INTERMITTENT 42 REPLACED DRIVERS SEAT BELT BUCKLE. FAILS ON CU STOMER.

INSTALLED SEAT BELT RF LATCH

BUCKLE HAS INTERNAL FAILURE S40 42 INSPECT REMOVE REPLACE DRIVER SEATBELT BUCKLE.

REPLACED RT FRONT SEAT BELT

REMOVE AND INSTALL LEFT FRONT SEAT TO REPLACE INNER SEAT BELT BUCKLE ASSEMBLY

CHECK OUT BOTH FRT SEAT BELT BUCKLES NOT STAYING LATCHED, REPLACE BOTH FRT SEAT BELT BUCKLES (NOT OPERATING PROPERLY)

6669 INSTALLED NEW SEATBELT BUCKLE

R I DRIVE SIDE FRONT SEAT (BRACKET) REPLACE SEAT BELT BUCKLE

RREPLACED SEAT BELT

2001 Exped repeat repair_ AREA_ CD	2001 Exped repeat repair_C OUNTRY CD	2001 Exped repeat repair_SL S_DLR_C D	2001 Exped repeat repair_TX N CD	2001 Exped repeat repair_CN TRY_SOL D	2001 Exped repeat repair_Q RT_CD
2001 Exped repeat repair_CUST_TXT					
CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED	515	USA	363589	2	USA Q21
C S THE DRIVERS SEAT BELT WILL NOT STAY LATCHED	770	USA	326233	E84	USA Q21
S25 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE	813	USA	325169	E84	USA Q21
CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.	214	USA	387510	1	USA Q21
CK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN	661	USA	354041	E84	USA Q21
S25 LT FT SEAT BELT WONT STAY LATCHED	713	USA	152031	1	USA Q21
CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE.	650	USA	172013	2	USA Q21
WARRANTY REPAIR DRIVER SIDE SESAT BELTR BUCKLE WILL NOT HOLD	954	USA	124009	E84	USA Q21
CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED	580	USA	152568	E84	USA Q21
S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE..	872	USA	152509	1	USA Q21
DRIVER SIDE SEATBELT DOEN T HOLD	805	USA	171498	1	USA Q21
CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE	412	USA	144017	1	USA Q21
CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART	317	USA	147027	1	USA Q21
RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK	209	USA	172514	1	USA Q21

T80 C 8 DRIVERS SEAT BELT WONT STAY LATCHED SOP	504	USA	123009	1	USA	Q21
S26 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED	601	USA	123309	E84	USA	Q21
CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...	916	USA	152016	2	USA	Q21
CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO	251	USA	124017	E84	USA	Q21
CK DRIVERS SEAT BELT WONT STAY ATTACHED	972	USA	152014	1	USA	Q21
DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	229	USA	121408	1	USA	Q21
S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING	210	USA	152063	E84	USA	Q21
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/139533	818	USA	171040	2	USA	Q21
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/139533	818	USA	171040	2	USA	Q21
S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE	818	USA	171040	1	USA	Q21
CUSTOMER STATES THE DRIVERS SEAT BELT WILL NOT STAY LATCHED	509	USA	174484	E84	USA	Q21
LEFT SEAT BELT WONT HOLD	712	USA	153554	1	USA	Q21
CUSTOMER STATES SEAT BELT NOT OPERATING PROPERLLY	409	USA	152031	E84	USA	Q21
DR SHLDR BELT WONT STAY BUCKLED UP	805	USA	171047	E84	USA	Q21
PASSENGER SEAT BELT WILL NOT HOLD	208	USA	156603	2	USA	Q21
CK SEATBELT AT R F COMES UNLATCHED AT TIMES	601	USA	123359	E84	USA	Q21
SEAT BELT, FRT. WILL NOT STAY LATCHED	602	USA	171171	E84	USA	Q21

REPAIR BOTH FRONT SEAT BELTS WONT STAY BUCKLED	808	USA	141379	2	USA	Q21
SEAT BELTS ARE NOT HOLDING ON BOTH THE DRIVERS SIDE AND THE PASS. SIDE, CORRECT FOR	816	USA	153900	1	USA	Q21
CK PASS SEATBELT WONT STAY CLICKED	843	USA	121291	2	USA	Q21
SEAT BELT NOT HOLDING	281	USA	152024	2	USA	Q21
CUST STATES SEAT BELTS DONT STAY LATCHED.	303	USA	150005	E84	USA	Q21
OTHER RESTRAINT TROUBLES THE SEAT BELTS DO NOT STAY ENGAGED	507	USA	158667	2	USA	Q21
CUSTOMER SAYS DRIVERS SEATBELT WONT STAY LATCHED	*	USA	153080	E84	USA	Q21
PASS SIDE SEAT BELT WONT STAY LATCHED	920	USA	141379	2	USA	Q21
STATES SEAT BELT BUCKLE DOES NOT HOLD SEATBELT IN PASSENGER SIDE	831	USA	113488	1	USA	Q21
PASS SIDE SEAT BELT DOESNT STAY BUCKLED	808	USA	141102	2	USA	Q21
RIGHT FRONT SEAT BELT WONT STAY LATCHED.	814	USA	113635	1	USA	Q21
CUSTOMER STATES THE PASSENGER SEAT BELT WONT STAY LATCHED(RECALL PREVIOUSLY PERFORMED)	303	USA	156001	1	USA	Q21
CHECK PASSENGER FRONT SEAT BELT IT DOESNT HOLD	507	USA	158661	1	USA	Q21
CK/ADV PASS SIDE SEAT BUCKLE WONT STAY LATCHED 40	734	USA	148032	E84	USA	Q21
PASS SIDE SEATBELT WONT STAY LATCHED. (S25) CUST HAD 01821 PERFORMED ELSEWHERE AND WAS TOLD	952	USA	158007	E84	USA	Q21
CK RT SEAT BELT DOESNT STAY LATCH	651	USA	158594	E84	USA	Q21
PASSENGER SEAT BELT DOESNT HOLD	802	USA	111541	E84	USA	Q21
CHECK DRIVERS SEAT BELT	816	USA	153002	2	USA	Q21
CUSTOMER STATES R F SEAT BELT WILL NOT STAY BUCKELED	303	USA	156009	1	USA	Q21
RF SEATBELT ASSY WILL NOT STAY LATCHED	802	USA	171177	E84	USA	Q21
CUSTOMER STATES DRIVERS SEAT BELT DOESNT STAY LATCHED	802	USA	111602	2	USA	Q21

CHECK DRIVER SIDE SEAT BELT WONT STAY LATCH	414	USA	141112	E84	USA	Q21
CUSTOMER STATES FRONT SEAT BELT WILL NOT STAY LATCHED BOTH DRIVER AND PASSENGER CHECK AND ADVISE	303	USA	156008	2	USA	Q21
PASS SEAT BELT WONT STAY LATCH	972	USA	152509	E84	USA	Q21
CUSTOMER STATES PASSENGER SEATBELT PULLS APART. INSTALL SOP	407	USA	147202	E84	USA	Q21
PASS FRONT SEAT BELT WILL NOT STAY LATCHED POPS OPEN WHILE DRIVING	216	USA	127043	2	USA	Q21
C S PASS SIDE SEAT BELT WILL NOT STAY LOCKED	407	USA	124226	2	USA	Q21
BOTH DRIVER AND PASSENGER SIDE SEAT BELTS WILL NOT STAY BUCKLED	828	USA	121661	1	USA	Q21
	972	USA	152012	2	USA	Q21
	941	USA	124543	2	USA	Q21
	609	USA	116020	E84	USA	Q21
	540	USA	127458	2	USA	Q21
	513	USA	147555	1	USA	Q21
	218	USA	158498	1	USA	Q21
	919	USA	121356	1	USA	Q21
	408	USA	172013	E84	USA	Q21
	530	USA	172436	2	USA	Q21
	716	USA	144119	1	USA	Q21
	631	USA	113101	2	USA	Q21
	979	USA	152762	E84	USA	Q21

	661	USA	171153	E84	USA	Q21
	480	USA	171176	2	USA	Q21
	740	USA	144050	2	USA	Q21
	361	USA	152139	E84	USA	Q21
	810	USA	148544	2	USA	Q21
	479	USA	123250	2	USA	Q21
	817	USA	152018	E84	USA	Q21
	903	USA	152449	E84	USA	Q21
	402	USA	158464	2	USA	Q21
	810	USA	148544	E84	USA	Q21
	602	USA	171206	2	USA	Q21
	423	USA	147441	2	USA	Q21
	530	USA	172436	2	USA	Q21
	665	USA	121687	2	USA	Q21
	503	USA	171431	E84	USA	Q21

	360	USA	174494	1	USA	Q21
	319	USA	141200	1	USA	Q21
	816	USA	153118	2	USA	Q21
	847	USA	141057	1	USA	Q21
	570	USA	116302	1	USA	Q21
	302	USA	118213	1	USA	Q21
	952	USA	121718	2	USA	Q21
	708	USA	121450	2	USA	Q21
	863	USA	124476	1	USA	Q21
	906	USA	141816	E84	USA	Q21
	337	USA	123271	2	USA	Q21
	304	USA	147545	1	USA	Q21
	801	USA	156558	1	USA	Q21
	319	USA	141526	E84	USA	Q21
	352	USA	124402	E84	USA	Q21
	515	USA	153546	2	USA	Q21
	419	USA	144305	E84	USA	Q21
	806	USA	147405	2	USA	Q21

	207	USA	111044	2	USA	Q21
	336	USA	121617	E84	USA	Q21
	724	USA	144026	2	USA	Q21
	562	USA	171055	1	USA	Q21
	830	USA	162909	2	USA	Q21
	413	USA	116052	2	USA	Q21
	608	USA	111647	2	USA	Q21
	630	USA	141442	2	USA	Q21
	417	USA	153482	1	USA	Q21
	607	USA	113529	1	USA	Q21
	818	USA	171040	2	USA	Q21
	607	USA	158621	E84	USA	Q21
	210	USA	152718	E84	USA	Q21
	808	USA	172414	1	USA	Q21
	419	USA	148223	1	USA	Q21
	973	USA	113452	2	USA	Q21
	510	USA	172007	2	USA	Q21
	916	USA	172207	2	USA	Q21

K024-011 14438

	419	USA	147128	E84	USA	Q21
	406	USA	148409	2	USA	Q21
	517	USA	148580	2	USA	Q21
	209	USA	172425	1	USA	Q21
	570	USA	118302	1	USA	Q21
	863	USA	124425	E84	USA	Q21
	281	USA	152055	2	USA	Q21
	419	USA	148223	1	USA	Q21
	360	USA	174021	2	USA	Q21
	616	USA	148589	1	USA	Q21
	615	USA	123198	E84	USA	Q21
	765	USA	147420	1	USA	Q21
	616	USA	148584	2	USA	Q21
	409	USA	152082	E84	USA	Q21
	423	USA	121201	E93	USA	Q21
	512	USA	152804	1	USA	Q21
	972	USA	152012	1	USA	Q21

RO04-011 14437

	972	USA	152012	1	USA	Q21
	979	USA	152768	1	USA	Q21
	770	USA	121480	E84	USA	Q21
	541	USA	174469	1	USA	Q21
	978	USA	111300	2	USA	Q21
	661	USA	171040	E84	USA	Q21
	615	USA	121444	E84	USA	Q21
	814	USA	113489	2	USA	Q21
RIGHT FRONT SEATBELT WONT STAY LATCHED	540	USA	127080	2	USA	Q21
RT FRT SEAT BELT WILL NOT STAY LATCHED	608	USA	171227	E84	USA	Q21
RT SIDE SEAT BUCKLE WONT STAY LATCHED	734	USA	148426	2	USA	Q21
CUSTOMER STATES:THAT THE PASS FRONT SEATBELT LATCH IS NOT HOLDING, SOP	434	USA	127551	2	USA	Q21
PASSENGER SIDE SEAT BELT WONT STAY HOOKED	910	USA	124125	E84	USA	Q21
PASSENGER SEATBELT WILL NOT STAY LATCHED SOP	414	USA	127636	E81	USA	Q21
CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT ALWAYS STAY IN HOLDER	716	USA	144120	1	USA	Q21
PASSENGER SEAT BELT WILL NOT STAY LATCHED	574	USA	148204	2	USA	Q21
CUSTOMER STATES RF SEATBELT WILL NOT STAY LATCHED.	704	USA	121660	1	USA	Q21
SEAT BELT WONT STAY LATCHED	734	USA	124325	E84	USA	Q21
CS DRIVER SEATBLET WILL NOT STAY LATCHED	409	USA	124773	E84	USA	Q21
CUST STATES DRIVER SIDE SEAT BELT BUCKLE WONT STAY LATCHED	865	USA	121697	2	USA	Q21

CHECK FOR PASSENGER SEAT BELT BUCKLE NOT STAYING LATCHED	807	CAN	4B8802	1	CAN	Q21
CUSTOMER STATES: DRIVERS SEATBELT DOES NOT LOCK WHEN BUCKLED, MUST PUSH IN 5 6 TIMES TO LOCK BUCKLE.	860	USA	312470	E84	USA	Q21
CHK AND ADVISE CUST STATES FRONT PASSENGER SIDE SEAT BELT BUCKLE RELEASES BELT, IT DOES NOT STAY BUCKLED. 920	582	USA	354081	E84	USA	Q21
S40 CUSTOMER STATES DRIVERS SEATBELT LOOSE	407	USA	325202	1	USA	Q21
PASSENGER SEAT BELT BUCKLE WILL NOT STAY BUCKLED PART IN	231	USA	345330	1	USA	Q21
CUSTOMER REPORTS PASSENGER FRONT SEATBELT WILL NOT HOLD	770	USA	328217	1	USA	Q21
BOTH FRONT SEAT BELT BUCKLES WILL NOT LATCH	918	USA	367057	1	USA	Q21
SEAT BELT WILL NOT STAY BUCKLED	281	USA	367023	1	USA	Q21
SEAT BELT BUCKLE WILL NOT STAY LOCKED	810	USA	345288	2	USA	Q21
REPLACE SEAT BELT BUCKLES WONT HOLD	918	USA	354170	2	USA	Q21
PASS SEATBELT WONT HOLD	301	USA	357716	E84	USA	Q21
SOP RIGHT FRONT SEAT BELT WONT STAY BUCKLE	817	USA	345741	E84	USA	Q21
CUSTOMER STATES THE SEAT BELT BUCKLE WILL NOT STAY FASTENED	270	USA	348677	E84	USA	Q21
FRONT SEAT BELT BUCKLES DO NOT HOLD	937	USA	348096	2	USA	Q21
PASS FRONT SELTBELT BUCKLE WILL NOT STAY LATCHED	252	USA	325740	E84	USA	Q21
DRIVERS SEAT BELT WONT STAY FASTENED	*	USA	325832	E84	USA	Q21
CUSTS AYS FRT SEAT BELTS WONT HOLD	254	USA	367326	2	USA	Q21
DR SEAT BELT WOULD NOT STAY LATCHED.	334	USA	315245	2	USA	Q21

RT FRONT SEAT BELT DOESNT STAY LATCHED ERRATIC BUT OFTEN	313	USA	345350	2	USA	Q21
	304	USA	325727	E84	USA	Q21
S26 AT TIMES DRIVERS SEAT BELT LATCH WILL NOT HOLD.	972	USA	367324	E84	USA	Q21
RIGHT FRONT SEAT BELT BUCKLE LOOSE SOP HERE	352	USA	328506	E84	USA	Q21
DRIVER FRONT SEAT BELT IS LOOSE AT ATTACHING POINT ALSO CHECK FEMALE LATCH TO ENSURE PROPER LATCHING	903	USA	367838	E84	USA	Q21
RT FRT SEAT BELT BUCKLE RELEASE BUTTON STICKS	517	USA	345198	2	USA	Q21
CUSTOMER REPORTS PASSENGER FRONT SEATBELT WILL NOT HOLD	770	USA	326217	1	USA	Q21
L F SEATBELT BUCKLE WILL NOT STAY LATCHED	512	USA	367014	E84	USA	Q21
SEAT BELT WONT HOLD	760	USA	171415	E84	USA	Q21
CUSTOMER STATES SEAT BELTS DO NOT STAY LATCHED	931	USA	123346	1	USA	Q21
CUSTOMER STATE BOTH FRONT SEAT BELT WILL NOT STAY LATCHED RECALL HAS ALREADY BEEN PERFORMED AND PASSED	573	USA	153339	1	USA	Q21
DRIVERS SIDE SEATBELT WILL NOT STAY LATCHED	740	USA	144521	2	USA	Q21
CHECK BOTH FRONT SEAT BELTS WILL NOT STAY LATCHED IN BUCKLES.	610	USA	144004	2	USA	Q21
CK FOR DRIVERS SIDE SEAT BELT,NOT STAYING LATCHED	410	USA	127030	E84	USA	Q21
CUSTOMER REQUEST TO RECHECK BOTH FRT SEAT BELTS AS RELATED TO RECALL; NOT STAYING BUCKLED.	541	USA	174021	2	USA	Q21
SEAT BELTS WILL NOT STAY LATCHED	940	USA	152792	E84	USA	Q21
SEATBELTS WILL NOT STAY BUCKLED	616	USA	174821	2	USA	Q21
BOTH FRONT SEAT BELTS WONT STAY LATCHED	231	USA	148515	E84	USA	Q21

CUSTOMER STATES: DR. SIDE SEAT BELT RECIEVER NOT HOLDING	386	USA	124535	E84	USA	Q21
CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED	219	USA	147113	E84	USA	Q21
DRIVERS SEAT BELT W STAY BUCKLED SOP	410	USA	127039	E84	USA	Q21
R F SEATBELT WILL NOT STAY BUCKLED. S.O.P.	520	USA	171421	E84	USA	Q21
DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED	281	USA	152064	1	USA	Q21
CUST STATES DRIVERS SIDE SEAT BELT WONT STAY LATCHED	562	USA	171088	1	USA	Q21
FRONT SEATBELT BUCKLE WONT HOLD	609	USA	116443	E84	USA	Q21

RO04-D11 14441

2001 Exped repeat repair_VF G CD	2001 Exped repeat repair_A WS_VL_ CD	2001 Exped repeat repair_VRT_CD	2001 Exped repeat repair_TIS_FLAG	Days Between Repair	DBR2	Miles Between Repair	Inspection	Repair
V05	B4	S08		2	0	43	i	
V05	B4	S08		157	180	8405	i	
V05	B4	S08		6	10	98	i	
V05	B4	S08		138	140	11454		r
V05	B4	S08		221	220	13468	i	
V05	B3	S08		14	10	484	i	
V05	B3	S08		28	30	592	i	
V05	B3	S08		0	0	0	i	
V05	B3	S08		16	20	803	i	
V05	B3	S08		15	20	710	i	
V05	B3	S08		1	0	50	i	
V05	B3	S08		57	60	805	i	
V05	B3	S08		17	20	518	i	
V05	B3	S08		168	170	8243		r

RO24-011 1444Z

V74	B3	S08		91	90
V05	B3	S08	②	146	150
V05	B3	S08		86	90
V05	B3	S08		166	170
V74	B3	S08		9	10
V05	B3	S08		5	10
V05	B3	S08		98	100
V05	B3	S08		29	30
V05	B3	S08		141	140
V05	B3	S08		142	140
V05	F5	S08		109	110
V05	F5	S08		63	60
V05	F5	S08		43	40
V05	F5	S08		80	80
V05	F5	S08		111	110
V05	F5	S08		76	80
V05	F5	S08		55	60

5075		r
6352		
2539		r
16798		
603		
216		
4569		
1232		
1434		r
5612		
14009		
1228		
1453		
8870		
2069		
3679		
4057		

V05	F5	S08		148	150
V05	F5	S08		45	50
V05	F5	S08	@	308	310
V05	F5	S08		40	40
V05	R1	S08		188	170
V05	R1	S08		83	80
V05	R1	S08	@	222	220
V05	R1	S08		124	120
V05	R1	S08		84	80
V05	R1	S08		87	70
V05	R1	S08		123	120
V03	R1	S08		119	120
V05	R1	S08		53	50
V05	R1	S08		59	60
V05	R1	S08		63	80
V05	R1	S08		176	180
V05	R1	S08		138	140
V05	R1	S08		51	50
V05	R1	S08		184	180
V05	R1	S08		220	220
V05	R1	S08		250	250

8026		
1361		
5101		
584		
10701		
1554		
3115		
3104		
1175		
3729		
5230		
2539		
2956		
1669		
8281		
11506		
14832		
1777		
3982		
8058		
7743		

K004-011 1444

V05	R1	S08		257	280
V06	R1	S08		118	120
V05	R1	S08		69	70
V05	R1	S08		105	110
V05	R1	S08		91	90
V05	R1	S08		212	210
V05	R1	S08		34	30
V05	F7	S08		306	310
V05	F7	S08		302	300
V05	F7	S08	@	287	290
V05	F7	S08		281	280
V05	F7	S08		252	250
V05	F7	S08		243	240
V05	F7	S08		232	230
V05	F7	S08		202	200
V05	F7	S08		200	200
V06	F7	S08		196	200
V05	F7	S08		195	200
V05	F7	S08		190	180

11605		
2882		
3072		
5965		
2800		
8784		
135		
11016		
6391		
23549		
3913		
2682		
5015		
6397		
6946		
8207		
5228		
7839		
11463		

NOB-011 1445

V05	F7	S08		184	180	12104		
V06	F7	S08		183	180	6348		
V05	F7	S08		181	180	1083		
V05	F7	S08	@	178	180	10398		
V05	F7	S08		182	160	7391		
V05	F7	S08		181	160	5205		
V05	F7	S08		159	160	9181		
V05	F7	S08		157	160	12493		
V05	F7	S08		153	150	6593		
V05	F7	S08		152	150	10958		
V05	F7	S08		148	150	1335		
V05	F7	S08		145	150	4480		
V06	F7	S08		140	140	5001		
V06	F7	S08		139	140	11453		
V06	F7	S08		138	140	13652		

K084-011 1448

V06	F7	S08		133	130	9559		
V06	F7	S08		129	130	3180		
V05	F7	S08		129	130	3110		
V05	F7	S08		126	130	300		
V05	F7	S08		126	130	5984		
V05	F7	S08		124	120	2447		
V05	F7	S08		121	120	3284		
V05	F7	S08		119	120	9214		
V05	F7	S08		118	120	2794		
V05	F7	S08		113	110	8665		
V03	F7	S08		112	110	5890		
V05	F7	S08		111	110	3806		
V05	F7	S08		107	110	4806		
V05	F7	S08		102	100	5412		
V05	F7	S08		101	100	6128		
V05	F7	S08		100	100	523		
V05	F7	S08		100	100	7127		
V05	F7	S08		100	100	1748		

V05	F7	S08		98	100
V05	F7	S08	6	98	100
V05	F7	S08		96	100
V05	F7	S08		95	100
V05	F7	S08		93	90
V05	F7	S08		92	90
V05	F7	S08		89	90
V05	F7	S08		86	90
V05	F7	S08		84	80
V05	F7	S08		84	80
V05	F7	S08		79	80
V05	F7	S08		71	70
V05	F7	S08		69	70
V05	F7	S08		66	70
V05	F7	S08		58	60
V05	F7	S08		57	60
V05	F7	S08		53	50
V05	F7	S08		52	50

4422		
4223		
3869		
2876		
4802		
4043		
5581		
1824		
4160		
2261		
1839		
5264		
6389		
201		
1200		
4000		
5340		
1270		

V05	F7	S08		51	50
V05	F7	S08		60	50
V05	F7	S08		46	50
V05	F7	S08		44	40
V05	F7	S08		43	40
V05	F7	S08		42	40
V05	F7	S08		42	40
V05	F7	S08		37	40
V05	F7	S08		34	30
V05	F7	S08		30	30
V05	F7	S08		29	30
V05	F7	S08		28	30
V05	F7	S08		16	20
V05	F7	S08		13	10
V05	F7	S08		12	10
V05	F7	S08		10	10
V05	F7	S08		7	10

3485		
4209		
3782		
3421		
550		
3611		
1753		
1296		
1092		
1204		
1423		
4434		
1097		
828		
834		
451		
1221		

V05	F7	S08		7	10
V05	F7	S08		4	0
V05	F7	S08		2	0
V05	F7	S08		0	0
V05	F7	S08		0	0
V05	F7	S08		0	0
V05	F7	S08		0	0
V05	F7	S08		0	0
V05	F7	S08		0	0
V05	A3	S08		194	190
V05	A3	S08	@	51	50
V05	A3	S08		62	60
V44	A3	S11		112	110
V03	A3	S08		124	120
V05	A3	S08		155	160
V05	A3	S08		175	180
V05	A3	S08		177	180
V05	A3	S08		227	230
V05	A3	S08	@	290	290
V05	A3	S08		14	10
V05	A3	S08		236	240

145		
239		
128		
0		
0		
0		
0		
0		
0		
11233		
1189		
2210		
7189		
1000		
14320		
3927		
9150		
5608		
21067		
1224		
11269		

5084-011 14459

V05	A3	S08		42	40
V05	VB	S08		82	80
V05	VB	S08		188	190
V05	VB	S08		0	0
V05	VB	S08		10	10
V05	VB	S08		69	70
V05	VB	S08		147	150
V05	VB	S08		1	0
V05	VB	S08		22	20
V05	VB	S08		14	10
V05	VB	S08		16	20
V05	VB	S08		230	230
V05	VB	S08		67	70
V05	VB	S08		40	40
V05	VB	S08		263	260
V05	VB	S08		84	80
V05	VB	S08		90	90
V05	VB	S08		88	90

			1794		
			4265		
			15193		
			0		
			98		
			348		
			2948		
			7		
			791		
			964		
			1255		
			1405		
			2235		
			3122		
			3203		
			3730		
			4000		
			5850		

V05	VB	S08		217	220
V05	VB	S08		221	220
V05	VB	S08		200	200
V05	VB	S08		289	290
V05	VB	S08		235	240
V05	VB	S08		0	0
V05	VB	S08		90	90
V05	VB	S08		129	130
V05	FB	S08		23	20
V06	FB	S08		28	30
V05	FB	S08		70	70
V05	FB	S08		109	110
V05	FB	S08		37	40
V05	FB	S08		191	190
V05	FB	S08		101	100
V05	FB	S08		157	160
V05	FB	S08		123	120
V05	FB	S08		84	80

6108		
7810		
9459		
11778		
12906		
0		
1025		
4415		
286		
287		
3420		
3540		
3840		
6171		
7420		
18762		
2540		
12462		

V05	L1	S08		110	110
V05	L1	S08		195	200
V05	L1	S08		45	50
V05	L1	S08		153	150
V05	L1	S08		12	10
V05	L1	S08		68	70
V05	L1	S08		228	230

24741		
20978		
9939		
18455		
10353		
5		
7944		

82	2001	22	*	*	*	2/28/2002	7
258	2001	258	*	*	*	10/18/2001	7
278	2001	278	*	*	*	3/21/2002	14
114	2001	74	*	*	*	10/2/2001	8
343	2001	343	*	*	*	1/30/2002	17
198	2001	198	*	*	*	3/28/2002	10
129	2001	89	*	*	*	1/30/2002	8
281	2001	281	*	*	*	11/1/2001	13
98	2001	88	*	*	*	8/17/2001	4
323	2001	323	*	*	*	10/5/2001	4
296	2001	285	*	*	*	11/8/2001	12
210	2001	170	*	*	*	11/28/2001	10
378	2001	378	*	*	*	8/7/2001	1
227	2001	227	*	*	*	5/27/2001	8
148	2001	108	*	*	*	9/20/2001	6
368	2001	368	*	*	*	4/15/2002	18
385	2001	385	*	*	*	3/18/2002	14
142	2001	102	*	*	*	10/15/2001	10
208	2001	188	*	*	*	11/9/2001	8
14	2001	135	*	*	*	8/31/2001	3
208	2001	188	*	*	*	7/18/2001	2
180	2001	110	*	*	*	9/3/2001	8

317	2001	317	*	*	*	8/28/2001	7
180	2001	180	*	*	*	8/13/2001	2
347	2001	247	*	*	*	6/21/2001	8
218	2001	178	*	*	*	8/17/2001	3
68	2001	28	*	*	*	9/11/2001	8
368	2001	368	*	*	*	7/10/2001	0
84	2001	44	*	*	*	10/4/2001	8
50	2001	40	*	*	*	12/8/2001	11
41	2001	1	*	*	*	7/27/2001	4
271	2001	271	*	*	*	11/14/2001	4
188	2001	148	*	*	*	6/7/2001	4
276	2001	276	*	*	*	9/12/2001	8
212	2001	172	*	*	*	10/1/2001	8
188	2001	148	*	*	*	1/7/2002	4
78	2001	38	*	*	*	6/12/2001	1
287	2001	187	*	*	*	7/25/2001	8
46	2001	8	*	*	*	8/6/2001	10
88	2001	58	*	*	*	8/16/2001	11
275	2001	275	*	*	*	8/8/2001	5
110	2001	70	*	*	*	7/11/2001	2
138	2001	88	*	*	*	8/10/2001	13

RD04-011 14955

220	2001	180	*	*	*	10/22/2001	8
47	2001	7	*	*	*	3/9/2001	8
8	2001	180	*	*	*	10/4/2001	7
282	2001	282	*	*	*	7/30/2001	11
218	2001	178	*	*	*	8/11/2001	2
147	2001	107	*	*	*	8/1/2001	3
204	2001	184	*	*	*	8/2/2001	2
28	2001	207	*	*	*	8/21/2001	8
187	2001	147	*	*	*	7/25/2001	0
28	2001	208	*	*	*	7/23/2001	7
287	2001	287	*	*	*	2/9/2001	4
285	2001	288	*	*	*	8/7/2001	8
252	2001	252	*	*	*	8/8/2001	7
241	2001	241	*	*	*	7/28/2001	8
111	2001	71	*	*	*	8/5/2001	6
316	2001	318	*	*	*	5/21/2001	8
254	2001	254	*	*	*	6/18/2001	2
18	2001	188	*	*	*	7/17/2001	0
83	2001	43	*	*	*	11/1/2001	7
313	2001	313	*	*	*	8/13/2001	7
287	2001	287	*	*	*	11/21/2001	2
353	2001	353	*	*	*	10/2/2001	2
21	2001	202	*	*	*	10/12/2001	0
88	2001	48	*	*	*	7/25/2001	0
168	2001	118	*	*	*	11/12/2001	7
288	2001	288	*	*	*	2/1/2002	8
85	2001	48	*	*	*	8/21/2001	4


35	2001	218	*	*	*	10/3/2001	7
108	2001	168	*	*	*	8/15/2001	11
193	2001	153	*	*	*	6/11/2001	5
127	2001	87	*	*	*	10/10/2001	1
243	2001	243	*	*	*	5/23/2001	10
22	2001	205	*	*	*	7/31/2001	6
100	2001	80	*	*	*	7/20/2001	0
194	2001	154	*	*	*	8/20/2001	7
89	2001	220	*	*	*	7/20/2001	0
357	2001	357	*	*	*	10/15/2001	2
87	2001	27	*	*	*	7/31/2001	5
354	2001	354	*	*	*	8/6/2001	7
356	2001	359	*	*	*	8/9/2001	3
17	2001	195	*	*	*	7/31/2001	4
198	2001	156	*	*	*	8/21/2001	9
188	2001	126	*	*	*	5/5/2001	8
209	2001	189	*	*	*	12/9/2001	8
133	2001	113	*	*	*	5/25/2001	3
211	2001	171	*	*	*	11/8/2001	11
312	2001	312	*	*	*	10/9/2001	5

ROSA-B11 14457

385	2001	385	*	*	*	12/5/2001	5
152	2001	112	*	*	*	11/28/2001	8
115	2001	75	*	*	*	12/4/2001	8
53	2001	13	*	*	*	8/2/2001	4
381	2001	381	*	*	*	9/4/2001	1
176	2001	188	*	*	*	12/18/2001	10
379	2001	379	*	*	*	8/4/2001	8
18	2001	187	*	*	*	7/29/2001	3
75	2001	35	*	*	*	9/21/2001	6
345	2001	343	*	*	*	8/24/2001	8
202	2001	182	*	*	*	5/20/2001	4
208	2001	183	*	*	*	7/27/2001	0
238	2001	228	*	*	*	7/27/2001	8
128	2001	85	*	*	*	8/4/2001	1
68	2001	19	*	*	*	12/7/2001	3
277	2001	277	*	*	*	10/25/2001	9
53	2001	13	*	*	*	6/8/2001	4
52	2001	12	*	*	*	10/2/2001	7
332	2001	332	*	*	*	9/27/2001	4
45	2001	5	*	*	*	9/15/2001	11


37	2001	218	*	*	*	7/18/2001	0
132	2001	92	*	*	*	6/31/2001	11
328	2001	328	*	*	*	7/17/2001	0
139	2001	99	*	*	*	7/31/2001	4
534	2001	334	*	*	*	6/27/2001	4
578	2001	578	*	*	*	7/17/2001	0
168	2001	118	*	*	*	9/5/2001	0
7	2001	188	*	*	*	8/24/2001	8
88	2001	49	*	*	*	9/11/2001	6
380	2001	350	*	*	*	11/8/2001	6
263	2001	253	*	*	*	9/20/2001	6
145	2001	108	*	*	*	6/14/2001	4
144	2001	104	*	*	*	8/20/2001	3
55	2001	18	*	*	*	5/1/2001	2
217	2001	177	*	*	*	7/20/2001	0

7181007 4780
4756873 5859
7685711 22580
4122147 787
8919498 20973
7613579 7612
8586307 2084
4838877 13864
3729874 4010
4221791 4061
9018224 8272
8348890 18290
2808100 33
3299278 16432
2899840 10277
8015218 18298
7485728 24138
4429412 19885
5148783 19029
3583688 788
3362037 443
8415728 9355



11494 * NA
11831 * NA
478 * NA
10125 * NA
12089 * NA
11480 * NA
10436 * NA
13428 * NA
13577 * NA
10286 * NA
10951 * NA
10088 * NA
2286 * NA
10042 * NA
6082 * NA
8718 * NA
1483 * NA
10084 * NA
45440 * NA
10823 * NA
11633 * NA
48284 * NA

5299298 8018
9682018 4780
3783078 22078
3113184 1941
9085130 2388
2484430 88
4187707 9040
8714878 15112
2708992 8907
8883530 4320
2870880 3004
3888837 8804
4088827 8214
8270811 3482
2283108 1808
2548840 13
3008814 18288
3231122 8841
2828408 8828
2848178 1232
8213818 28888



10023 * NA
10123 * NA
4870 * NA
1888 * NA
8227 * NA
10088 * NA
11803 * NA
404 * NA
12729 * NA
18128 * NA
4384 * NA
12147 * NA
11808 * NA
11414 * NA
8807 * NA
10888 * NA
10288 * NA
11812 * NA
11808 * NA
11858 * NA
1827 * NA


4800270 10179
3871600 9909
4157197 9087
3166398 17888
5796389 3507
2917330 8904
2977282 9142
3885008 12135
2941448 11
2968869 11922
3977437 12189
2977770 9101
3783441 13728
2987389 13
3474231 8684
3473423 8747
3188511 8788
2763156 5
4816532 10800
3243828 13252
8314907 2028
4430184 900
4398110 5
2843296 4
5115808 10091
6801884 8529
9131497 4979



19570 * NA
10451 * NA
10839 * NA
42235 * NA
42280 * NA
42272 * NA
11630 * NA
8778 * NA
11406 * NA
10236 * NA
45451 * NA
12361 * NA
42286 * NA
7897 * NA
45262 * NA
45188 * NA
12844 * NA
10890 * NA
2283 * NA
1736 * NA
10008 * NA
10432 * NA
13961 * NA
10184 * NA
12901 * NA
12712 * NA
10868 * NA

ROD-011 14482


4188207 19870
4090261 18931
3186980 18410
4328954 811
3578134 12242
6173818 10426
2848787 114
3183821 12810
3722068 10
4783278 885
2827586 9083
3786041 21028
3828378 8667
2788906 5428
3186000 14642
3474172 12886
8589322 4418
4085811 7775
5608258 18956
4887122 17818



1401 * NA
14487 * NA
11808 * NA
10710 * NA
744 * NA
48288 * NA
13482 * NA
10803 * NA
10414 * NA
10183 * NA
13108 * NA
48143 * NA
46307 * NA
11442 * NA
11885 * NA
83275 * NA
10473 * NA
11232 * NA
48748 * NA
12058 * NA

FORM-911 14483


0530000 2021
0412162 2034
0020165 2044
2732871 1325
3068100 100
0072362 10178
0020001 17001
4297435 0224
4150020 0140
3267914 10200
3111550 7970
2500400 4
3530332 11877
3428102 1107
6705753 072
4005410 22046
2733971 1320
4005557 4222
4150027 1317
3034402 0004



13425 * NA
11270 * NA
11833 * NA
13411 * NA
13411 * NA
0030 * NA
12700 * NA
40421 * NA
13025 * NA
12047 * NA
1172 * NA
10021 * NA
40094 * NA
3030 * NA
10104 * NA
45500 * NA
13411 * NA
11000 * NA
10712 * NA
10037 * NA

2486530

10



11442

*

NA

3864808

14874

13482

*

NA

2487888

10

12847

*

NA

2704348

8987

10114

*

NA

3429435

9118

4448

*

NA

2428137

10

12858

*

NA

4488289

183

11808

*

NA

8371390

17837

10332

*

NA

4881823

3852

10858

*

NA

5142175

14180

18348

*

NA

3864381

13045

12388

*

NA

3088243

3715

10013

*

NA

3231968

1824

11650

*

NA

3184388

3371

10281

*

NA

2731381

22

10008

*

NA

TX	.	4788 RECALL INSPECT SEATBELT END HOLD PROPERLY TK372
CA	.	1 INSPECTION ONLY NO REPAIRS NEEDED
AL	.	RECALL PERFORMED
NC	.	PERFORMED RECALL
LA	.	20973 WARN PERFORMED RECALL 01821 SEATBELTS PASSED WITH EXCEPTION ON DR SIDE WHICH HAD ANOTHER CONCERN
TX	.	INSPECTED BOTH FRONT SEAT BELT BUCKLES OK. NO REPAIR NECESSARY AS PER RECALL 01821.
PA	.	1 INSPECT SEAT BELT BUCKLE AND IF NECESSARY, REPLACE BUCKLE INSPECTION ONLY
NY	.	PERFORMED RECALL 01821 INSPECTED OK
TX	.	RECALL COMPLETE
NY	.	OPEN CAMPAIGN INSPECT AS PER CAMPAIGN
MI	.	1 INSPECT PER RECALL OK
IL	.	1 INSPECTED AND ORDERED SEAT BELT BUCKLES
OH	.	INSPECTED SEATBELTS OK
ND	.	INSPECTED SEAT BELTS FOUND BOTH TO BE SECURE
MN	.	NEEDS FRONT BUCKLE ASSY
KY	.	RECALL COMPLETE
LA	.	INSPECT ONLY
GA	.	PERFORM RECALL 01821
MA	.	
MI	.	01821A 01821A
GA	.	RECALL 01821 RECALL PERFORMED
WI	.	PERFORMED THE RECALL AS OUTLINED REPAIR DONE BY HERTZ ON 8 8 01

MD	*	01821 RECALL
AL	*	INSPECTED SEAT BELTS, OK AT THIS TIME, RECALL NOT NEEDED
FL	*	INSPECT SEAT BELT BUCKLES ALL OK
MB	*	INSPECTED AS PER RECALL 01821 NO PROBLEM FOUND AT THIS TIME.
AR	*	01821 CHECK SEAT BELTS ALL OK
TX	*	RECALL 01821 CHECKED SEAT BELT BUCKLES, OK.
FL	*	1 INSPECTED SEAT BELT BUCKLES PER RECALL 01821 NO BUCKLE REPLACEMENT NEEDED VEHICLE IS OK.
GA	*	SEAT BELT
IN	*	RECALL DONE PER RECALL
NH	*	PERF RECALL 01821
NY	*	RECALL PERFORMED
WI	*	COMPLETED RECALL 01821A
KY	*	ALL SEATBELTS PASSED REQUIRED INSPECTION
TX	*	01821 INSPECT SEAT BELT BUCKLES PER RECALL
ME	*	1806 DID RECALL OK **LTS
GA	*	PERFORMED RECALL
AR	*	RECALL 01821 01821A .3 INSPECTED AND TESTED SEATBELTS AS PER RECALL 01821 W C 01821A .3 ADMIN .1 RECALL
FL	*	INSPECT SEATBELT BUCKLES PER 01821 RECALL
FL	*	6826 INSPECTED PER RECALL PASSED
AZ	*	INSPECT SEATBELTS PER RECALL OK.
IL	*	01821 RECALL

TX	.	VERIFY RECALL. CHECK BOTH FRONT SEAT BELT BUCKLES. BOTH BUCKLES PASS TEST. NO REPAIRS REQUIRED.
PA	.	01821 COMPLETED
M	.	RECALL 01821 INSPECT.
GA	.	PERFORMED THE RECALL AS OUTLINED
IL	.	PERFORMED THE RECALL AS OUTLINED
OH	.	PERFORMED SAFETY RECALL
FL	.	RECALL 01821 COMPLETED
VA	.	PERFORM RECALL INSPECT ONLY
TX	.	INSPECT SEATBELT BUCKLE BUILD DATE CODE PER RECALL 01821
AL	.	INSPECTED BUCKLE NO REPLACEMENT
CO	.	
NC	.	INSPECT SEAT BELT NO ACTION TAKEN
NV	.	COMPLETED FORD RECALL
GA	.	78: PERFORMED 01821 RECALL, INSPECTED SEATBELTS OK
TX	.	PERFORMED THE RECALL AS OUTLINED
CA	.	
MO	.	RECALL 01821 RECALL 01821
PA	.	CHECK SEATBELT BUCKLE OK 018214
OH	.	PERFORMED SEAT BELT RECALL
IL	.	DIAG AND CHECKED FOR RECALL INSPECTION NO SEAT BELT NEEDED
VA	.	RECALL INSPECT SEAT BELT AS PER RECALL 01821A
NJ	.	RECALL 01821 NO FURTHER ACTION REQUIRED
MI	.	PERFORMED RECALL
TX	.	01821 RECALL INSPECTION ONLY
MI	.	PERFORMED RECALL 01821 INSPECT
CA	.	
GA	.	PERFORMED RECALL 01821 INSPECTION ONLY PER RECALL 01821.

MD	*	PERFORMED RECALL 01821
TX	*	1 VEHICLE NOT AFFECTED
KY	*	RECALL 01821 RECALL 01821 COMPLETED
OH	*	011 TEST SEAT BELTS, THEY ARE OK WARR
NY	*	CK BUCKLES AS PER RECALL ALL OK
FL	*	PERFORMED SAFETY RECALL
TX	*	1 PERFORMED RECALL
TX	*	SEATBELT BUCKLES OKAY
PA	*	
MI	*	01821 01821
CT	*	1 TEST SEAT BELT BUCKLE PASSED TEST
VA	*	
MI	*	
TX	*	INSPECT OK
FL	*	RECALL 01821 PERFORMED RECALL 01821
TN	*	PERFORMED THE RECALL AS OUTLINED
CA	*	RECALL COMPLETED RECALL NO PARTS NEEDED.QC#31844.
NJ	*	1 COMPLETED SEAT BELT RECALL INSPECTION ONLY NO REPAIRS NEEDED
AZ	*	
LA	*	17810 RECALL RECALL INSPECTED AS PER RECALL DID NOT APPLY

NY	*	PERFORMED RECALL 01821
NY	*	PERFORMED INSPECTION OF SEAT BELTS NO PROBLEM FOUND AT THIS TIME
GA	*	RECALL 01821 01821 RECALL INSPECTION PERFORMED
NJ	*	1 RECALL COMPLETE,INSPECTED SEAT BELT BUCKLES FOUND NO NEED FOR REPLACEMENT.
NJ	*	1 PERFORM RECALL ALL BELTS OKAY
CA	*	18178 RECALL 01821A 0.3 7282 TEST SEAT BELT BUCKLES PASS PER RECALL
NV	*	RECALL DONE PER RECALL
CA	*	PERFORMED THE RECALL
IN	*	1 PERFORMED RECALL 01821 SEAT BELT
MO	*	RECALL INSPECT SEAT BELT RETENTION
FL	*	RECALL 01821 PERFORM INSPECTION
FL	*	R SEAT BELT BUCKLE INSPECTION
CA	*	COMPLETED FORD RECALL
OK	*	INSPECTED SEAT BELT BUCKLES. NO PROBLEM FOUND AT THIS TIME.
TX	*	.
NY	*	
NJ	*	1 RECALL COMPLETE,INSPECTED SEAT BELT BUCKLES FOUND NO NEED FOR REPLACEMENT.
AZ	*	RECALL PERFORMED
MI	*	1817 PERFORM SEATBELT INSPECTION OK AT TIME OF INSPECTION
MI	*	RECALL 01821 COMPLETED RECALL

TX	*	10 INSPECT,OK
TX	*	1 PERFORMED RECALL
MO	*	RECALL INSPECT SEAT BELT RETENTION
SC	*	SEATBELT INSPECTION CHECK SEAT BELT OPERATION PER 01821 CHECKS OK AT THIS TIME
TX	*	RECALL. PERFORM RECALL 01521 AS PER BULLETIN AND REPLACED LEFT SIDE SEATBELT 01821C .#
MO	*	Q RC 01821 INSPECT BELT BUCKLES. REPLACE RH FRONT SEAT BELT BUCKLE
FL	*	190 R01821 01821M 1.8 REPLACED L F SEAT BELT BUCKLE AS IT WAS BAD.
MD	*	17887 PERFORM 01821 RECALL & REPLACE PASSENGER SIDE SEATBELT BUCKLE VEHICLE HAS SIDE AIR BAGS
GA	*	REPLACED DRIVERS BELT ANCHOR PER RECALL 01821 INSPECTION DONE ON R01768 REPLACED THE ANCHOR THIS VISIT
CA	*	PERFORMED RECALL TEST AND REPLACE LF SIDE SEAT BELT BUCKLE
MD	*	REPLACE RIGHT FRONT SEAT BELT
VA	*	8715 REPLACE RT FRNT SEAT BELT BUCKLE
AZ	*	RECALL 01821C REPLACED R 6 SEAT BUCKLE PER RECALL
TX	*	PERFORM RECALL 01821
LA	*	INSPECT AND REPLACED ONE SEAT BELT BUCKLE

R084-011 14471

RECALL 01521 SEAT BELT BUCKLES	817	USA	367013	01521	USA
PERFORM RECALL AS PER FACTORY SPEC'S 01521 SEAT BELT	714	USA	35488J	01521	USA
01521 RECALL	208	USA	346741	01521	USA
RECALL 01521 SEAT BELT BUCKLE RETENTION	704	USA	325120	01521	USA
CK FOR RECALL	604	USA	322841	01521	USA
01521 SEAT BELT BUCKLE RECALL	210	USA	327400	01521	USA
		USA	318148	01521	USA
CUST STATES 01521	815	USA	314017	01521	USA
01521 SEAT BELT BUCKLE	840	USA	367111	01521	USA
RECALL 01 & 21 CK SEAT BELTS	719	USA	318030	01521	USA
01521 SEAT BELT BUCKLE RETENTION	313	USA	345281	01521	USA
RECALL 01521 SEAT BELTS	708	USA	342575	01521	USA
01521 SEATBELTS	419	USA	312712	01521	USA
PERFORM RECALL 01521	410	USA	328044	01521	USA
INSPECT SEAT BELT BUCKLES AS PER RECALL	218	USA	342838	01521	USA
RECALL 01521	568	USA	345741	01521	USA
SEAT BELT RECALL 01521	318	USA	325707	01521	USA
RECALL 01521	708	USA	325707	01521	USA
		USA	325727	01521	USA
01521 SEAT BELT BUCKLE	313	USA	348175	01521	USA
RECALL 01521 OPEN	612	USA	358216	01521	USA
RECALL 01521 DUE		USA	342835	01521	USA

ROSA-011 14472

CJBT HAS RECALL NOTICE	410	USA	328051	01821	USA
PERFORM RECALL 01821	206	USA	328330	01821	USA
INSPECT FOR RECALL ON SEAT BELTS	881	USA	326707	01821	USA
SEAT BELT RECALL 01821	801	USA	322882	01821	USA
01821 RECALL	479	USA	323421	01821	USA
01821 RECALL SEAT BELT BUCKLE	281	USA	387032	01821	USA
CERTAIN 2001 CROWN VICTORIA, EXCURSION, EXPEDITION, F1 50, F300 T THROUGH F350, GRAND MARQUIS, NAVIGATOR, RANGER, TOWN CAR AND	813	USA	325007	01821	USA
RECALL 01821 SEAT BELT	770	USA	328835	01821	USA
OPEN RECALL #01821 SEAT BELT BUCKLE	702	USA	357011	01821	USA
PERF RECALL 01821	803	USA	312235	01821	USA
RECALL 01821	846	USA	314325	01821	USA
OPEN RECALL		USA	342686	01821	USA
RECALL 01821	858	USA	348618	01821	USA
RECALL 01821 SEAT BELT	817	USA	387111	01821	USA
(A Q) 01821 SEAT BELT BUCKLE RETENTION INSPECTION AND POSSIBLE REPLACEMENT ON CERTAIN 2001 MODELS	807	USA	318013	01821	USA
INSPECTED SEATBELTS NO REPLACEMENT NEEDED	876	USA	326385	01821	USA
01821 RECALL	801	USA	322883	01821	USA
ADD ON RECALL 01821 SEAT BELT	407	USA	328032	01821	USA
WPG40, RECALL 01821 SEAT BELT INSPECTION .1.	407	USA	325188	01821	USA
RECALL 00821	802	USA	354587	01821	USA
RECALL 01821	708	USA	342679	01821	USA

RECALL 01821 SEAT BELT BUCKLE	903	USA	367311	01821	USA
OPEN RECALL 01821 SEAT BELT BUCKLE	717	USA	315107	01821	USA
PERFORM RECALL 01821	818	USA	345180	01821	USA
PERFORM RECALL 01821		USA	345741	01821	USA
RECALL 01821 DUE		USA	345741	01821	USA
SAFETY RECALL 01821		USA	345741	01821	USA
01821 SEAT BELT BUCKLE	904	USA	325082	01821	USA
01821 SEAT BELT BUCKLE	540	USA	39481L	01821	USA
01821 SEATBELT BUCKLE	719	USA	397180	01821	USA
RECALL 01821	334	USA	329033	01821	USA
RECALL 01821		USA	325707	01821	USA
SEATBELT BUCKLE INSPECT REPLACE	919	USA	329884	01821	USA
PERFORM RECALL 01821		USA	354748	01821	USA
PERFORM 01821 RECALL, SEATBELT RETENTION	859	USA	354748	01821	USA
RECALL 01821 DUE		USA	397748	01821	USA
		USA	354708	01821	USA
RECALL 01821	314	USA	369529	01821	USA
RECALL 01821 SEAT BELT BUCKLE	810	USA	316130	01821	USA
RECALL 01821 SEAT BELT RECALL	418	USA	316477	01821	USA
RECALL 01821	317	USA	342574	01821	USA
	703	USA	328068	01821	USA
RECALL 01821 SEAT BELT BUCKLE	898	USA	314031	01821	USA
RECALL 01821	817	USA	346186	01821	USA
01821 SEAT BELT BUCKLE	591	USA	397029	01821	USA
ADD RECALL 01821	810	USA	348258	01821	USA
	916	USA	354179	01821	USA
RECALL 01821 SEAT BELT BUCKLE	770	USA	328217	01821	USA

RECALL 01821	301	USA	387716	01821	USA
PERFORM RECALL 01821 SEAT BELT	317	USA	345741	01821	USA
CUSTOMER STATES THAT RECALL 01821 NOT COMPLETED	270	USA	348877	01821	USA
01821 SEAT BELT INSPECTION OR REPLACEMENT	614	USA	348086	01821	USA
01821 SEATBELT BUCKLES	718	USA	325740	01821	USA
RECALL 01821 DUE		USA	325832	01821	USA
SEATBELT RECALL 01821	254	USA	387326	01821	USA
01821 RECALL	254	USA	387014	01821	USA
	610	USA	315245	01821	USA
RECALL 01821 SEAT BELT BUCKLES	313	USA	345880	01821	USA
CUSTOMER REQUEST: RECALL 01821 SEATBELT BUCKLE	350	USA	312470	01821	USA
		USA	325727	01821	USA
		USA	325727	01821	USA
SEAT BELT BUCKLE	972	USA	387334	01821	USA
RECALL 01821 SEAT BELT	352	USA	328508	01821	USA
RECALL 01821 DUE		USA	387336	01821	USA
01821 SEAT BELT BUCKLE RECALL GUEST STATES THIS HAPPENS ALOT. BUCKLES COME UNLATCHED	616	USA	384600	01821	USA
OWNER STATES PERFORM SEATBELT RECALL	306	USA	314474	01821	USA
		USA	354744	01821	USA
RECALL (01821) SEAT BELT BUCKLE	504	USA	322800	01821	USA

CUSTOMER REQUESTS PERFORM RECALL 01821	818	USA	314017	01821	USA
	818	USA	314381	01821	USA
CUSTOMER REQUESTS PERFORM RECALL 01821	812	USA	328218	01821	USA
CUSTOMER REQUESTS PERFORM RECALL 01821, SEAT BELT BUCKLE.	201	USA	314340	01821	USA
RECALL REQUEST 01821 SEAT BELT INSPECTION	201	USA	314422	01821	USA
RECALL SEATBELT 01821	809	USA	354708	01821	USA
01821	702	USA	312710	01821	USA
RECALL 01821 DUE		USA	354748	01821	USA
SEAT BELT RECALL 01821	219	USA	342291	01821	USA
SEAT BELT BUCKLE RETENTION	314	USA	328707	01821	USA
RECALL 01821 SEAT BELT BUCKLE	407	USA	329087	01821	USA
01821 SEAT BELT BUCKLE	407	USA	328189	01821	USA
RECALL 01821 DUE		USA	354748	01821	USA
OTHER RESTRAINT TROUBLE DRIVER SEAT BELT BUCKLE COMES LOOSE.	860	USA	367128	01821	USA
01821 SEAT BELT BUCKLE	281	USA	367081	01821	USA
		USA	354744	01821	USA
CUSTOMER REQUESTS PERFORM RECALL 01821, SEAT BELT BUCKLE.	201	USA	314340	01821	USA
RECALL 01821 SEAT BELT BUCKLE	480	USA	364042	01821	USA
01821 INSPECT VEHICLE (CROWN VICTORIA, EXCURSION EXPEDITION, F 150, F 250, GRAND MARQUIS, NAVIGATOR, TOWN CAR, AND WINDSTAR SEATBELT BUCKLE RETENTION	313	USA	348070	01821	USA
PERFORM RECALL 001821 SEAT BELT BUCKLE	734	USA	364042	01821	USA