



RECEIVED
178-215
2006 FEB 23 A 10: 25
UNIT OF
DEFECTS INVESTIGATION

Timothy A. Blubaugh
Director
Government Technical Affairs

Freightliner LLC
4747 N. Channel Avenue
Portland, OR 97217-7699
503.745.5219 Telephone
503.745.6800 Facsimile
TimothyBlubaugh@Freightliner.com

February 8, 2006

Dan Smith
Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590


**Re: Defect Information Report – supplemental information
FL-460, NHTSA no. 05V-467, Meritor Spindle on Meritor and AAC Rear Axles**

Mr. Smith:

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Freightliner LLC herewith submits supplemental defect information to revise the estimated date to send notifications to owners.

Please contact me if you have any questions.

Sincerely yours,



Timothy Blubaugh

Cc: Michael Mason, CAL-OSHA
DOSH, Legal Unit
10th Floor
455 Golden Gate Avenue
San Francisco, CA 94102

Enclosure

Certified Mail Article Number:

7003 2260 0001 3403 4049

Section 573.6 Defect Information Report
FL-460, NHTSA no. 05V-467
Supplement No.: 02

February 8, 2006

(c) (1) Manufacturer: FREIGHTLINER LLC
P.O. BOX 3849
Portland, Oregon 97208
(503) 745-5219

(c)(8) Estimated date to send owner notifications: March 17, 2006