

**FREIGHTLINER®**  
LLC  
A DaimlerChrysler Company

RECEIVED  
NVS-215

2006 MAY 31 P 3:21

OFFICE OF  
DEFECTS INVESTIGATION

Timothy A. Blubaugh  
Director  
Government Technical Affairs

Freightliner LLC  
4747 N. Channel Avenue  
Portland, OR 97217-7699  
503.745.5219 Telephone  
503.745.6800 Facsimile  
TimothyBlubaugh@Freightliner.com

May 24, 2006

Dan Smith  
Associate Administrator for Vehicle Safety  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

**Re: Defect Information Report – supplemental information  
(FL-451), NHTSA no. 05V-285, ConMet TruTurn Drum Tapered Mounting Flange**

Mr. Smith:

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Freightliner LLC herewith submits supplemental defect information to revise the affected population. The supplier has identified additional production dates that may contain the defect.

Please contact me if you have any questions.

Sincerely yours,



Timothy Blubaugh

Cc: Michael Mason, CAL-OSHA  
DOSH, Legal Unit  
10th Floor  
455 Golden Gate Avenue  
San Francisco, CA 94102

Enclosure

Certified Mail Article Number:

7002 3150 0004 1405 0679

**Section 573.6 Defect Information Report**  
**FL-451, ConMet TruTurn Drum Tapered Mounting Flange; NHTSA no. 05V-285**  
**Supplement No.: 04**

May 24, 2006

**(c) (1) Manufacturer:** FREIGHTLINER LLC  
P.O. BOX 3849  
Portland, Oregon 97208  
(503) 745-5219

**(c) (3) Total number of vehicles potentially affected:** (Revise to read) 4,651

**(c) (9) Communications sent to dealers:** posted March 8, 2006  
**Communications sent to owners:** Owner notifications were mailed to the original group March 15, 2006. Owner notifications will be mailed for the vehicles being added in the second phase on June 9, 2006