



RECEIVED

2006 JUN 12 A 11: 12

OFFICE OF DEFECTS
INVESTIGATION

Campaign # 06E050
June 12, 2006

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal-Mogul has decided that a defect which relates to motor vehicle safety exists in certain Federal-Mogul hub assemblies with a part number of 515058. Therefore, Federal-Mogul is recalling certain National 515058 hub assemblies distributed between Feb. 1, 2006 and May 26, 2006 in the United States and Canada. Only part numbers with packaging date codes listed below are affected.

Federal-Mogul records indicate that you have purchased one or more of these part numbers during the identified time period. Your stock may be mixed with defective hub assemblies.

1. Identification of equipment affected:

Certain National brand hub assembly 515058 product distributed between Feb. 1, 2006 and May 26, 2006 in the United States and Canada. These parts can be identified according to Attachment A.

Part No.	Date Code	Description	Application
515058 National Hub Assemblies	Feb. 1, 2006 and May 26, 2006 Packaging Date Code: 06039, 06045, 06046, 06069, 06081, 06082, 06087, 06108, 06138 Manufacturing Date Code: BA5, BAY, BAZ, BB6, BBA, BBB, BBC, BBN, BBO, BBP, BCJ, BDN, BDO, BDW	Hub Assembly	GM Truck, 1500/2500 4WD, 2001 - 2006

2. Description of possible malfunction and risk evaluation:

On the subject hub assemblies, the ABS sensor cord departs from the hub assembly at a 90 degree angle. As a result, there is a fit issue with the Brake Rotor Dust Shield interfering with the ABS sensor cord. If the hub assembly is installed despite this interference, the gap between the ABS sensor and the tone wheel may be altered. This may weaken the output of the ABS sensor. Diminished output could result in an unwanted ABS activation at low speeds and stopping distance could be effected. If stopping distance is limited, a vehicle crash could occur without prior warning.

3. Vehicle owner precautions:

The subject parts were distributed for aftermarket use. Customers who have installed one of these hub assemblies should have the subject part replaced as soon as possible.

Federal-Mogul Corporation
26555 Northwestern Hwy
Southfield, MI 48034

Page 1 of 2

4. Defect remedy measures:

Federal-Mogul wishes to sort and recover as many of these parts as possible. Therefore, we respectfully request that you quarantine and return the subject part numbers according to Attachment A. Federal-Mogul will assist in communicating to all customers the issue and proper procedure in identifying and returning all defective product. The return of the part(s) will be at no cost to you. Upon return of this part(s), your account will be credited for the part(s). For replacement of recalled product, you will need to order the appropriate stock number from customer service.

If the part is suspected to have been installed on a vehicle, Federal-Mogul will pay for inspection and replacement of the defective part(s), as well as shipping charges. Federal-Mogul will reimburse a maximum of \$52 for the labor cost of inspection and replacement of the defective parts. In order to qualify for this labor cost reimbursement, the subject defective part(s) must be written-up and routed through Federal-Mogul's normal labor claim procedure. Reimbursement will be paid for **inspection or product and labor claim – not both**.

For assistance on inspection reimbursement for National brand product, contact your local Federal-Mogul Sales Representative.

For return of unused defective parts, please complete the attached Recall RGA Request Form and fax to 314-977-0963. A return goods authorization (RGA) and shipping instructions will be sent back to you in a timely manner. The return package should be clearly marked with "**reference hub assembly recall**".

For return of installed parts, a labor claim form, complete with an RGA number and appropriate receipts **must** accompany all defective returns removed from the vehicles. The reason for return on the labor claim form should include "**reference hub assembly recall**".

If you should have any questions regarding this recall, please contact your sales representative or call 1-877-489-6659 and a representative will be available to assist you.

5. Owner complaint process

If the owner believes that Federal-Mogul has failed or is unable to remedy without charge the condition outlined above within a reasonable time, the owner with a 515058 hub assembly may call the toll free Vehicle Safety Hotline at 1-888-327-4236, (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Our commitment to product quality is at the forefront of all we do at Federal-Mogul. Our dedication to manufacturing mastery is supported by all within the organization.

Federal-Mogul apologizes for any inconvenience. We know, however, that you share our concern for vehicle safety. We appreciate your immediate response to this matter.

Sincerely,



Joe Stephan
Marketing Director
Federal-Mogul