

IDENTIFICATION OF DEFECTIVE HUB ASSEMBLY



Title: Hub Assembly Recall: 515058

ATTACHMENT A

DRAFT 05/26/06

1 of 1

(Document Identification #)

(Revision Level)

(Page(s))

Background:

Federal-Mogul has identified an interference problem between the ABS sensor cord and the brake rotor dust shield on certain 515058 hub assemblies. The subject hub assemblies have been shipped to customers by Federal-Mogul between dates of Feb. 1, 2006 and May 26, 2006.

Part No.	Date Code	Description	Application
515058 CARQUEST Hub Assemblies	Feb. 1, 2006 and May 26, 2006 Packaging Date Code: 06039, 06045, 06046, 06069, 06081,06082, 06087, 06108, 06138 Date code on Hub Assembly: BA5,BAY,BAZ, BB6,BBA,BBB, BBC,BBN,BBO, BBP,BCJ,BDN, BDO,BDW	Hub Assembly	GM Truck, 1500/2500 4WD, 2001 - 2006

Identification of defective hub assemblies

Defective hub assemblies can be identified in two ways:

1. Date Code on the Hub Assembly
2. Date Code on the Hub Assembly package

Action required

If you find defective product in your stock, please **quarantine** those hub assemblies and call your Federal Mogul sales representative or call 1-877-489-6659 and a representative will be available to assist you.

IDENTIFICATION OF DEFECTIVE HUB ASSEMBLY



Title: Hub Assembly Recall: 515058

ATTACHMENT A

DRAFT 05/26/06

1 of 1

(Document Identification #)

(Revision Level)

(Page(s))

Background:

Federal-Mogul has identified an interference problem between the ABS sensor cord and the brake rotor dust shield on certain 515058 hub assemblies. The subject hub assemblies have been shipped to customers by Federal-Mogul between dates of Feb. 1, 2006 and May 26, 2006.

Part No.	Date Code	Description	Application
515058 <u>National Hub Assemblies</u>	Feb. 1, 2006 and May 26, 2006 Packaging Date Code: 06039, 06045, 06046, 06069, 06081,06082, 06087, 06108, 06138 Date code on Hub Assembly: BA5,BAY,BAZ, BB6,BBA,BBB, BBC,BBN,BBO, BBP,BCJ,BDN, BDO,BDW	Hub Assembly	GM Truck, 1500/2500 4WD, 2001 - 2006

Identification of defective hub assemblies

Defective hub assemblies can be identified in two ways:

1. Date Code on the Hub Assembly
2. Date Code on the Hub Assembly package

Action required

If you find defective product in your stock, please **quarantine** those hub assemblies and call your Federal Mogul sales representative or call 1-877-489-6659 and a representative will be available to assist you.