



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

JUL - 7 2006

400 Seventh Street, SW
Washington, DC 20590

MR. KEVIN FENG
VICE PRESIDENT
AAI MOTORSPORTS USA, LLC
709 EAST CEDAR STREET
ST. ONTARIO, CA 91761

NVS-215kjs
06E-060

Subject: FMVSS 108/AMBER SIDE REFLECTORS

Dear MR. FENG:

This letter is to acknowledge your recent noncompliance information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AAI MOTORSPORTS/COMBINATION LAMPS/9999
ACURA/INTEGRA/1990-2001
AUDI/A4/1995-2000
BMW/E36/1992-2003
CHEVROLET/C10/1994-1998
CHEVROLET/S10/1998-2003
CHEVROLET/SILVERADO/1999-2006
DODGE/NEON/1995-1998
DODGE/RAM/1994-2001
FORD/EXPEDITION/1997-2001
FORD/F150/1997-2001
FORD/F150/2004-2006
FORD/MUSTANG/1994-1998
HONDA/ACCORD/1990-2002
HONDA/CIVIC/1996-2003
HONDA/CRX/1988-1991
HONDA/DEL SOL/1993-1997
HONDA/PRELUDE/1992-2006
INFINITI/G35/2003-2004

MITSUBISHI/ECLIPSE/1995-2003
SUBARU/WRX/2002-2006
TOYOTA/SCION XB/2002-2006
TOYOTA/SOLARA/1998-2001
VOLKSWAGEN/BEETLE/1998-2002

NHTSA Campaign Number: 06E-060

Mfg's Report Date: June 20, 2006

Components:

EXTERIOR LIGHTING

Potential Number of Units Affected: 87,745

Summary:

CERTAIN AAI MOTORSPORTS COMBINATION LAMPS SOLD AS REPLACEMENT LAMPS FOR USE ON THE ABOVE LISTED PASSENGER VEHICLES. COMBINATION LAMPS NOT EQUIPPED WITH AMBER SIDE REFLECTORS FAIL TO CONFORM WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT."

Consequence:

LACK OF AMBER SIDE REFLECTORS IN THE LAMPS WILL DECREASE LIGHTING VISIBILITY TO OTHER DRIVERS AND MAY POSSIBLY RESULT IN A VEHICLE CRASH

Remedy:

AAI MOTORSPORTS WILL NOTIFY OWNERS AND REPLACE THE LAMPS FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING JULY 2006. OWNERS MAY CONTACT AAI MOTORSPORTS AT 909-923-9188.

Notes:

THIS RECALL ONLY PERTAINS TO AAI MOTORSPORTS AFTERMARKET LAMPS AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON THE LISTED PASSENGER VEHICLES. FOR MORE INFORMATION ON THE LAMP MODEL NUMBERS, CLICK ON DOCUMENT SEARCH AND VIEW DOCUMENT TITLED "LAMP MODEL NUMBERS." CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

This recall is the result of an investigation, OA-108-060505A, conducted by the Office of Vehicle Safety Compliance.


Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, the recall is expected to begin during July 2006. Therefore, the first quarterly report will be due in this office on or before 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227 or by email at KSCHULER@NHTSA.DOT.GOV. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement