

SAFETY RECALL NOTICE
Voluntary Safety Recall Campaign 06E043

RECEIVED

2006 JUL 11 A 9:47
OFFICE OF DEFECTS
INVESTIGATION

June 6, 2006

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Honeywell Consumer Products Group has decided that a defect which relates to motor vehicle safety exists in certain fuel filters manufactured distributed by Honeywell under the FRAM brand name. Honeywell is voluntarily recalling the affected product.

WHAT PRODUCTS ARE INVOLVED?

This recall involves G3727 fuel filters that were manufactured in Mexico from October 18, 2005 through March 21, 2006. These products were sold exclusively in the aftermarket.

Important Note: Not all G3727 fuel filters are involved. Rather, only products with (i) date codes X52911 through X60801 sequentially or X600141 and (ii) a Mexico country of origin marking on the fuel filter housing are subject to this recall. A depiction of the product showing location of the date code and country of origin is attached to this notice for your convenience.

WHAT IS THE PROBLEM?

The connector on the fuel filter was not manufactured to Honeywell's specification. As a result, the O-ring may not seat correctly on the fuel line. This condition may cause an inadequate seal at this connection, leading to a potential fuel leak (i.e., wetting or dripping) and possible vehicle fire.

WHAT SHOULD YOU DO?

If you have purchased one of the subject fuel filters through a retailer or installer, please contact your supplier for replacement instructions. Free replacement fuel filters are available upon return of the product to your supplier.

If you have any questions, please call FRAM Customer Service at 1-800-890-2075 (option 1). You may also contact the Administrator, National Highway Traffic Safety Administration, at 400 Seventh Street, S.W., Washington, D.C. 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4326 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if you are unable to obtain a remedy without charge within a reasonable time.



The part number (G3727), country of origin (Mexico) and the date code (e.g., X60031) are located on the side of the fuel filter.



The UPC number (009100350855) and the part number (G3727) are located on the end of the carton.

* * *

FRAM apologizes for any inconvenience this may cause, but is taking this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.