

SAFETY RECALL NOTICE



AUTOCAR SAFETY RECALL A-0604 NHTSA RECALL 07V-007

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

A defect relating to motor vehicle safety exists in certain WX, WXR and WXML 2006 and 2007 model-year, heavy-duty Class 8 vehicles shipped between October 3, 2006 and December 9, 2006 with serial numbers in the range 203647 through 204784. Attached for your reference is a list of affected vehicle identification numbers (VIN's).

- SAFETY DEFECT:** On certain heavy duty Class 8 Xpeditors, some of the seat base mounting fasteners that secure the seat base to the cab floor bracket may have been left loose or not installed at all. See Figure 1 on page 3 for the location of the outer seat base mounting fasteners (only those on the LH side of the LH seat are shown on the photo).
- POTENTIAL RISK:** Improperly torqued seat-mounting fasteners may allow movement of the driver's seat while he/she is operating the vehicle. This movement could result in a temporary loss of control, increasing the risk of a crash that could result in severe injury or death.
- PRECAUTIONS YOU CAN TAKE:** Inspect the seat mounting fasteners visually. If any of the fasteners are loose or missing, do not drive the vehicle until they are properly secured.
- REPAIR:** An Autocar dealer will inspect, and if necessary, repair your vehicle at no charge to you.
- TIME REQUIRED FOR THE REPAIR:** The labor time required to inspect your vehicle and secure any suspect seat fasteners is about one-half hour.
- WHAT YOU SHOULD DO:** Immediately contact an Autocar dealer to schedule a service appointment to have your vehicle inspected and repaired. To locate an Autocar dealer, go to www.autocartruck.com and select Sales, Service & Parts, or call 1-877-973-3486 ext. 2572.

SAFETY RECALL NOTICE



**PRE-
NOTIFICATION
REPAIR:**

If you have previously paid for repairs to the seat base mounting fasteners, you may be entitled to recover any amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

**NOTICE
REGARDING
LEASED
VEHICLES:**

If you are a Lessor (as defined below) of a vehicle that is affected by this Notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice, and the VIN(s) of the vehicle(s) that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles (as defined in 49 CFR Section 577.4), as of the date of this Notice.

**OWNER RECALL
RESPONSE
CARD:**

The enclosed "Owner Recall Response Card" identifies your vehicle. Presentation of this card to any Authorized Full Service or Parts and Service Autocar dealer will assist in the processing of your vehicle in the shortest time possible. If you do not own, have sold or have traded the vehicle identified on the card, please let us know by completing and signing the postage-paid card and returning it to Autocar at the address below.

ASSISTANCE:

If your vehicle has not been inspected and repaired within a reasonable time after delivering it to the dealer on the agreed-upon service date, please contact:

Autocar, LLC
Service & Warranty Department
P. O. Box 190
Hagerstown, IN 47346-0190
Toll free: 1-877-973-3486

You may also submit a complaint to:

Administrator
National Highway Traffic Safety Administration
400 Seventh Street S. W.
Washington DC 20590
Toll-free Auto Safety Hot Line: 1-888-327-4236
Toll-free Vehicle Safety Hotline: 1-888-327-4236
(TTY: 1-800-424-9153)
<http://www.safercar.gov>

SAFETY RECALL NOTICE




Figure 1

We regret any inconvenience this recall may cause, but we hope you recognize our concern for your safety and satisfaction with your vehicle.

Sincerely,

AUTOCAR, LLC

Jo Theart
Compliance
Phone: 765-489-6040
Fax: 765-489-5230
jtheart@autocartruck.com

SAFETY RECALL NOTICE



AUTOCAR SAFETY RECALL A-0604 NHTSA RECALL 07V-007

List of affected vehicle identification numbers (VIN's):

5VDC6ME07H203647	5VDC6ME27H203648	5VDC6ME47H203649	5VDC6ME07H203650
5VDC6BF17H203670	5VDC6MF97H203784	5VDC6MF07H203785	5VDC6MF77H203878
5VDC6MF77H203881	5VDC6MF97H203882	5VDC6MFX7H203891	5VDC6MF47H203935
5VDC6MF67H203936	5VDC6MF87H203937	5VDC6MFX7H203938	5VDC6MF17H203939
5VDC6MFX7H203941	5VDC6MF17H203942	5VDC6MF37H203943	5VDC6MF57H203944
5VDC6MF77H203945	5VDC6MF97H203946	5VDC6MF07H203947	5VDC6MF27H203948
5VDC6MF47H203949	5VDC6MF07H203950	5VDC6MF47H203952	5VDC6MF67H203953
5VDC6MF87H203954	5VDC6MF17H203956	5VDC6MF17H203990	5VDC6MF37H203991
5VCHC6PE67H204024	5VDC6MF07H204032	5VCHC6MF47H204035	5VDC6BE37H204150
5VDC6MF87H204165	5VDC6MF37H204199	5VDC6MF67H204200	5VDC6MFX7H204216
5VDC6MF17H204217	5VDC6MF37H204218	5VDC6MF57H204219	5VDC6MF17H204220
5VDC6MF37H204221	5VDC6MF57H204222	5VDC6MF77H204223	5VDC6MF97H204224
5VDC6MF07H204225	5VDC6MF27H204226	5VDC6MF47H204227	5VDC6MF67H204228
5VDC6MF87H204229	5VDC6MF47H204230	5VDC6MF67H204231	5VDC6MF87H204232
5VDC6MFX7H204233	5VDC6MF17H204234	5VDC6MF37H204235	5VDC6MF57H204236
5VDC6MF27H204274	5VDC6MF47H204275	5VDC6MF67H204276	5VCHC6MF27H204289
5VCH36MF57H204299	5VCH36MF87H204300	5VDC6MF07H204354	5VDC6MF27H204355
5VDC6MF47H204356	5VDC6MF67H204357	5VDC6BE87H204371	5VDC6BE57H204375
5VDC6BE27H204382	5VDC6MF27H204386	5VDC6MF47H204387	5VDC6MF67H204388
5VDC6BE37H204391	5VDC6BE57H204392	5VDC6BE97H204394	5VCHC6MF17H204395
5VCHC6MF37H204396	5VCHC6MF77H204398	5VDC6MF27H204419	5VDC6MF97H204420
5VDC6MF07H204421	5VDC6MF27H204422	5VDC6RE67H204424	5VCHC6RE97H204435
5VCHC6RE07H204436	5VCHC6RE27H204437	5VCHC6RE47H204438	5VCHC6RE67H204439
5VCHC6RE27H204440	5VCHC6RE47H204441	5VCH36FE47H204458	5VCH36FE67H204459
5VDC6MF97H204479	5VDC6MF57H204480	5VDC6MF77H204481	5VDC6FE27H204490
5VDC6FE47H204491	5VDC6RE97H204496	5VDC6RE07H204497	5VDC6FE77H204498
5VDC6MF07H204502	5VDC6MF27H204503	5VDC6MF17H204508	5VDC6MF37H204509
5VDC6MF47H204518	5VDC6MF67H204519	5VCH36PE77H204520	5VDC6BE17H204521
5VDC6BE37H204522	5VDC6BE57H204523	5VDC6BE77H204524	5VDC6BE97H204525
5VCHC6MF37H204527	5VDC6KE47H204528	5VDC6MF97H204529	5VDC6MF57H204530
5VDC6MF77H204531	5VDC6FE97H204535	5VDC6MF67H204536	5VDC6BG37H204537
5VDC6MFX7H204538	5VDC6MF17H204542	5VDC6MF37H204543	5VDC6MF57H204544
5VDC6MF77H204545	5VDC6MF97H204546	5VDC6MF67H204553	5VDC6MF87H204554
5VDC6MFX7H204555	5VDC6BE97H204556	5VDC6BE07H204557	5VDC6BE27H204558
5VDC6BE17H204566	5VDC6MF67H204567	5VDC6MF87H204568	5VDC6MFX7H204569
5VDC6MF67H204570	5VDC6MF87H204571	5VDC6MFX7H204572	5VDC6MF17H204573
5VDC6MF37H204574	5VDC6MF57H204575	5VDC6MF77H204576	5VDC6MF97H204577
5VDC6MF87H204585	5VDC6BE27H204592	5VDC6BE47H204593	5VDC6BE67H204594
5VDC6BE87H204595	5VCHC6MF27H204597	5VCHC6MF47H204598	5VCHC6MF67H204599
5VCHC6FE57H204601	5VCHC6FE77H204602	5VCHC6FE97H204603	5VCHC6FE47H204606
5VCHC6FE67H204607	5VDC6MF57H204608	5VCHC6MF57H204609	5VCHC6MF37H204611
5VCHC6MF57H204612	5VCHC6MF07H204615	5VCHC6MF27H204616	5VCHC6MF87H204619
5VDC6ME07H204622	5VDC6ME27H204623	5VDC6ME67H204625	5VDC6ME87H204626
5VDC6MEX7H204627	5VDC6ME17H204628	5VDC6ME37H204629	5VDC6MEX7H204630
5VDC6ME17H204631	5VDC6ME37H204632	5VDC6ME57H204633	5VDC6ME77H204634
5VDC6ME97H204635	5VDC6ME07H204636	5VDC6ME27H204637	5VDC6ME47H204638
5VDC6ME67H204639	5VDC6ME27H204640	5VDC6ME47H204641	5VDC6ME67H204642
5VDC6ME87H204643	5VDC6MEX7H204644	5VDC6ME17H204645	5VDC6ME37H204646
5VDC6ME57H204647	5VDC6ME77H204648	5VDC6ME97H204649	5VDC6ME57H204650
5VDC6ME97H204652	5VDC6ME07H204653	5VDC6ME27H204654	5VDC6ME47H204655
5VDC6ME67H204656	5VDC6MEX7H204658	5VDC6ME87H204660	5VDC6ME17H204662

SAFETY RECALL NOTICE



5VCDC6ME57H204664	5VCHC6MF87H204684	5VCHC6MFX7H204685	5VCHC6MF17H204686
5VCDC6JE07H204687	5VCDC6BG27H204688	5VCDC6MF47H204700	5VCDC6MF67H204701
5VCDC6MF87H204702	5VCDC6REX7H204703	5VCDC6RE17H204704	5VCDC6MF57H204706
5VCDC6MF77H204710	5VCDC6MF97H204711	5VCDC6MF47H204728	5VCDC6MF57H204754
5VCHC6MF07H204775	5VCHC6MF27H204776	5VCHC6MF47H204777	5VCHC6MF67H204778
5VCHC6MF87H204779	5VCHC6MF47H204780	5VCHC6MFX7H204783	5VCHC6MF17H204784
5VCDC6BE27H204804	5VCDC6BE47H204805	5VCDC6RE47H204809	5VCDC6MF47H204812
5VCDC6MF67H204813	5VCDC6MF87H204814	5VCDC6MF47H204826	5VCDC6MFX7H204829