



Driven to Explore

RECEIVED

2007 JULY - 10 P 1:00

July 3, 2007

DEFECTS INVESTIGATION
RECALL MGMT DIV.

Fleetwood Enterprises, Inc
3030 Myers Street / Riverside, CA 92507-5527
P.O. Box 7638 / Riverside, CA 92513-7638
P: 951.322.8216 / www.fleetwood.com

Mr. Kenneth Weinstein
Administration for Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street S.W.
Washington, DC 20590

07V-294
(2 Pages)

Re: Amended Safety Defect Report

Dear Mr. Weinstein:

Fleetwood Enterprises, Inc. has decided that a safety defect exists in motor homes as listed below, and is furnishing this notification in accordance with 49 CFR Part 573 Defect and Non-compliance reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on June 27, 2007.
 - Fleetwood has assigned 70702 as an identification code to this recall.
- (1) The affected motor homes were manufactured by the following wholly owned subsidiaries of Fleetwood Enterprises, Inc.

Fleetwood Motor Homes of California, Inc. #47
5300 Via Ricardo, P.O. Box 5726
Riverside, California 92517

Fleetwood Motor Homes of Pennsylvania, Inc. #71
Drawer5
Route 487
Paxinos, Pennsylvania 17860

The agency should contact the following individual with respect to this recall:

David Coffin
Director of Product Development
Motor Home Division
2970 Myers Street
Riverside, California 92513-7638
Telephone: (951) 351-3804
Fax: (951) 351-3644

- (2) The vehicles involved in this recall are 2008 model year Jamboree and Tioga brand class C motor homes manufactured between March 30, 2007 and May 29, 2007. The May 29, 2007 date coincides with the installation of the correct spare wheel. These motor homes were built with a Fleetwood identification number range of 788Q84796995 through 741M84797738 and 789W87171667 through 789W87171896. Please see Service Bulletin #70702 for a complete listing of serial numbers involved in this recall campaign.

- (3) Fleetwood reports 260 as an approximate number of motor homes containing the safety defect.
- (4) Fleetwood estimates that 75% of the identified motor homes contain the safety defect.
- (5) On certain Jamboree and Tioga class C motor homes affected by this recall the contour surface of the spare wheel when installed on the front axle, may contact the front brake caliper mounting brackets. Owners of the subject motor homes may experience a grinding/scraping noise in the front with the spare wheel installed. This could cause premature wheel failure resulting in a loss of vehicle control and or an accident.
- (6) Not applicable.
- (7) Fleetwood began an investigation in June, 2007 when this situation was discovered during manufacture.

Fleetwood is not aware of any accidents or injuries that have resulted from this safety defect.

- (8) Fleetwood will inspect and install the correct spare wheel.
- (9) Fleetwood intends to conduct a dealer notification mailing on July 23, 2007.
Fleetwood intends to conduct a customer notification mailing on July 30, 2007.
- (10) Fleetwood does not foresee any problems with implementing this voluntary recall campaign.
- (11) Copies of subsequent correspondence will be submitted to NHTSA within five (5) working days of distribution. This correspondence will include:
 - I) Letter of dealer notification
 - II) Letter of customer notification
 - III) Service Bulletin

Drafts of the service bulletin and letters to dealers and owners will be forthcoming for your review.

If additional information is required, please contact Shelley Smith by phone: (951) 351-3646 or e-mail: ssmith@fleetwood.com.

Sincerely,



David Coffin
Director of Product Development
Motor Home Division