

Service Bulletin SBU0124



**SERVICE
BULLETIN:
SBU0124**

**YEAR(S)
AFFECTED:
1997-2004**

**PRODUCT(S)
AFFECTED:**
All
Motor Homes,
Travel Trailers,
and
5th Wheel Travel
Trailers

**MODEL(S)
AFFECTED:
All**

SUBJECT:
Notification
of Dometic
Refrigerator
Recall, 06E-076

KEYWORDS:
Refrigerator,
Dometic, Refer,
Boiler Tube,
Ammonia,
Coolant

ISSUE DATE:
July 2007

The purpose of this Bulletin is to inform all Fleetwood dealers about a Dometic Corporation Safety Recall Campaign Number 06E-076, on certain Dometic two-way and three-way refrigerators. Dometic manufactured the refrigerators between April 1997 and May 2003. This Bulletin explains the procedure on how to identify affected refrigerator models and serial numbers.

CONDITION:

After some period of use, a fatigue crack may develop in the boiler tube of the covered refrigerators that may release a sufficient amount of pressurized coolant solution into an area where an ignition source may be present. If this were to occur under certain conditions, the coolant could ignite and result in a fire.

AFFECTED DOMETIC REFRIGERATOR IDENTIFICATION:

To determine if a recreational vehicle has an affected refrigerator, record the Dometic model and serial number for reference.

NOTE: The Dometic serial number is listed on a sticker inside the refrigerator.

Dometic has established the following internet address:

<http://www.dometicusa.com/recall.php>

Log into the Dometic internet address listed above, select the model number of the refrigerator from the drop-down box on this web site, and enter the 8-digit serial number to learn if the refrigerator is affected by this Dometic recall.

Affected refrigerators should be repaired according to service instructions available from the Dometic Corporation.

NOTE: The Dometic Corporation has contracted with Stericycle, Inc. to administrate all details for this Recall including repair service claim processing.

Claims should not be submitted to Fleetwood for this repair.

If you have any questions concerning this Dometic Safety Recall Campaign, contact the Dometic Corporation at:

1-888-446-5157

© 2007 Fleetwood Enterprises, Inc.

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assume that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."