


VOLKSWAGEN of America, Inc.



Product Compliance
3800 Hamlin Road
Auburn Hills, MI 48326
Phone: 1 (248) 754-5000
Fax: 1 (248) 754-5093

September 14, 2007

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue, S.E.
Washington, DC 20590

Subject: Notification of Recall
2006 – 2008 Model Year Audi A6 Avant, 2007 – 2008 Model Year Audi Q7
Automatic Rear Lid Software

Dear Mr. Smith,

This will amend our Part 573 Report dated July 23, 2007 by providing the following additional information regarding the Voluntary Recall 07V-334.

Volkswagen is broadening the range of vehicles as follows:

573.6 (c) (2) **Identification of Vehicles**

Make : Audi
Line : A6 Avant, Audi Q7
Model Years : A6 Avant: 2006 – 2008
Audi Q7: 2007 – 2008
Month/Year
of Manufacture : A6 Avant: Jan 2006 – July 2007
Audi Q7: December 2005 – July 2007
VIN Numbers : WAU___4F_6N128894 – WAU___4F_8N032532
of Affected : WA1___4L_7D001257 – WA1___4L_8D014458
Vehicles
Other
Identification : None

573.6 (c) (3) **Number of Vehicles Potentially Containing the Defect**

The number of additional affected vehicles is approximately 1,028 Audi A6 Avant vehicles and 21,849 Audi Q7 vehicles.

573.6 (c) (6)

Basis for Determination

Internal testing conducted by Audi AG in conjunction with a recent similar strut failure on a Q7 vehicle indicated that these additional vehicles may be affected by the defect. In an abundance of caution, Audi AG is including these Q7 vehicles as well as additional A6 Avant vehicles.

Date of determination: September 10, 2007

573.6 (c) (8)


Proposed Remedial Program

Mailing dates are anticipated as follows:

Dealers: On or about September 21, 2007

Owners: On or about September 27, 2007

Sincerely,



John Maddox
Product Compliance Officer
Volkswagen of America