



U.S. Department
of Transportation

1200 New Jersey Avenue, SE.
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

February 14, 2008

MR. ROBERT BABCOCK
SENIOR MANAGER
HYUNDAI-KIA AMERICA TECHNICAL CENTER, INC.
6800 GEDDES ROAD
SUPERIOR TOWNSHIP, MI 48198

NVS-215kjs
08E-016

Subject: AFTERMARKET TOW HITCH SYSTEM/WIRING HARNESS

Dear MR. BABCOCK:

This letter serves to acknowledge Hyundai-Kia America Technical Center Inc.'s (Hyundai) notification to the National Highway Traffic Safety Administration (NHTSA) of a defect for the products listed below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/SANTA FE/2007-2008
HYUNDAI/VERACRUZ/2007-2008
HYUNDAI/U86102B100/9999
HYUNDAI/U86103J000/9999
HYUNDAI/U86122B000/9999
HYUNDAI/U86123J000/9999

NHTSA Campaign Number: 08E-016

Mfg's Report Date: January 31, 2008

Components: TRAILER HITCHES

Potential Number of Units Affected: 3,387

Summary:

HYUNDAI IS RECALLING 3,387 TRAILER HITCH WIRING HARNESSSES EITHER INCLUDED WITH A TRAILER HITCH OR SOLD AS A SERVICE PART MANUFACTURED BY THULE TOWING SYSTEMS AND DISTRIBUTED BY HYUNDAI FOR INSTALLATION ON MY 2007-2008 SANTA FE AND VERACRUZ VEHICLES. THE ACCESSORY TRAILER HITCH WIRING HARNESS CONVERTER MODULE IS MOUNTED TO THE TOP SURFACE OF THE REAR BUMPER REINFORCEMENT. HIGH CURRENT LEAKAGE OR A SHORT CIRCUIT OF CAPACITOR C1 COULD CAUSE HEAT RELATED DAMAGE TO THE WIRING HARNESS CONVERTER MODULE.

Consequence:

EXCESSIVE HEAT MAY CAUSE DAMAGE TO THE REAR BUMPER AREA AND MAY POTENTIALLY RESULT IN A FIRE.

Remedy:

HYUNDAI WILL NOTIFY OWNERS AND WILL REPLACE THE TRAILER HITCH WIRING HARNESS FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING FEBRUARY 2008. OWNERS MAY CONTACT HYUNDAI AT 1-800-633-5151.

Notes:

HYUNDAI RECALL NO. 082. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

We have received Hyundai's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete. Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for the successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read "G. Person". The signature is fluid and cursive, with a large initial "G" and a long, sweeping underline.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement