

Next Unread Message

View Message

Sent on 03 19 2008 Expires on 03 30 2008
 From Motorcycle Service Management
 Subject STOP SALE: Fuel Leakage SAFETY RECALL



Motorcycle Division

March 19, 2008

Dear Honda Motorcycle Dealer:

RECALL and STOP SALE NOTICE

AFFECTED UNITS: (see model/VIN list below)

VT600C	2006-2008	VT600CD	2006-2008	VT750C	2007-2008
VT750C2	2007-2008	VTX1300C	2007-2008	VTX1300R	2007-2008

American Honda (AHM) is conducting a **SAFETY RECALL** on affected motorcycles per the model and VIN list below. The **SAFETY RECALL** will correct a problem that may exist in some motorcycles which could allow fuel to leak past the petcock diaphragm. Leakage of this type would negatively affect engine operation, vehicle emissions, and under certain circumstance could present a fire hazard.

Effective immediately **YOU MUST NOT SELL** any affected model in your inventory until the required repair has been completed. Please make sure ALL DEPARTMENTS in your dealership; Parts, Sales, and Service are made aware of this action.

Information including instructions, procedures, and parts delivery schedule to repair affected motorcycles will be made available to your dealership as soon as possible. Date specific information as to each of these items will be sent to you the week of March 31, 2008.

If you have recently sold an affected model, please submit the warranty registration information immediately, so that AHM can contact the owner.

If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Model	YM	VIN	
		From	To
VT600C6	2006	JH2PC21046M700001	JH2PC21096M700544
VT600C6	2006	JH2PC21136M700001	JH2PC21196M700102
VT600C6	2006	JH2PC21056K710001	JH2PC21036K710918
VT600C6	2006	JH2PC21146K710001	JH2PC21136K710068
VT600C7	2007	JH2PC21097M800001	JH2PC21017M801157
VT600C7	2007	JH2PC21187M800001	JH2PC21107M800204
VT600C7	2007	JH2PC210X7K810001	JH2PC21077K810408
VT600CD6	2006	JH2PC214X6M700006	JH2PC21486M702109
VT600CD6	2006	JH2PC21576M700005	JH2PC21516M700341
VT600CD6	2006	JH2PC21416K710001	JH2PC214X6K712006
VT600CD6	2006	JH2PC21506K710001	JH2PC21516K710170
VT600CD7	2007	JH2PC21457M800001	JH2PC21467M803604
VT600CD7	2007	JH2PC21467M820001	JH2PC21417M821802
VT600CD7	2007	JH2PC21547M800001	JH2PC215X7M800374
VT600CD7	2007	JH2PC21557M820001	JH2PC21567M820170

VT600CD7	2007	JH2PC21467K810001	JH2PC21427K810884
VT600CD7	2007	JH2PC21557K810001	JH2PC21547K810068
VT750C27	2007	JH2RC53047M000794	JH2RC53067M003910
VT750C27	2007	JH2RC53147M000044	JH2RC531X7M000422
VT750C28	2008	JH2RC53038M100001	JH2RC53008M102580
VT750C28	2008	JH2RC53128M100001	JH2RC53118M100300
VT750C28	2008	JH2RC53048K110001	JH2RC53018K110540
VT750C28	2008	JH2RC53138K110001	JH2RC53188K110060
VT750C2F7	2007	JH2RC53407M001007	JH2RC53437M005133
VT750C2F7	2007	JH2RC53517M000067	JH2RC53527M000515
VT750C2F8	2008	JH2RC534X8M100001	JH2RC53498M102645
VT750C2F8	2008	JH2RC53598M100001	JH2RC53588M100300
VT750C2F8	2008	JH2RC53408K110001	JH2RC53408K110371
VT750C2F8	2008	JH2RC535X8K110001	JH2RC53568K110030
VT750C7	2007	JH2RC50037K310001	JH2RC50027K310930
VT750C7	2007	JH2RC50127K310001	JH2RC50197K310030
VT750C8	2008	JH2RC50078M400003	JH2RC50028M401802
VT750C8	2008	JH2RC50168M400003	JH2RC50158M400183
VT750C8	2008	JH2RC50088K410001	JH2RC50088K410533
VT750C8	2008	JH2RC50178K410001	JH2RC50118K410060
VT750CA7	2007	JH2RC50487M304329	JH2RC50497M305408
VT750CA7	2007	JH2RC50547M300481	JH2RC50587M300600
VT750CA8	2008	JH2RC50438M400002	JH2RC50478M401801
VT750CA8	2008	JH2RC50528M400004	JH2RC50518M400183
VT750CA8	2008	JH2RC50448K410001	JH2RC50418K410750
VT750CA8	2008	JH2RC50538K410001	JH2RC505X8K410240
VTX1300C7	2007	1HFSC55047A302231	1HFSC55017A308830
VTX1300C7	2007	1HFSC55177A300174	1HFSC55187A300300
VTX1300C8	2008	1HFSC55048A400001	1HFSC55018A400270
VTX1300C8	2008	1HFSC55138A400001	1HFSC55148A400071
VTX1300R7/T7	2007	1HFSC52687A404091	1HFSC52637A411580
VTX1300R7/T7	2007	1HFSC52737A400121	1HFSC52717A400540
VTX1300R8/T8	2008	1HFSC526X8A500001	1HFSC52638A500331
VTX1300R8/T8	2008	1HFSC52T28A500001	1HFSC52T68A500553
VTX1300R8/T8	2008	1HFSC52798A500001	1HFSC52708A500060
VTX1300R8/T8	2008	1HFSC52N08A500001	1HFSC52N48A500065

Thank you for your cooperation.

American Honda Motor Co., Inc.



Robert E. Clever
Senior Manager – Service
Motorcycle Division

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
08-0131	1	of	1	SERVICE

Next Unread Message

View Message

Sent on 03 21 2008 Expires on 04 02 2008
 From Motorcycle Service Management
 Subject REVISED STOP SALE: Fuel Leakage RECALL (expanded VIN list and models)



Motorcycle Division

March 21, 2008

Dear Honda Motorcycle Dealer:

RECALL and STOP SALE NOTICE

AFFECTED UNITS: (see model/VIN list below)

VT600C	2006-2007	VT750C	2007-2008	VTX1300C	2007-2008
VT600CD	2006-2007	VT750CA	2007-2008	VTX1300R	2007-2008
		VT750C2	2007-2008	VTX1300S	2007-2008
		VT750C2F	2007-2008	VTX1300T	2008

American Honda (AHM) is conducting a **SAFETY RECALL** on affected motorcycles per the model and VIN list below. The **SAFETY RECALL** will correct a problem that may exist in some motorcycles which could allow fuel to leak past the petcock diaphragm. Leakage of this type would negatively affect engine operation, vehicle emissions, and under certain circumstances could present a fire hazard.

Effective immediately **YOU MUST NOT SELL** any affected model in your inventory until the required repair has been completed. Please make sure ALL DEPARTMENTS in your dealership; Parts, Sales, and Service are made aware of this action.

Information including instructions, procedures, and parts delivery schedule to repair affected motorcycles will be made available to your dealership as soon as possible. Date specific information as to each of these items will be sent to you the week of March 31, 2008.

If you have recently sold an affected model, please submit the warranty registration information immediately, so that AHM can contact the owner.

If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Thank you for your cooperation.

American Honda Motor Co., Inc.

Robert E. Clever
 Senior Manager – Service
 Motorcycle Division

(*) denotes check digit

Year	Model	VIN
------	-------	-----

		From	To
2006	VT600C	JH2PC210*6M700001	JH2PC210*6M700544
	VT600C	JH2PC210*6K710001	JH2PC210*6K710918
	VT600CL	JH2PC211*6M700001	JH2PC211*6M700102
	VT600CL	JH2PC211*6K710001	JH2PC211*6K710068
	VT600CD	JH2PC214*6M700006	JH2PC214*6M702109
	VT600CD	JH2PC214*6K710001	JH2PC214*6K712006
	VT600CDL	JH2PC215*6M700005	JH2PC215*6M700341
	VT600CDL	JH2PC215*6K710001	JH2PC215*6K710170
2007	VT600C	JH2PC210*7M800001	JH2PC210*7M801157
	VT600C	JH2PC210*7K810001	JH2PC210*7K810408
	VT600CL	JH2PC211*7M800001	JH2PC211*7M800204
	VT600CD	JH2PC214*7M800001	JH2PC214*7M803604
	VT600CD	JH2PC214*7M820001	JH2PC214*7M821802
	VT600CD	JH2PC214*7K810001	JH2PC214*7K810884
	VT600CDL	JH2PC215*7M800001	JH2PC215*7M800374
	VT600CDL	JH2PC215*7M820001	JH2PC215*7M820170
	VT600CDL	JH2PC215*7K810001	JH2PC215*7K810068
	VT750C	JH2RC500*7K310001	JH2RC500*7K310930
	VT750CL	JH2RC501*7K310001	JH2RC501*7K310030
	VT750CA	JH2RC504*7M304329	JH2RC504*7M305408
	VT750CAL	JH2RC505*7M300481	JH2RC505*7M300600
	VT750C2	JH2RC530*7M000794	JH2RC530*7M003910
	VT750C2L	JH2RC531*7M000044	JH2RC531*7M000422
	VT750C2F	JH2RC534*7M001007	JH2RC534*7M005133
	VT750C2F	JH2RC535*7M000067	JH2RC535*7M000515
	VTX1300C	1HFSC550*7A302231	1HFSC550*7A308830
	VTX1300CL	1HFSC551*7A300174	1HFSC551*7A300300
	VTX1300R	1HFSC526*7A404091	1HFSC526*7A411580
VTX1300RL	1HFSC527*7A400121	1HFSC527*7A400540	
VTX1300S	1HFSC520*7A404151	1HFSC520*7A410000	
VTX1300SL	1HFSC521*7A400161	1HFSC521*7A400480	
2008	VT750C	JH2RC500*8M400003	JH2RC500*8M401802
	VT750C	JH2RC500*8K410001	JH2RC500*8K410533
	VT750CL	JH2RC501*8M400003	JH2RC501*8M400183
	VT750CL	JH2RC501*8K410001	JH2RC501*8K410060
	VT750CA	JH2RC504*8M400002	JH2RC504*8M401801
	VT750CA	JH2RC504*8K410001	JH2RC504*8K410750
	VT750CAL	JH2RC505*8M400004	JH2RC505*8M400183
	VT750CAL	JH2RC505*8K410001	JH2RC505*8K410240
	VT750C2	JH2RC530*8M100001	JH2RC530*8M102580
	VT750C2	JH2RC530*8K110001	JH2RC530*8K110540
	VT750C2L	JH2RC531*8M100001	JH2RC531*8M100300
	VT750C2L	JH2RC531*8K110001	JH2RC531*8K110060
	VT750C2F	JH2RC534*8M100001	JH2RC534*8M102645
	VT750C2F	JH2RC534*8K110001	JH2RC534*8K110371
	VT750C2FL	JH2RC535*8M100001	JH2RC535*8M100300
	VT750C2FL	JH2RC535*8K110001	JH2RC535*8K110030
	VTX1300C	1HFSC550*8A400001	1HFSC550*8A400270
	VTX1300CL	1HFSC551*8A400001	1HFSC551*8A400071
	VTX1300R	1HFSC526*8A500001	1HFSC526*8A500331
	VTX1300RL	1HFSC527*8A500001	1HFSC527*8A500060
	VTX1300T	1HFSC52T*8A500001	1HFSC52T*8A500553
	VTX1300TL	1HFSC52N*8A500001	1HFSC52N*8A500065

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
08-0141	1	of	1	SERVICE

View Message

Sent on 03 26 2008 Expires on 04 02 2008
 From Motorcycle Service Management
 Subject VT/VTX RECALL: Status Report



Motorcycle Division

March 26, 2008

Dear Honda Motorcycle Dealer:

VT/VTX RECALL: Status Report

As communicated to you last week, American Honda (AHM) is conducting a **SAFETY RECALL** on affected motorcycles per the VIN list shown below. The **SAFETY RECALL** will correct a problem which may allow fuel to leak past the petcock diaphragm. Check the attached VIN list to determine model application.

Recall Information

The following information is provided to help you plan your business and wherever possible to minimize the impact this important action might have on your customers.

- ✓ A **Service Bulletin** describing the repair procedure and providing claim submission information will be posted on iN beginning April 3, 2008.
- ✓ **Parts** required to repair your inventory and allow you to resume sales will be automatically shipped to you beginning on April 4, 2008. You can expect arrival 1 to 2 days later.
 - Parts will be placed on open order immediately after the first shipment to dealers. The complete supply of **Parts** required to perform repairs on all motorcycles, your inventory and customer owned motorcycles, will arrive rapidly. We anticipate enough parts to complete all repairs will be here by April 19, 2008.
- ✓ **Customer letters** notifying registered owners of the Recall will be mailed on April 10, 2008.
- ✓ Any motorcycle shipped to you after March 20, 2008 will have been corrected prior to shipment, and may be immediately delivered to a customer.

Additional updates will be provided to you as more information becomes available.

Thank you for your cooperation.
 American Honda Motor Co., Inc.

Robert E. Clever
 Senior Manager – Service
 Motorcycle Division

(*) denotes check digit

VIN

Year	Model	From	To
2006	VT600C	JH2PC210*6M700001	JH2PC210*6M700544
	VT600C	JH2PC210*6K710001	JH2PC210*6K710918
	VT600CL	JH2PC211*6M700001	JH2PC211*6M700102
	VT600CL	JH2PC211*6K710001	JH2PC211*6K710068
	VT600CD	JH2PC214*6M700006	JH2PC214*6M702109
	VT600CD	JH2PC214*6K710001	JH2PC214*6K712006
	VT600CDL	JH2PC215*6M700005	JH2PC215*6M700341
	VT600CDL	JH2PC215*6K710001	JH2PC215*6K710170
2007	VT600C	JH2PC210*7M800001	JH2PC210*7M801157
	VT600C	JH2PC210*7K810001	JH2PC210*7K810408
	VT600CL	JH2PC211*7M800001	JH2PC211*7M800204
	VT600CD	JH2PC214*7M800001	JH2PC214*7M803604
	VT600CD	JH2PC214*7M820001	JH2PC214*7M821802
	VT600CD	JH2PC214*7K810001	JH2PC214*7K810884
	VT600CDL	JH2PC215*7M800001	JH2PC215*7M800374
	VT600CDL	JH2PC215*7M820001	JH2PC215*7M820170
	VT600CDL	JH2PC215*7K810001	JH2PC215*7K810068
	VT750C	JH2RC500*7K310001	JH2RC500*7K310930
	VT750CL	JH2RC501*7K310001	JH2RC501*7K310030
	VT750CA	JH2RC504*7M304329	JH2RC504*7M305408
	VT750CAL	JH2RC505*7M300481	JH2RC505*7M300600
	VT750C2	JH2RC530*7M000794	JH2RC530*7M003910
	VT750C2L	JH2RC531*7M000044	JH2RC531*7M000422
	VT750C2F	JH2RC534*7M001007	JH2RC534*7M005133
	VT750C2F	JH2RC535*7M000067	JH2RC535*7M000515
	VTX1300C	1HFSC550*7A302231	1HFSC550*7A308830
	VTX1300CL	1HFSC551*7A300174	1HFSC551*7A300300
	VTX1300R	1HFSC526*7A404091	1HFSC526*7A411580
VTX1300RL	1HFSC527*7A400121	1HFSC527*7A400540	
VTX1300S	1HFSC520*7A404151	1HFSC520*7A410000	
VTX1300SL	1HFSC521*7A400161	1HFSC521*7A400480	
2008	VT750C	JH2RC500*8M400003	JH2RC500*8M401802
	VT750C	JH2RC500*8K410001	JH2RC500*8K410533
	VT750CL	JH2RC501*8M400003	JH2RC501*8M400183
	VT750CL	JH2RC501*8K410001	JH2RC501*8K410060
	VT750CA	JH2RC504*8M400002	JH2RC504*8M401801
	VT750CA	JH2RC504*8K410001	JH2RC504*8K410750
	VT750CAL	JH2RC505*8M400004	JH2RC505*8M400183
	VT750CAL	JH2RC505*8K410001	JH2RC505*8K410240
	VT750C2	JH2RC530*8M100001	JH2RC530*8M102580
	VT750C2	JH2RC530*8K110001	JH2RC530*8K110540
	VT750C2L	JH2RC531*8M100001	JH2RC531*8M100300
	VT750C2L	JH2RC531*8K110001	JH2RC531*8K110060
	VT750C2F	JH2RC534*8M100001	JH2RC534*8M102645
	VT750C2F	JH2RC534*8K110001	JH2RC534*8K110371
	VT750C2FL	JH2RC535*8M100001	JH2RC535*8M100300
	VT750C2FL	JH2RC535*8K110001	JH2RC535*8K110030
	VTX1300C	1HFSC550*8A400001	1HFSC550*8A400270
	VTX1300CL	1HFSC551*8A400001	1HFSC551*8A400071
	VTX1300R	1HFSC526*8A500001	1HFSC526*8A500331
	VTX1300RL	1HFSC527*8A500001	1HFSC527*8A500060
VTX1300T	1HFSC52T*8A500001	1HFSC52T*8A500553	
VTX1300TL	1HFSC52N*8A500001	1HFSC52N*8A500065	

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
08-0151	1	of	1	SERVICE