

**Daimler Trucks  
North America LLC**

Daimler Trucks North America LLC  
P.O. Box 4090  
Portland, OR 97208-4090  
800.547.0712 Phone  
503.745.9009 Fax

**May 2008  
FL504H  
NHTSA #07V-302**

**Subject: Bendix SR-7 Park Brake Valves  
Additional Inspection**

This notice is to inform you of further inspection needed under recall FL504, Bendix SR-7 Park Brake Valves. Our records show that your vehicle was inspected and the SR-7 park brake valve required no additional work at that time.

The manufacturing date code range covered by the inspection has been revised, and your vehicle requires a second inspection to ensure the safety issue addressed by this recall has been corrected. The SR-7 valve will be inspected and the internal check valve cartridge will be replaced, if needed.

Please contact your authorized dealer to arrange to have this inspection performed. Refer to campaign number FL504H. The work will take approximately an hour and will be performed at no charge to you.

If you have questions, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address [WarrantyCampaigns@freightliner.com](mailto:WarrantyCampaigns@freightliner.com).

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure