

SERVICE

MC 08-08

April 18, 2008

**MODEL: 2006-2008 VULCAN® 900 CLASSIC (VN900B6F/L, B7F/L, B8F/L),
2007-2008 VULCAN® 900 CUSTOM (VN900C7F/L, C8F/L),
2006-2008 VULCAN® 900 CLASSIC LT (VN900D6F/L, D7F/L, D8F/L)**
TITLE: FUEL HOSE INSPECTION/REPLACEMENT

SERVICE INFORMATION

Subject

Kawasaki Motors Corp., U.S.A. recently issued Recall Service Bulletin MC 08-05, Fuel Hose Inspection/Replacement, for 2006-2008 Vulcan 900 models. When performing the Recall service, you should first inspect the fuel hose connection as outlined in the Recall Bulletin before ordering parts. Very few fuel hose connections have damaged locks, and pre-ordering parts often creates a back-order situation for those customers whose Vulcan 900 may actually have a damaged fuel hose connection lock.

Warranty Information

This bulletin is service information only, not warranty authorization.

File behind the "MC" tab in your Kawasaki
"Service and Warranty" binder.

© 2008 Kawasaki Motors Corp., U.S.A.

Kawasaki
Let the good times roll.™