

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Electric Auxiliary Coolant Pump Recall 12V-008, 2007-2011 R5x and R60 with N14 and N18 engines
Date: Monday, April 09, 2012 9:39:07 AM

Publish Date: April 09, 2012
From: Technical Service
Expiration Date: April 23, 2012

DCSnet Message 
Important

Subject: Electric Auxiliary Coolant Pump Recall 12V-008, 2007-2011 R5x and R60 with N14 and N18 engines

BMW of North America, LLC has determined that additional vehicle production was affected by auxiliary coolant pumps that were not manufactured correctly. Key Reader or DCS inquiry identification of these vehicles is expected by April 13.

Parts should only be ordered in small quantities as needed; large orders will be cancelled. Avoid overstocking of the Recall part numbers. Less than 1,500 vehicles are being added to the Recall nationwide.

The attached list of Questions and Answers has been prepared that should address most inquiries our customers may have. Please provide and discuss this information with your staff.

Sincerely,

BMW of North America, LLC

Technical Service Department

Attachments:  [MINI_12V-008QA_\(2\)\[80dd596d\].pdf](#)  [MINI_12V-008QA_\(2\)\[80dd596d\].pdf](#)

Recipients: MINI Passenger Cars, All Offerings, All Regions, All Areas, Service, All
MINI Passenger Cars, All Offerings, All Regions, All Areas, Parts, All