



ACURA

MEDIA INFORMATION

For more information:
Alison Sobkowski (310) 783-3396

For Immediate Release

**Statement by Acura Regarding
Power Steering Hose Recall: 2007-2008 Acura TL**

TORRANCE, Calif. – May 17, 2012 – Acura will voluntarily recall 52,615 model-year 2007-2008 TL sedans in the United States to replace the power steering hose. Over time, the power steering hose may deteriorate and develop a fluid leak. Leaking power steering fluid could lead to loss of power steering assistance or, if it leaks onto a catalytic converter it may result in smoke, or in the worst case, fire. No crashes, injuries or fires have been reported related to this issue.

Acura is announcing this recall to encourage owners of all affected vehicles to take their vehicles to an authorized dealer as soon as they receive notification of this recall from Acura. Mailed notification to customers will begin in mid-June 2012. In addition to contacting customers by mail, in mid-June, owners of these vehicles will be able to determine if their vehicles require repair by going on-line to www.recalls.acura.com or by calling (800) 382-2238, and selecting option 4.

###