

RECEIVED
By Recall Management Division at 8:17 am, Jun 29, 2012

Toyota Motor Engineering & Manufacturing North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

June 27, 2012

Ms. Nancy Lummen Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Ave, SE
Washington, D.C. 20590

Re: Recall # 12V-092
Certain Toyota Tacoma Spiral Cables
Part 573, Defect Information Report

Dear Ms. Lewis:

In connection with the above referenced matter, this supplements Toyota's letter of March 7, 2012. The affected vehicle VIN range and corresponding number of affected vehicles has been revised as indicated below.

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period	Population
			VDS	VIS		
Tacoma	2005 – 2009	TMMCA	#U##N	5Z001009 – 9Z625899	September 14, 2004 Through August 29, 2008	481,333
			#X##N	5Z001023 – 9Z625828		
		TMMBC	#U##N	5M001024 – 9M077844	October 19, 2004 through August 29, 2008	

Should you have any questions about this report, please contact me at (310) 468-8551.

Sincerely,



Vinnie Venugopal
General Manager
Toyota Motor Engineering & Manufacturing
North America, Inc.

cc: J. Timian