


RECALL DOCUMENT



RECALLED BY NAME: 05V455000

Artemis # : 05V455000

Record Created Date : 10-06-2005

Printed Date : 07/27/2012

Mfr Name : GENERAL MOTORS CORP.

Description : POWER STEERING HOSE

Document Type : Other Recall Related Documents

Print

Close

Ascender Power Steering Hose Safety Recall

05V-455

ISZA-FSO 10/06

Reported Condition:

Some 2006 Model Year GMT800, GMT360/370, GMT610, Hummer H2 and Y-Car vehicles have a high pressure power steering hose manufactured with an incorrect compound in the inner core / tube mix making the hose susceptible to high pressure failure.

The correction would consist of the dealership inspecting the power steering hose assemblies for the suspect codes, and to replace the suspect material with the new parts currently released for production.

Affected Vehicle:

1,085 2006 Isuzu Ascender built between 7/25/05 – 8/25/05
VIN 700001 - 701063

Affected Part:

8260950370 Hose, Power Steering

Schedule:

10/4/05?	NHTSA Notification
10/13/05 Thurs	All documents (TSB, Letter(s)) approved for release
10/14/05 Fri	Document forward to printers
10/17/05 Mon	Executive Internal Notification
10/18/05 Tues	Electronic Internal Notification
10/19/05 Wed	Electronic Dealer Executive Notification (GM 10/6)
10/20/05 Thurs	US Mail Bulletins/AWS Reports to Regions
10/20/05 Thurs	US Mail Bulletins/AWS Report to Dealers
10/28/05 Fri	Customer Notification (GM 10/14)

Action Item:

Dlr 28040 purchased suspect part 7/26/05. Will instruct dealer after launch of campaign to contact customer and inspect hose.