

November 6, 2012

INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

Mr. Frank S. Borris, II Director
Office of Defects Investigation
Enforcement
U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

Re: AQ12-001
Southern Honda Powersports

Dear Mr. Borris:

In response to your letter dated October 9, 2012, we are submitting the following:

- The three Information Requests as stated in your letter and our responses,
- Attachments 1 and 2, and
- A compact disc that contains an Excel file and Adobe Acrobat files referenced in our responses

INFORMATION REQUESTS

1. Separately, for each of the motorcycles identified by VIN in Attachment A, provide the following information:
 - a. State whether the motorcycle was included in the recall under which it is listed in Attachment A; and
 - b. If the motorcycle was included in the recall under which it is listed in Attachment A:
 - i. State whether the recall remedy was performed on that motorcycle;
 - ii. State whether the recall remedy was performed before the motorcycle was delivered to Southern Honda Powersports;
 - iii. State the date on which the recall remedy was performed on the motorcycle;
 - iv. State the identity of the entity that performed the recall remedy on the motorcycle;
 - v. State the date the motorcycle was delivered to Southern Honda Powersports;
 - vi. State the date the motorcycle was sold by Southern Honda Powersports;
 - vii. State the date the motorcycle was delivered to the purchaser by Southern Honda Powersports; and
 - viii. State the date warranty coverage began.

Please provide your responses in a spreadsheet table in either Microsoft Access or Excel, version 2007 or later.

Response:

The enclosed compact disc contains an Excel version 2007 file that provides the requested information for the 292 VINs. A printed copy of the Excel file is also provided as Attachment 1.

On Attachment 1, the date on which the recall remedy was performed (item iii) for 13 motorcycles is marked with an asterisk (). The asterisk denotes that the exact date the recall remedy was performed was not available; therefore, the date displayed is the date on which the unit was no longer being held for warehouse modification and was transferred to American Honda Motor Co., Inc.'s (AHM) saleable inventory.*

Sources: Warehouse lists and VIN Product Data
As of: October 24, 2012

2. **Produce copies of documents, organized by recall and by VIN, that evidence, substantiate, or are otherwise related to your responses to Information Request No. 1.**

Response:

The sources for information responsive to items i, ii, iii, and iv in Information Request No. 1 are Honda warehouse lists. These lists document the affected VINs that were in a Honda warehouse at the time a recall was launched, and the dates the recall inspection and remedies were performed by AHM or Honda Motor Co., Ltd. (HMC) on the units. The warehouse lists that provided information responsive to Information Request No. 1 are as follows:

- *07V-576 / Q67 warehouse list (warehouse 30)*
- *08V-141 / Q75 warehouse list (warehouse 10, 30, 50, and 90)*
- *09V-174 / R08 warehouse list (warehouse 30 and 50)*
- *10V-369 / R41 warehouse list (warehouse 30)*
- *11V-356 / R86 warehouse list (warehouse 30)*
- *11V-567 / S03 warehouse list (warehouse 30 and 90)*

Copies of these warehouse lists are provided as pdf files on the enclosed compact disc. For ease of identification, the VINs pertinent to this Audit Query are highlighted.

Information responsive to items v, vi, vii, and viii in Information Request No. 1 was obtained from the Honda VIN Product Data application. Screen shots of the VIN Product Data application for each of the 292 VINs are provided in a pdf file on the enclosed compact disc. Please note that the information responsive to items vi, vii, and viii was provided to AHM by the dealer (Southern Honda Powersports) via AHM's unit sales and warranty registration reporting processes; AHM does not have any independent information about sales, delivery, and warranty start dates.

Source: Warehouse lists and VIN Product Data
As of: October 24, 2012

3. **Separately, for each of the six recalls identified in Attachment A, and for recall 11V-310, state when Honda provided to Southern Honda Powersports notification of the recall.**

Response:

For the six recalls identified in Attachment A and recall 11V-310, initial and reminder recall notifications were electronically sent through the Honda Interactive Network (iN) to authorized Honda motorcycle dealers, including Southern Honda Powersports. The

dates on which the initial iN recall notifications were issued are listed in the table on the following page.

NHTSA ID	Honda Campaign	Initial Recall Notification Date
07V-576	Q67	11/27/2007
08V-141	Q75	3/19/2008
09V-174	R08	5/21/2009
10V-369	R41	8/11/2010
11V-310	R80	6/1/2011
11V-356	R86	7/6/2011
11V-567	S03	12/2/2011

For your convenience, copies of the initial iN recall notifications for these campaigns are enclosed as Attachment 2.

Source(s): Interactive Network notices
As of: October 1, 2012

If you have any questions or require further clarification on the submitted information, please contact me or James Jongkind at telephone number (310) 783-3402.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



Jay Joseph
Senior Manager
Product Regulatory Office

JWJ:dj

Enclosures

cc: John Piazza, Office of Chief Counsel

Attachment 1

Information for VINs

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
07V-576	JH2SC57017M	Yes	Yes	Yes	12/7/2007	AHM / HMC	12/15/2008	3/14/2009	3/14/2009	3/14/2009
08V-141	1HFSC55037	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	9/2/2009	9/2/2009	9/2/2009
08V-141	1HFSC55047	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	10/28/2011	10/28/2011	10/28/2011
08V-141	1HFSC55017	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	3/21/2009	3/21/2009	3/21/2009
08V-141	1HFSC55057	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	5/24/2008	5/24/2008	5/24/2008
08V-141	1HFSC55097	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	5/24/2008	5/24/2008	5/24/2008
08V-141	1HFSC55087	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/15/2008	6/20/2009	6/20/2009	6/20/2009
08V-141	1HFSC55057	Yes	Yes	Yes	3/31/2008	AHM / HMC	5/13/2008	6/14/2008	6/14/2008	6/14/2008
08V-141	1HFSC55057	Yes	Yes	Yes	4/7/2008	AHM / HMC	5/13/2008	6/11/2008	6/11/2008	6/11/2008
08V-141	1HFSC550X7	Yes	Yes	Yes	4/17/2008*	AHM / HMC	7/2/2008	3/27/2010	3/27/2010	3/27/2010
08V-141	1HFSC55047	Yes	Yes	Yes	4/7/2008	AHM / HMC	5/28/2008	6/23/2008	6/23/2008	6/23/2008
08V-141	1HFSC55067	Yes	Yes	Yes	3/25/2008	AHM / HMC	6/17/2008	9/18/2010	9/18/2010	9/18/2010
08V-141	1HFSC55057	Yes	Yes	Yes	3/25/2008	AHM / HMC	6/17/2008	8/22/2008	8/22/2008	8/22/2008
08V-141	1HFSC55007	Yes	Yes	Yes	3/25/2008	AHM / HMC	6/17/2008	7/24/2008	7/24/2008	7/24/2008
08V-141	1HFSC55087	Yes	Yes	Yes	3/25/2008	AHM / HMC	6/17/2008	10/30/2010	10/30/2010	10/30/2010
08V-141	1HFSC55017	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	7/19/2008	7/19/2008	7/19/2008
08V-141	1HFSC55057	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/18/2008	8/30/2008	8/30/2008	8/30/2008
08V-141	1HFSC55007	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	8/16/2008	8/16/2008	8/16/2008
08V-141	1HFSC55047	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	10/2/2010	10/2/2010	10/2/2010
08V-141	1HFSC55067	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/18/2008	3/12/2011	3/12/2011	3/12/2011
08V-141	1HFSC55027	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	3/3/2011	3/3/2011	3/3/2011
08V-141	1HFSC55087	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	11/11/2010	11/11/2010	11/11/2010
08V-141	1HFSC55057	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	7/12/2008	7/12/2008	7/12/2008
08V-141	1HFSC55007	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	7/12/2011	7/12/2011	7/12/2011
08V-141	1HFSC55007	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	7/7/2008	7/7/2008	7/7/2008
08V-141	1HFSC55027	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/11/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	1HFSC55027	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/11/2008	5/31/2008	5/31/2008	5/31/2008
08V-141	1HFSC55017	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	5/29/2010	5/29/2010	5/29/2010
08V-141	1HFSC55097	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/11/2008	5/29/2008	5/29/2008	5/29/2008
08V-141	1HFSC55017	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/17/2008	7/17/2008	7/17/2008
08V-141	1HFSC55047	Yes	Yes	Yes	4/21/2008	AHM / HMC	6/30/2008	12/15/2010	12/15/2010	12/15/2010
08V-141	1HFSC55087	Yes	Yes	Yes	4/21/2008	AHM / HMC	7/31/2008	7/8/2010	7/8/2010	7/8/2010

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
08V-141	1HFSC55057	Yes	Yes	Yes	4/21/2008	AHM / HMC	6/30/2008	10/23/2010	10/23/2010	10/23/2010
08V-141	1HFSC55097	Yes	Yes	Yes	4/21/2008	AHM / HMC	6/30/2008	3/5/2011	3/5/2011	3/5/2011
08V-141	1HFSC55057	Yes	Yes	Yes	4/3/2008	AHM / HMC	12/17/2008	8/3/2010	8/3/2010	8/3/2010
08V-141	1HFSC55067	Yes	Yes	Yes	4/3/2008	AHM / HMC	5/28/2008	7/3/2008	7/3/2008	7/3/2008
08V-141	1HFSC55017	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	12/31/2010	12/31/2010	12/31/2010
08V-141	1HFSC55077	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/30/2010	7/30/2010	7/30/2010
08V-141	1HFSC55047	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/10/2009	7/10/2009	7/10/2009
08V-141	1HFSC55047	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/19/2008	7/19/2008	7/19/2008
08V-141	1HFSC55037	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	11/6/2008	11/6/2008	11/6/2008
08V-141	1HFSC55057	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/26/2008	7/26/2008	7/26/2008
08V-141	1HFSC55007	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	10/29/2010	10/29/2010	10/29/2010
08V-141	1HFSC55027	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	8/22/2008	8/22/2008	8/22/2008
08V-141	1HFSC55047	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	8/29/2009	8/29/2009	8/29/2009
08V-141	1HFSC550X7	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	10/20/2008	10/20/2008	10/20/2008
08V-141	1HFSC55027	Yes	Yes	Yes	4/21/2008	AHM / HMC	7/31/2008	9/30/2010	9/30/2010	9/30/2010
08V-141	1HFSC55047	Yes	Yes	Yes	4/3/2008	AHM / HMC	5/28/2008	6/23/2008	6/23/2008	6/23/2008
08V-141	1HFSC55037	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/18/2008	7/11/2009	7/11/2009	7/11/2009
08V-141	1HFSC55057	Yes	Yes	Yes	4/3/2008	AHM / HMC	5/28/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	1HFSC55057	Yes	Yes	Yes	3/18/2008	AHM / HMC	7/3/2008	9/30/2010	9/30/2010	9/30/2010
08V-141	1HFSC52097	Yes	Yes	Yes	3/31/2008	AHM / HMC	6/23/2008	8/1/2008	8/1/2008	8/1/2008
08V-141	1HFSC52067	Yes	Yes	Yes	3/31/2008	AHM / HMC	6/23/2008	7/15/2008	7/15/2008	7/15/2008
08V-141	1HFSC52057	Yes	Yes	Yes	4/7/2008*	AHM / HMC	8/5/2008	5/19/2012	5/19/2012	5/19/2012
08V-141	1HFSC52027	Yes	Yes	Yes	3/31/2008*	AHM / HMC	7/31/2008	4/15/2011	4/15/2011	4/15/2011
08V-141	1HFSC52087	Yes	Yes	Yes	3/31/2008	AHM / HMC	7/31/2008	6/17/2011	6/17/2011	6/17/2011
08V-141	1HFSC52087	Yes	Yes	Yes	3/31/2008	AHM / HMC	7/31/2008	7/1/2011	7/1/2011	7/1/2011
08V-141	1HFSC52627	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	4/11/2009	4/11/2009	4/11/2009
08V-141	1HFSC52097	Yes	Yes	Yes	4/15/2008	AHM / HMC	7/31/2008	6/16/2011	6/16/2011	6/16/2011
08V-141	1HFSC52097	Yes	Yes	Yes	3/24/2008	AHM / HMC	7/30/2008	4/9/2011	4/9/2011	4/9/2011
08V-141	1HFSC52637	Yes	Yes	Yes	4/21/2008*	AHM / HMC	6/23/2008	6/5/2009	6/5/2009	6/5/2009
08V-141	1HFSC52607	Yes	Yes	Yes	4/21/2008*	AHM / HMC	6/23/2008	1/21/2012	1/21/2012	1/21/2012
08V-141	1HFSC52617	Yes	Yes	Yes	4/3/2008*	AHM / HMC	4/9/2008	8/9/2008	8/9/2008	8/9/2008
08V-141	1HFSC52677	Yes	Yes	Yes	4/3/2008	AHM / HMC	4/9/2008	8/2/2008	8/2/2008	8/2/2008

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
08V-141	1HFSC52067A	Yes	Yes	Yes	4/14/2008	AHM / HMC	7/31/2008	1/24/2012	1/24/2012	1/24/2012
08V-141	1HFSC52027A	Yes	Yes	Yes	4/14/2008	AHM / HMC	7/31/2008	12/2/2011	12/2/2011	12/2/2011
08V-141	1HFSC52017A	Yes	Yes	Yes	4/14/2008	AHM / HMC	7/31/2008	3/26/2011	3/26/2011	3/26/2011
08V-141	1HFSC52007A	Yes	Yes	Yes	4/14/2008	AHM / HMC	7/31/2008	6/11/2011	6/11/2011	6/11/2011
08V-141	1HFSC52037A	Yes	Yes	Yes	4/7/2008*	AHM / HMC	8/5/2008	6/20/2011	6/20/2011	6/20/2011
08V-141	1HFSC52057A	Yes	Yes	Yes	4/7/2008*	AHM / HMC	8/5/2008	3/17/2012	3/17/2012	3/17/2012
08V-141	1HFSC52637A	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	1HFSC52617A	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	8/14/2008	8/14/2008	8/14/2008
08V-141	1HFSC52637A	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	12/31/2008	12/31/2008	12/31/2008
08V-141	1HFSC52087A	Yes	Yes	Yes	4/22/2008	AHM / HMC	7/29/2008	9/17/2011	9/17/2011	9/17/2011
08V-141	1HFSC52617A	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	1HFSC52667A	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/14/2008	6/14/2008	6/14/2008
08V-141	1HFSC52687A	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/30/2008	6/30/2008	6/30/2008
08V-141	1HFSC52637A	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	7/25/2008	7/25/2008	7/25/2008
08V-141	1HFSC52667A	Yes	Yes	Yes	3/28/2008	AHM / HMC	4/3/2008	8/9/2008	8/9/2008	8/9/2008
08V-141	1HFSC52667A	Yes	Yes	Yes	3/28/2008	AHM / HMC	4/3/2008	8/14/2008	8/14/2008	8/14/2008
08V-141	1HFSC52687A	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	8/9/2008	8/9/2008	8/9/2008
08V-141	1HFSC52687A	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	7/1/2008	7/1/2008	7/1/2008
08V-141	1HFSC526X7A	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	6/18/2008	6/18/2008	6/18/2008
08V-141	1HFSC52617A	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	12/9/2009	12/9/2009	12/9/2009
08V-141	1HFSC52047A	Yes	Yes	Yes	4/14/2008	AHM / HMC	7/31/2008	9/3/2011	9/3/2011	9/3/2011
08V-141	1HFSC52027A	Yes	Yes	Yes	4/7/2008*	AHM / HMC	8/5/2008	10/15/2011	10/15/2011	10/15/2011
08V-141	1HFSC52697A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	7/28/2009	7/28/2009	7/28/2009
08V-141	1HFSC52607A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	6/17/2010	6/17/2010	6/17/2010
08V-141	1HFSC52627A	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	7/7/2008	7/7/2008	7/7/2008
08V-141	1HFSC52667A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/9/2008	7/5/2008	7/5/2008	7/5/2008
08V-141	1HFSC52657A	Yes	Yes	Yes	4/2/2008	AHM / HMC	4/9/2008	7/7/2008	7/7/2008	7/7/2008
08V-141	1HFSC52667A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/9/2008	8/11/2008	8/11/2008	8/11/2008
08V-141	1HFSC52687A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/9/2008	7/5/2008	7/5/2008	7/5/2008
08V-141	1HFSC52617A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/11/2008	6/8/2011	6/8/2011	6/8/2011
08V-141	1HFSC52677A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/11/2008	10/8/2010	10/8/2010	10/8/2010
08V-141	1HFSC52697A	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	11/26/2010	11/26/2010	11/26/2010

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
08V-141	1HFSC52627	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/11/2008	12/27/2010	12/27/2010	12/27/2010
08V-141	1HFSC52647	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	7/29/2008	7/29/2008	7/29/2008
08V-141	1HFSC52617	Yes	Yes	Yes	3/20/2008	AHM / HMC	4/3/2008	7/11/2008	7/11/2008	7/11/2008
08V-141	1HFSC52607	Yes	Yes	Yes	3/20/2008	AHM / HMC	4/3/2008	6/5/2008	6/5/2008	6/5/2008
08V-141	1HFSC52647	Yes	Yes	Yes	3/20/2008	AHM / HMC	4/3/2008	6/14/2008	6/14/2008	6/14/2008
08V-141	1HFSC52627	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	12/1/2010	12/1/2010	12/1/2010
08V-141	1HFSC52667	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	6/20/2009	6/20/2009	6/20/2009
08V-141	1HFSC526X7	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	8/20/2008	8/20/2008	8/20/2008
08V-141	1HFSC52657	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	6/16/2009	6/16/2009	6/16/2009
08V-141	1HFSC52637	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/9/2008	8/2/2008	8/2/2008	8/2/2008
08V-141	1HFSC52617	Yes	Yes	Yes	3/28/2008	AHM / HMC	4/9/2008	4/27/2009	4/27/2009	4/27/2009
08V-141	1HFSC52687	Yes	Yes	Yes	3/20/2008	AHM / HMC	4/3/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	1HFSC52617	Yes	Yes	Yes	3/20/2008	AHM / HMC	4/3/2008	9/1/2008	9/1/2008	9/1/2008
08V-141	1HFSC526X7	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	6/25/2008	6/25/2008	6/25/2008
08V-141	1HFSC52677	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	6/23/2008	6/23/2008	6/23/2008
08V-141	1HFSC526X7	Yes	Yes	Yes	3/19/2008	AHM / HMC	4/3/2008	7/9/2008	7/9/2008	7/9/2008
08V-141	1HFSC52637	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	8/23/2008	8/23/2008	8/23/2008
08V-141	1HFSC52647	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	6/20/2008	6/20/2008	6/20/2008
08V-141	1HFSC52607	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	8/9/2008	8/9/2008	8/9/2008
08V-141	1HFSC52627	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	8/15/2008	8/15/2008	8/15/2008
08V-141	1HFSC52687	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	9/3/2008	9/3/2008	9/3/2008
08V-141	1HFSC52677	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/3/2008	8/13/2008	8/13/2008	8/13/2008
08V-141	1HFSC52697	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/3/2008	6/20/2008	6/20/2008	6/20/2008
08V-141	1HFSC52607	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/3/2008	8/1/2008	8/1/2008	8/1/2008
08V-141	1HFSC52617	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/3/2008	10/18/2008	10/18/2008	10/18/2008
08V-141	1HFSC52697	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	11/10/2008	11/10/2008	11/10/2008
08V-141	1HFSC52647	Yes	Yes	Yes	3/25/2008	AHM / HMC	4/3/2008	5/16/2009	5/16/2009	5/16/2009
08V-141	1HFSC52637	Yes	Yes	Yes	3/26/2008	AHM / HMC	4/9/2008	6/25/2008	6/25/2008	6/25/2008
08V-141	1HFSC52637	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/16/2008	6/16/2008	6/16/2008
08V-141	1HFSC52697	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/23/2008	6/23/2008	6/23/2008
08V-141	1HFSC52697	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	1HFSC52657	Yes	Yes	Yes	3/21/2008	AHM / HMC	4/3/2008	7/3/2008	7/3/2008	7/3/2008

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
08V-141	JH2RC53577M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/14/2008	7/14/2008	7/14/2008
08V-141	JH2RC53547M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/19/2008	7/19/2008	7/19/2008
08V-141	JH2RC53537M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/23/2008	7/23/2008	7/23/2008
08V-141	JH2RC53517M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/11/2008	7/11/2008	7/11/2008
08V-141	JH2RC53597M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/19/2008	7/19/2008	7/19/2008
08V-141	JH2RC53507M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	2/17/2009	2/17/2009	2/17/2009
08V-141	JH2RC53527M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/18/2008	7/18/2008	7/18/2008
08V-141	JH2RC53507M	Yes	Yes	Yes	4/9/2008	AHM / HMC	6/11/2008	7/12/2008	7/12/2008	7/12/2008
08V-141	JH2PC21497M	Yes	Yes	Yes	4/3/2008*	AHM / HMC	5/13/2008	6/13/2008	6/13/2008	6/13/2008
08V-141	JH2PC21477M	Yes	Yes	Yes	4/3/2008*	AHM / HMC	5/13/2008	5/31/2008	5/31/2008	5/31/2008
08V-141	JH2PC21407M	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/18/2008	7/15/2008	7/15/2008	7/15/2008
08V-141	JH2PC21407M	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/17/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	JH2PC21437M	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/9/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	JH2PC21477M	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/9/2008	7/2/2008	7/2/2008	7/2/2008
08V-141	JH2PC21417M	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/9/2008	7/14/2008	7/14/2008	7/14/2008
08V-141	JH2PC21407M	Yes	Yes	Yes	4/2/2008	AHM / HMC	6/9/2008	6/17/2008	6/17/2008	6/17/2008
08V-141	JH2RC53158M	Yes	Yes	Yes	4/8/2008	AHM / HMC	6/30/2008	7/2/2011	7/2/2011	7/2/2011
08V-141	JH2RC53438M	Yes	Yes	Yes	4/23/2008*	AHM / HMC	8/25/2009	9/17/2009	9/17/2009	9/17/2009
08V-141	JH2RC50028M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/30/2008	6/30/2008	6/30/2008
08V-141	JH2RC50018M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	JH2RC50038M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	JH2RC50058M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	7/3/2008	7/3/2008	7/3/2008
08V-141	JH2RC50078M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/14/2008	6/14/2008	6/14/2008
08V-141	JH2RC50098M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/27/2008	6/27/2008	6/27/2008
08V-141	JH2RC50008M	Yes	Yes	Yes	4/3/2008	AHM / HMC	6/2/2008	6/28/2008	6/28/2008	6/28/2008
08V-141	JH2RC50008M	Yes	Yes	Yes	3/28/2008	AHM / HMC	6/2/2008	6/21/2008	6/21/2008	6/21/2008
08V-141	JH2RC530X8M	Yes	Yes	Yes	4/7/2008	AHM / HMC	8/27/2008	5/18/2011	5/18/2011	5/18/2011
08V-141	JH2RC53078M	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	6/30/2011	6/30/2011	6/30/2011
08V-141	JH2RC53088M	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	4/29/2009	4/29/2009	4/29/2009
08V-141	JH2RC53008M	Yes	Yes	Yes	3/31/2008	AHM / HMC	6/6/2008	6/23/2008	6/23/2008	6/23/2008
08V-141	JH2RC53038M	Yes	Yes	Yes	3/31/2008	AHM / HMC	6/6/2008	9/5/2008	9/5/2008	9/5/2008
08V-141	JH2RC53008M	Yes	Yes	Yes	3/31/2008	AHM / HMC	6/6/2008	8/9/2008	8/9/2008	8/9/2008

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (vii)
08V-141	JH2RC53028N	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	7/24/2008	7/24/2008	7/24/2008
08V-141	JH2RC53048N	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	7/5/2008	7/5/2008	7/5/2008
08V-141	JH2RC53068N	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	7/25/2008	7/25/2008	7/25/2008
08V-141	JH2RC530X8N	Yes	Yes	Yes	4/7/2008	AHM / HMC	6/6/2008	7/8/2008	7/8/2008	7/8/2008
08V-141	JH2RC504X8N	Yes	Yes	Yes	4/16/2008*	AHM / HMC	4/22/2008	9/6/2008	9/6/2008	9/6/2008
08V-141	JH2RC50038N	Yes	Yes	Yes	3/31/2008	AHM / HMC	5/14/2008	7/5/2008	7/5/2008	7/5/2008
08V-141	JH2RC50028N	Yes	Yes	Yes	3/31/2008	AHM / HMC	5/14/2008	7/2/2008	7/2/2008	7/2/2008
09V-174	JH2SC59048N	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	3/3/2010	3/3/2010	3/3/2010
09V-174	JH2SC59038N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/18/2010	3/18/2010	3/18/2010
09V-174	JH2SC59058N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	1/30/2010	1/30/2010	1/30/2010
09V-174	JH2SC59078N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/27/2010	2/27/2010	2/27/2010
09V-174	JH2SC59048N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC59008N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/19/2010	3/19/2010	3/19/2010
09V-174	JH2SC59028N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/3/2010	3/3/2010	3/3/2010
09V-174	JH2SC59068N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/15/2010	2/15/2010	2/15/2010
09V-174	JH2SC59018N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/20/2010	2/20/2010	2/20/2010
09V-174	JH2SC59078N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/6/2010	2/6/2010	2/6/2010
09V-174	JH2SC59088N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/22/2010	2/22/2010	2/22/2010
09V-174	JH2SC59018N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	1/23/2010	1/23/2010	1/23/2010
09V-174	JH2SC59098N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/24/2010	2/24/2010	2/24/2010
09V-174	JH2SC59068N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/26/2010	2/26/2010	2/26/2010
09V-174	JH2SC590X8N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	1/30/2010	1/30/2010	1/30/2010
09V-174	JH2SC59058N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	10/13/2009	10/13/2009	10/13/2009
09V-174	JH2SC59068N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/18/2010	2/18/2010	2/18/2010
09V-174	JH2SC590X8N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/11/2010	3/11/2010	3/11/2010
09V-174	JH2SC59098N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/12/2010	3/12/2010	3/12/2010
09V-174	JH2SC59008N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC59048N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/15/2010	2/15/2010	2/15/2010
09V-174	JH2SC59068N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	2/13/2010	2/13/2010	2/13/2010
09V-174	JH2SC59048N	Yes	Yes	Yes	6/8/2009	AHM / HMC	9/25/2009	3/2/2010	3/2/2010	3/2/2010
09V-174	JH2SC59028N	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/11/2010	3/11/2010	3/11/2010
09V-174	JH2SC59038N	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/4/2010	3/4/2010	3/4/2010

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
09V-174	JH2SC59078M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/5/2010	3/5/2010	3/5/2010
09V-174	JH2SC59028M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/4/2010	3/4/2010	3/4/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/9/2010	3/9/2010	3/9/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/16/2009	10/16/2009	10/16/2009
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/27/2009	10/27/2009	10/27/2009
09V-174	JH2SC59078M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	11/2/2009	11/2/2009	11/2/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	11/11/2009	11/11/2009	11/11/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/31/2009	10/31/2009	10/31/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/24/2009	10/24/2009	10/24/2009
09V-174	JH2SC59078M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	9/19/2009	9/19/2009	9/19/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/14/2009	10/14/2009	10/14/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/13/2009	10/13/2009	10/13/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/3/2009	10/21/2009	10/21/2009	10/21/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/23/2009	10/23/2009	10/23/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	9/17/2009	9/17/2009	9/17/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/24/2009	10/24/2009	10/24/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	11/6/2009	11/6/2009	11/6/2009
09V-174	JH2SC59028M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/31/2009	10/31/2009	10/31/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/14/2009	10/14/2009	10/14/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	11/21/2009	11/21/2009	11/21/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	3/27/2010	3/27/2010	3/27/2010
09V-174	JH2SC59038M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	2/6/2010	2/6/2010	2/6/2010
09V-174	JH2SC59048M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	3/8/2010	3/8/2010	3/8/2010
09V-174	JH2SC590X8M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	2/1/2010	2/1/2010	2/1/2010
09V-174	JH2SC59008M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	12/3/2009	12/3/2009	12/3/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	2/4/2010	2/4/2010	2/4/2010
09V-174	JH2SC59018M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/14/2009	11/14/2009	11/14/2009

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	12/30/2009	12/30/2009	12/30/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/28/2009	11/28/2009	11/28/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/30/2009	10/30/2009	10/30/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/30/2009	10/30/2009	10/30/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	9/29/2009	9/29/2009	9/29/2009
09V-174	JH2SC59028M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/16/2009	10/16/2009	10/16/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/3/2009	10/3/2009	10/3/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/1/2009	10/1/2009	10/1/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/29/2009	9/29/2009	9/29/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/25/2009	9/25/2009	9/25/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	10/3/2009	10/3/2009	10/3/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/23/2009	9/23/2009	9/23/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	12/31/2009	12/31/2009	12/31/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/3/2009	AHM / HMC	9/14/2009	10/27/2009	10/27/2009	10/27/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/22/2009	9/22/2009	9/22/2009
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	10/6/2009	10/6/2009	10/6/2009
09V-174	JH2SC59048M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	10/31/2009	10/31/2009	10/31/2009
09V-174	JH2SC59028M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/19/2009	9/19/2009	9/19/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/15/2009	9/23/2009	9/23/2009	9/23/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	2/3/2010	2/3/2010	2/3/2010
09V-174	JH2SC59018M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	11/27/2009	11/27/2009	11/27/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	3/4/2010	3/4/2010	3/4/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	2/26/2010	2/26/2010	2/26/2010
09V-174	JH2SC59048M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	2/27/2010	2/27/2010	2/27/2010
09V-174	JH2SC590X8M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	10/9/2009	10/9/2009	10/9/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	2/27/2010	2/27/2010	2/27/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	3/20/2010	3/20/2010	3/20/2010
09V-174	JH2SC59038M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/4/2009	11/4/2009	11/4/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	2/15/2010	2/15/2010	2/15/2010
09V-174	JH2SC59038M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/27/2009	11/27/2009	11/27/2009
09V-174	JH2SC59048M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/26/2009	10/26/2009	10/26/2009

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
09V-174	JH2SC59028M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/24/2009	10/24/2009	10/24/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	12/23/2009	12/23/2009	12/23/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/15/2009	10/15/2009	10/15/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	12/5/2009	12/5/2009	12/5/2009
09V-174	JH2SC59078M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	2/12/2010	2/12/2010	2/12/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/14/2009	11/14/2009	11/14/2009
09V-174	JH2SC59078M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/29/2009	10/29/2009	10/29/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/16/2009	11/16/2009	11/16/2009
09V-174	JH2SC59028M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC59048M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/15/2009	10/15/2009	10/15/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/3/2009	10/3/2009	10/3/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/10/2009	10/10/2009	10/10/2009
09V-174	JH2SC590X8M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	12/4/2009	12/4/2009	12/4/2009
09V-174	JH2SC59018M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	12/31/2009	12/31/2009	12/31/2009
09V-174	JH2SC59088M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/7/2009	10/7/2009	10/7/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	10/23/2009	10/23/2009	10/23/2009
09V-174	JH2SC59068M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	2/2/2010	2/2/2010	2/2/2010
09V-174	JH2SC59018M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	11/2/2009	11/2/2009	11/2/2009
09V-174	JH2SC59038M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/3/2009	10/17/2009	10/17/2009	10/17/2009
09V-174	JH2SC59078M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/20/2010	3/20/2010	3/20/2010
09V-174	JH2SC59008M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/4/2010	3/4/2010	3/4/2010
09V-174	JH2SC59088M	Yes	Yes	Yes	6/4/2009	AHM / HMC	9/3/2009	11/6/2009	11/6/2009	11/6/2009
09V-174	JH2SC59058M	Yes	Yes	Yes	6/2/2009	AHM / HMC	9/14/2009	3/8/2010	3/8/2010	3/8/2010
09V-174	JH2SC59018M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	1/16/2010	1/16/2010	1/16/2010
09V-174	JH2SC59098M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	12/29/2009	12/29/2009	12/29/2009
09V-174	JH2SC59008M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	3/4/2010	3/4/2010	3/4/2010
09V-174	JH2SC59018M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	12/19/2009	12/19/2009	12/19/2009
09V-174	JH2SC59098M	Yes	Yes	Yes	5/19/2009	AHM / HMC	9/22/2009	2/6/2010	2/6/2010	2/6/2010
10V-369	JH2SC6675A	Yes	Yes	Yes	8/13/2010	AHM / HMC	9/13/2010	5/30/2011	5/30/2011	5/30/2011
11V-356	JH2SC5100A	Yes	Yes	Yes	7/26/2011	AHM / HMC	8/4/2011	9/17/2011	9/17/2011	9/17/2011
11V-567	JH2SC68M5C	Yes	Yes	Yes	1/10/2012	AHM / HMC	1/16/2012	2/18/2012	2/18/2012	2/18/2012

* Date VIN was transferred to AHM saleable inventory

Recall	VIN	Included in Recall (a)	Remedy Performed (i)	Before Delivery to SHP (ii)	Date Remedy Performed (iii)	Entity that Performed Remedy (iv)	Date Sold to SHP (v)	Date Sold by SHP (vi)	Date Delivered by SHP (vii)	Warranty Start Date (viii)
11V-567	JH2SC68L6CK	Yes	Yes	Yes	1/10/2012	AHM / HMC	1/16/2012	4/28/2012	4/28/2012	4/28/2012
11V-567	JH2SC68H5CK	Yes	Yes	Yes	12/21/2011	AHM / HMC	1/9/2012	6/9/2012	6/9/2012	6/9/2012
11V-567	JH2SC68H3CK	Yes	Yes	Yes	1/11/2012	AHM / HMC	2/6/2012	5/1/2012	5/1/2012	5/1/2012
11V-567	JH2SC68H2CK	Yes	Yes	Yes	1/10/2012	AHM / HMC	2/6/2012	6/15/2012	6/15/2012	6/15/2012

Attachment 2

Recall Notifications



November 27, 2007

Dear Honda Motorcycle Dealer:

SERVICE ACTION NOTICE

AFFECTED UNITS: All 2006-2007 CBR1000RR Motorcycles

American Honda is conducting a **SERVICE ACTION** on affected models per the description above. The action will correct a problem that may exist in the brazed portion of the air vent pipe in the bottom of the fuel tank of 2006-2007 CBR1000RR motorcycles. In limited circumstances cracking could occur due to fatigue, resulting in fuel leakage.

Effective immediately **YOU MUST NOT SELL** any affected model in your inventory until the required repair has been completed. Please make sure **ALL DEPARTMENTS** in your dealership – Parts, Sales, and Service – are made aware of this action.

The instructions, procedures, and parts necessary to repair affected motorcycles will be made available to your dealership as soon as possible. Date specific information as to each of these items will be sent to you the week of December 10, 2007.

If you have recently sold an affected model, please submit the warranty registration information. If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Thank you for your cooperation.
American Honda Motor Co., Inc.

Robert E. Clever
Senior Manager – Service
Motorcycle Division

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
07-0772	1	of	1	SERVICE

Next Unread Message

View Message

Sent on 03 19 2008 Expires on 03 30 2008
 From Motorcycle Service Management
 Subject STOP SALE: Fuel Leakage SAFETY RECALL



Motorcycle Division

March 19, 2008

Dear Honda Motorcycle Dealer:

RECALL and STOP SALE NOTICE

AFFECTED UNITS: (see model/VIN list below)

VT600C 2006-2008 VT600CD 2006-2008 VT750C 2007-2008
VT750C2 2007-2008 VTX1300C 2007-2008 VTX1300R 2007-2008

American Honda (AHM) is conducting a **SAFETY RECALL** on affected motorcycles per the model and VIN list below. The **SAFETY RECALL** will correct a problem that may exist in some motorcycles which could allow fuel to leak past the petcock diaphragm. Leakage of this type would negatively affect engine operation, vehicle emissions, and under certain circumstance could present a fire hazard.

Effective immediately **YOU MUST NOT SELL** any affected model in your inventory until the required repair has been completed. Please make sure ALL DEPARTMENTS in your dealership; Parts, Sales, and Service are made aware of this action.

Information including instructions, procedures, and parts delivery schedule to repair affected motorcycles will be made available to your dealership as soon as possible. Date specific information as to each of these items will be sent to you the week of March 31, 2008.

If you have recently sold an affected model, please submit the warranty registration information immediately, so that AHM can contact the owner.

If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Model	YM	VIN	
		From	To
VT600C6	2006	JH2PC21046M	JH2PC21096M
VT600C6	2006	JH2PC21136M	JH2PC21196M
VT600C6	2006	JH2PC21056K	JH2PC21036K
VT600C6	2006	JH2PC21146K	JH2PC21136K
VT600C7	2007	JH2PC21097M	JH2PC21017M
VT600C7	2007	JH2PC21187M	JH2PC21107M
VT600C7	2007	JH2PC210X7K	JH2PC21077K
VT600CD6	2006	JH2PC214X6M	JH2PC21486M
VT600CD6	2006	JH2PC21576M	JH2PC21516M
VT600CD6	2006	JH2PC21416K	JH2PC214X6K
VT600CD6	2006	JH2PC21506K	JH2PC21516K
VT600CD7	2007	JH2PC21457M	JH2PC21467M
VT600CD7	2007	JH2PC21467M	JH2PC21417M
VT600CD7	2007	JH2PC21547M	JH2PC215X7M
VT600CD7	2007	JH2PC21557M	JH2PC21567M

INTERACTIVE NETWORK

VT600CD7	2007	JH2PC21467H		JH2PC21427K
VT600CD7	2007	JH2PC21557H		JH2PC21547K
VT750C27	2007	JH2RC53047M		JH2RC53067M
VT750C27	2007	JH2RC53147M		JH2RC531X7M
VT750C28	2008	JH2RC53038M		JH2RC53008M
VT750C28	2008	JH2RC53128M		JH2RC53118M
VT750C28	2008	JH2RC53048H		JH2RC53018K
VT750C28	2008	JH2RC53138H		JH2RC53188K
VT750C2F7	2007	JH2RC53407M		JH2RC53437M
VT750C2F7	2007	JH2RC53517M		JH2RC53527M
VT750C2F8	2008	JH2RC534X8M		JH2RC53498M
VT750C2F8	2008	JH2RC53598M		JH2RC53588M
VT750C2F8	2008	JH2RC53408H		JH2RC53408K
VT750C2F8	2008	JH2RC535X8H		JH2RC53568K
VT750C7	2007	JH2RC50037H		JH2RC50027K
VT750C7	2007	JH2RC50127H		JH2RC50197K
VT750C8	2008	JH2RC50078M		JH2RC50028M
VT750C8	2008	JH2RC50168M		JH2RC50158M
VT750C8	2008	JH2RC50088H		JH2RC50088K
VT750C8	2008	JH2RC50178H		JH2RC50118K
VT750CA7	2007	JH2RC50487M		JH2RC50497M
VT750CA7	2007	JH2RC50547M		JH2RC50587M
VT750CA8	2008	JH2RC50438M		JH2RC50478M
VT750CA8	2008	JH2RC50528M		JH2RC50518M
VT750CA8	2008	JH2RC50448H		JH2RC50418K
VT750CA8	2008	JH2RC50538H		JH2RC505X8K
VTX1300C7	2007	1HFSC55047A		1HFSC55017A
VTX1300C7	2007	1HFSC55177A		1HFSC55187A
VTX1300C8	2008	1HFSC55048A		1HFSC55018A
VTX1300C8	2008	1HFSC55138A		1HFSC55148A
VTX1300R7/T7	2007	1HFSC52687A		1HFSC52637A
VTX1300R7/T7	2007	1HFSC52737A		1HFSC52717A
VTX1300R8/T8	2008	1HFSC526X8A		1HFSC52638A
VTX1300R8/T8	2008	1HFSC52T28A		1HFSC52T68A
VTX1300R8/T8	2008	1HFSC52798A		1HFSC52708A
VTX1300R8/T8	2008	1HFSC52N08A		1HFSC52N48A

Thank you for your cooperation.

American Honda Motor Co., Inc.



Robert E. Clever
Senior Manager – Service
Motorcycle Division

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
08-0131	1	of	1	SERVICE

© 2000–2008, American Honda Motor Co., Inc. All Rights Reserved.

Next Unread Message

View Message

Sent on 05 21 2009 Expires on 06 21 2009
 From Motorcycle Division
 Subject 2008 CBR1000RR Coolant Hose Clamp Replacement Safety Recall



Motorcycle Division

May 21, 2009

Dear Honda Dealer:

RE: 2008 CBR1000RR Coolant Hose Clamp Replacement Safety Recall

The *2008 CBR1000RR Coolant Hose Clamp Replacement Safety Recall (CBR1000RR #6)* is now posted on iN.

The Service Bulletin procedure must be completed before 2008 CBR1000RR units can be sold.

New hose clamps have been automatically allocated and will arrive at your dealership by Friday, May 22.

Sincerely,

**American Honda Motor Co., Inc.
Honda Motorcycle Division**

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
09-0256	1	of	1	SERVICE

▲ BACK TO TOP

© 2000–2009, American Honda Motor Co., Inc. All Rights Reserved.

Next Unread Message

View Message

Sent on 08 11 2010 Expires on 08 20 2010
 From Motorcycle Service Management
 Subject Stop Sale Notice: VT1300CR/CRA/CT - Non-Compliance Recall



Motorcycle Division

August 11, 2010

Dear Honda Motorcycle Dealer,

RE: Non-Compliance Recall: 2010 VT1300CR/CRA Stateline, and VT1300CT Interstate

Early production units of these models have incorrect GAWR (gross axle weight rating) values printed on the Safety Certification (VIN) Label.

American Honda Motor Co., Inc. will issue a Non-Compliance Recall to correct this situation. A Service Bulletin is expected to launch this Friday, August 13, 2010. We will ship correction stickers, via Federal Express, to your service manager to remedy the incorrect GAWR values.

Affected VIN Range:

- VT1300CR (A-type)**
JH2SC660*AK000006 thru JH2SC660*AK001855
 - VT1300CR (AC-type)**
JH2SC661*AK000001 thru JH2SC661*AK000096
 - VT1300CRA (A-type)**
JH2SC664*AK000011 thru JH2SC664*AK000240
 - VT1300CT (A-type)**
JH2SC667*AK000003 thru JH2SC667*AK000946
 - VT1300CT (AC-type)**
JH2SC668*AK000003 thru JH2SC668*AK000066
- (*) denotes check digit

Dealers must not sell any non-compliant vehicle prior to application of the correction sticker. A Dealer Responsibility Report, detailing affected units in your inventory, will be mailed to you shortly. If you are in a situation where you have a pending retail sale and correction stickers have not yet arrived or you have run out, please contact TechLine at (800) 421-1900, option 9.


Thank you for your cooperation.
American Honda Motor Co., Inc.

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
10-0270	1	of	1	SERVICE

[Next Unread Message](#)

[View Message](#)

Sent on 06 01 2011 Expires on 08 21 2011
From Motorcycle Service Communications
Subject STOP SALE NOTICE: 2010-2011 VT750C2B and 2011 VT750C



M/C Service Communications

June 1, 2011

Dear Honda Dealer:

SAFETY RECALL NOTICE

Honda is launching a SAFETY RECALL on certain 2010/2011 VT750C2B, and 2011 VT750C motorcycles to replace the bank angle sensor.

Effectively immediately, YOU MUST NOT SELL any units in the following affected VIN ranges:

- 2010 VT750C2B: All
 - 2011 VT750C2B (49 state): 001 to JH2RC537*BK101110
 - 2011 VT750C2B (CA): 001 to JH2RC538*BK100110
 - 2011 VT750C (49 state): 001 to JH2RC500*BK700180
 - 2011 VT750C (CA): 001 to JH2RC501*BK700020
- (*) denotes check digit

NOTE: Your dealership will be violating Federal Law, violating your sales and service agreement, and risking chargeback of sales incentives if you sell any affected products listed in this notice before they are repaired according to Service Bulletin VT750C/C2B #5. If you have any questions about the penalties, please refer to the link below:

[Sales Bulletin #10-0290 - Recall Compliance Letter](#)

To view a list of your affected inventory, log on to *iN* and follow this path:

Service > eResponsibility Report

If you have recently sold an affected model (up to and including the day of this message), immediately submit the sales registration to avoid penalties.

Parts Availability:

AHM will ship an initial supply of parts directly to dealers with affected inventory. Expect parts arrival in a week. The remainder of the parts will be available on open order to satisfy unit inventory and customer demand. Customer Recall Notification Letters will be mailed in the later half of June.

Make sure all departments at your dealership are aware of this action.

Additional information including the Service Bulletin will be posted by June 6th, 2011. If you have any further questions, contact Tech Line at (800) 421-1900 (Ext. 9), or contact your District Service Manager.

Sincerely,
American Honda Motor Co., Inc.

Bradley K. Little
Manager,
Motorcycle Service Communications.

Bulletin Number: 11-0218

[▲ BACK TO TOP](#)

[Next Unread Message](#)

[View Message](#)

Sent on 07 06 2011 Expires on 07 30 2011
From Motorcycle Service Communications
Subject STOP SALE NOTICE: 2008-2010 ST1300/A/PA



Motorcycle Service

July 6, 2010

Dear Honda Motorcycle Dealer,

Honda is launching a SAFETY RECALL on 2008, 2009, and 2010 model year ST1300 motorcycles to replace the rear brake master cylinder reservoir hose.

Effectively immediately, YOU MUST NOT SELL any 2008, 2009, or 2010 model year ST1300 of any model variation (standard type, ABS type, and Police type).

Parts Availability:

Initially, parts will be allocated around July 20 for dealer inventory and then made available on open order for customers responding to Recall Letters that should be mailed the following week.

Service Bulletin:

The Service Bulletin, including repair procedures, will be posted to *iN* around July 15.

NOTE: Your dealership will be violating Federal Law, violating your sales and service agreement, and forfeiting sales incentives if you sell any of the products listed in this notice before they are properly repaired according to Honda's instructions. If you have any questions about your obligations, please refer to this link:

[Sales Bulletin 10-0290, Recall Compliance Letter](#)

If you have recently sold an affected motorcycle, including up to the day of this message, immediately submit the sales registration information to avoid penalties.

Make sure all departments at your dealership are aware of this action.

Thank you for your cooperation.
American Honda Motor Co., Inc.
Motorcycle Division

Bulletin Number 11-0271

[▲ BACK TO TOP](#)

© 2000–2011, American Honda Motor Co., Inc. All Rights Reserved.

[Next Unread Message](#)

[View Message](#)

Sent on 12 02 2011 Expires on 02 10 2012
From Motorcycle Service
Subject STOP SALE NOTICE: 2001-2012 GL1800/A



Motorcycle Service

STOP SALE NOTICE

AFFECTED UNITS: 2001-2012 GL1800/A

Honda Motor Co., Ltd. is conducting a Safety Recall to inspect, and if necessary, replace the combined braking system's secondary master cylinder on affected GL1800/A motorcycles. The secondary master cylinder on some affected motorcycles may have insufficient internal freeplay between the pressure cup and the compensating port hole. If the freeplay is insufficient, the compensating port can become blocked by the pressure cup, which can cause the rear brake to drag after the rider has released the brakes. A dragging rear brake increases the risk of a crash and can generate enough heat to cause the rear brake to catch fire.

Effectively immediately, YOU MUST NOT SELL any NEW or USED units in the following affected VIN ranges:

2001 through 2010 model year GL1800/A: All units

2012 model year GL1800/A:

Type IV: JH2SC68G*CK000001 thru JH2SC68G*CK002608

Type V: JH2SC68H*CK000001 thru JH2SC68H*CK001746

Type VII: JH2SC68L*CK000001 thru JH2SC68L*CK001294

Type VIII: JH2SC68M*CK000001 thru JH2SC68M*CK000164

(*) denotes check digit

NOTE: Your dealership will be violating Federal Law, violating your sales and service agreement, and risking chargeback of sales incentives if you sell any affected products listed in this notice. If you have any questions about your responsibilities, please refer to this link:

[Sales Bulletin #10-0290 - Recall Compliance Letter](#)

To research a specific unit for recall applicability, log on to iN and follow this path:
Service >Unit Information

To manage your affected inventory, log on to iN and follow this path:
Service > Responsibility Report

If you have recently sold an affected model (up to and including the day of this message), immediately submit the sales registration to avoid penalties.

Service Bulletin, Parts, and Special Tool Availability:

AHM is immediately shipping an inspection tool to your dealership that is required to complete the recall inspection procedure. Units that pass an inspection procedure will be punch marked to indicate the completion of the Safety Recall, and will then be eligible for sale. For units that fail the inspection procedure, you must call or e-mail TechLine to have the repair parts released. The *Service Bulletin* will be published through iN by Monday, December 5. TechLine is available to answer calls as soon as you receive the inspection tool and the *Service Bulletin*.

Customer Notification:

Safety Recall Notification Letters will be mailed to affected customers in January 2012. However, affected customer units can be inspected/repared as soon as you receive the Service Bulletin.

Make sure all departments at your dealership are aware of this action.

If you have any questions, contact TechLine at (800) 421-1900 (Ext. 9), or contact your District Service Manager

Thank you for your cooperation.

American Honda Motor Co., Inc.
Motorcycle Division

Bulletin Number 11-0531

[▲ BACK TO TOP](#)

© 2000–2011, American Honda Motor Co., Inc. All Rights Reserved.