



RECEIVED

By Recall Management Division at 9:15 am, Mar 12, 2013

DEFECT INFORMATION REPORT

- 1. Manufacturer's name/address:** Terex South Dakota, Inc., 500 Oakwood Road, Watertown, SD 57201 is the equipment manufacturer.
- 2. Equipment involved in this defect notification:** T292, TL, and NT Aerial Devices manufactured in 2012 by Terex South Dakota, Inc. With 110 VAC inverters for tool power on the aerials operated from 48 Volt DC hydraulic pumps. The aerial device is installed on trucks used to elevate personnel for utility work while parked and stationary.
- 3. Total number of vehicles or items of equipment:** 23 units may be affected.
- 4. Approximate percentage of vehicles or equipment estimated to actually contain the defect:** Approximately 100% of the potentially affected aerials may experience the defect.
- 5. Description of the defect:** The Ground Fault Interrupt 110 volt outlets may not function and offer GFI protection, due to the floating neutral wiring in the inverter.
- 6. Chronological summary of events leading to this determination:** No reports of problems have been received. An audit of a production unit determined there was an issue.
- 7. The determination of existence of problem:** The failure of the GFI to operate was discovered during unit audit.
- 8. Description of proposed remedy:** The units will have a jumper wire added between the neutral and ground wire then tested to verify proper GFI operation.
- 9. Program for remedy campaign (including program for reimbursing any consumer who obtained the remedy at his/her own expense within one year of the opening of the EA, or within one year of this 573 report, whichever is earlier):** Repairs will be covered under warranty.
- 10The manufacturer's campaign number:** SN605.