



3400 East Walnut Street, Colmar, PA 18915

RECEIVED

By Recall Management Division at 8:45 am, May 09, 2013

13E-024
(2 pages)

Date: May 09, 2013

Via email.

Ms. Jennifer Timian
Chief, Recall Management Division
National Highway Traffic Safety Administration
Attention: Recall Management Division
1200 New Jersey Avenue SE
Washington, DC 20590

(NVS-215)cg

Re: Safety Defect and Noncompliance Report Guide for Equipment
Pursuant to 49 CFR 573.6(c)

EQ 13-001

Dear Associate Administrator:

This defect information report is being submitted by Dorman Products, Inc. pursuant to Part 573.6(c).

1. Manufacturer's name (573.6(c) (1):
Dorman Products Inc.

2. Identification of motor vehicle equipment (573.6(c) (2):

Master Cylinder BX2239671 as labeled by BOSCH and purchased as Dorman SKU UM630274.
These were relabeled and sold by Dorman as M630274-BX.

3. The total number of items of equipment (573.6(c) (3):

As referenced in NHTSA campaign number 13E011000, Dorman received a total of (7) pieces from Bosch under UM630274. Of these (7) parts, (3) were returned to BOSCH from Dorman inventory and (1) was determined to be scrapped in field due to shipping damage. The customer of the remaining (3) were determined to not have parts in inventory and their contact information has been provided to BOSCH.

4. The percentages of items of equipment estimated to contain the defect (573.6(c) (4):

Dorman has not received any complaints related to the issues described by BOSCH in campaign number 13E011000 for M630274-BX. Regardless, all cooperative efforts have been made with BOSCH to recover and/or track all (7) pieces.

5. Description of the defect (573.6(c) (5):

Please reference campaign 13E011000 for description by BOSCH.

6. A chronology of events (573.6(c) (6):

Dec 2012	BOSCH contacts Dorman of issue and requests inspection and return of non-certified material.
Feb 14, 2013	Dorman inventory sorted and (7) suspect units shipped to BOSCH
Feb 28, 2013	Dorman contacts customers and confirms none have unsold inventory. One customer reports a unit was scrapped due to shipping damage.
March 7, 2013	Dorman provides BOSCH with the contact information for customers that purchased and sold the unaccounted (3) pieces for direct follow-up.
March 8, 2013	BOSCH confirms that (3) of the returned parts meet criteria.
April 4, 2013	BOSCH provides confirmation that BOSCH will follow-up with purchasers as offered to Dorman.

7. A program to remedy the defect (573.6(c) (8):

Three of the seven total parts have not been accounted by Dorman. Information of the customers has been provided to BOSCH for follow-up.

8. Representative copy of all notices and bulletins (573.6(c) (10):

Reference campaign 13E011000.

9. Manufacturer's campaign number (573.6(c) (11):

Dorman has not issued a campaign number. Please reference BOSCH campaign 13E011000.

If you have any questions regarding this report, please contact Dorman Products, Inc. Attn: Michael Campana, Director – External Quality, 3400 East Walnut Street, Colmar, PA 18915.

Sincerely,

Dorman Products, Inc.



Michael Campana

Director of External Quality