

RECEIVED

By Recall Management Division at 10:02 am, May 28, 2013

Toyota Motor Engineering & Manufacturing North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

May 21, 2013

Ms. Nancy Lummen Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Ave, SE
Washington, D.C. 20590

Re: Recall # 13V-133
Certain Toyota and Lexus Vehicle Front Passenger Airbags
Part 573, Defect Information Report

Dear Ms. Lewis:

In connection with the above referenced matter, this supplements Toyota's letter of April 11, 2013.

The affected vehicle VIN range and corresponding number of affected vehicles is indicated below:

Identification of Affected Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Lexus/ SC	2002	TMC	FN48Y	20001059-20035548	January 8, 2001 through September 25, 2003
	2003			30035116-30046972	
	2004			40051445	
Toyota/ Corolla	2003	TMC	BR3*E	300002007-30051596 32000000-32016855	April 2, 2002 through November 28, 2003
	2004			40051487-40053026 42016856-42044363	
	2003	TMMC		3C000082-3C778027	December 17, 2001 through January 22, 2004
	2004			4C165645-4C815358	

	2003	NUMMI		3Z000001-3ZPP4315	December 28, 2001 through April 8, 2004
	2004			4Z190447-4Z336017	
Toyota/ Corolla Matrix	2003	TMMC	**3*E	3C000083-3C776114	December 17, 2001 through January 20, 2004
	2004			4C165644-4C278005	
Toyota/ Sequoia	2002	TMMI	*T**A	2S105332-2S137484	April 2, 2002 through July 14, 2004
	2003			3S100034-3S181311	
	2004			4S237174	
Toyota/ Tundra	2003	TMMI	****1	3S306031-3S425621	May 24, 2002 through July 8, 2004
	2004			4S435495-4S461298	
Pontiac/ Vibe	2003	NUMMI	S*6**	3Z400001-3ZPP1238	December 28, 2001 through May 5, 2003
	2004			4Z400001-4Z401279	

Note: (1) Toyota received information from the supplier that approximately 170,000 front passenger air bags containing potentially affected inflators had been supplied to Toyota for use in the subject vehicles.

(2) Although the involved vehicles are within the above VIN ranges, not all vehicles within these ranges were sold in the U.S.

(3) No other Toyota or Lexus vehicles use the affected air bag inflators.

Total Number of Vehicles Potentially Affected:

Lexus SC : 34,748
Toyota Corolla : 501,249
Toyota Corolla Matrix : 87,550
Toyota Sequoia : 73,423
Toyota Tundra : 62,745
Pontiac Vibe : 84,562

Should you have any questions about this report, please contact me at (310) 468-1946.

Sincerely,



Matthew D. Collins
Manager
Toyota Motor Engineering & Manufacturing
North America, Inc.

cc: J. Timian