

TMS-NTC-13131
June 10, 2013

Recall Management Division
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Re: Toyota Safety Recall 13V-133 Owner Notification Letter (Interim)


To whom it may concern:

Please find attached, for your records, representative copies of the previously approved Owner Notification Letter for Safety Recall 13V-133 on the following Toyota and Lexus vehicles:

- 2003-2004 Model Year Corolla, Corolla Matrix, and Tundra
- 2002-2003 Model Year Sequoia
- 2002 through certain 2003 Model Year SC 430

If you have any questions regarding this matter, please contact me at (310) 468-5316.

Sincerely,



Quality Compliance Assistant Manager

Attachments:

- Lexus 13V-133 (DLC) Owner Notification (Interim)
- Toyota 13V-133 (DOF) Owner Notification (Interim)



Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue
P.O. Box 2991
Torrance, CA 90509-2991

INTERIM NOTICE

We are currently preparing the remedy. We will notify you again when the remedy is ready.

**2003 to Certain 2004 Model Year Corolla, Corolla Matrix, and Tundra Vehicles and
2002 to Early 2004 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module
SAFETY RECALL NOTICE (Interim Notice)**

Dear Toyota Customer:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in 2003 to certain 2004 Model Year Corolla, Corolla Matrix, and Tundra vehicles and 2002 to early 2004 Model Year Sequoia vehicles.

The purpose of this letter is to explain the details of the recall and to keep you informed of Toyota's implementation plan. We are currently making preparations to implement the Safety Recall remedy. **We will send you a second notification when the remedy is available.**

What is the condition?

The subject vehicles are equipped with front passenger airbag inflators which could have been assembled with improperly manufactured propellant wafers. There is a chance that improperly manufactured propellant wafers could cause the inflator to rupture and propel fragments toward occupants in the event of a crash, increasing the risk of injury.

You will receive a second owner notification letter when the remedy is available.

If you would like to update your vehicle ownership or contact information, please go to www.toyota.com/ownersupdate. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

What should you do?

Once you receive the second notice, you will be instructed to bring your vehicle to an authorized Toyota dealer for inspection and replacement of the airbag inflator if necessary. Toyota anticipates the second notice will begin mailing in mid-July.

What if you have other questions?

Please visit us at www.toyota.com/recalls. Please input your 17-digit Vehicle Identification Number (VIN). Frequently Asked Questions (FAQ) are posted on this website for your reference. The FAQ will periodically be updated so please check back frequently.

Your local Toyota dealer will be more than happy to answer any of your questions. If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 a.m. to 6:00 p.m., Saturday 7:00 a.m. through 4:00 p.m. Pacific Time.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.safercar.gov.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

TOYOTA MOTOR SALES, U.S.A., INC.