



INSTRUCTIONS TO PERFORM CAMPAIGN 129

Models Affected:

This campaign affects 2011 model year E30W Winnebago® Vista® and Itasca® Sunstar®.

These motor homes were manufactured June 30, 2010 through June 16, 2011.

Kit Includes:



- (2) Vehicle Certification Labels
- Instructions

Procedure:

The affected vehicles were produced with a Vehicle Certification Label that incorrectly states the tire inflation pressures and wheel size. Incorrect labels will be replaced with correct ones.

The incorrect labels identify the front axle and rear axle tire inflation pressures as 80 PSI and wheel rim size as 19.5x6.75. See Photo A. The correct front axle tire inflation pressure is 95 PSI and rear axle rear axle tire inflation pressure is 100 PSI. The correct wheel rim size is 19.5x6.00 for all wheels. See Photo B.

NOTE: Incorrect tire pressures or tire size can lead to tire failure possibly resulting in loss of vehicle control and injury.




Vehicle Certification Labels are located both below the driver's window and inside the Owner InfoCase.

1. Cover the existing Vehicle Certification Label below the driver's window with the corrected label included with this campaign as shown in Photo C.



Install Label

2. Cover the existing Vehicle Certification Label inside the Owner InfoCase with the corrected label included with this campaign as shown in Photo D.



Install Label

After the new labels are installed, please complete the enclosed pre-addressed postage paid postcard and mail to Winnebago Industries.