



NHSTA Recall Number 13V-262

Date: July, 17th 2013

Subject: SAFETY RECALL NOTICE

Dear Brammo Empulse Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Brammo Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2013 Empulse and Empulse R models. This recall pertains to the rear tail section assembly which can fatigue over time and potentially break off while riding.

Failure of the tail section assembly could occur after prolonged fatigue of normal riding conditions. If the tail section assembly fails, the rear brake light and turn signals could come in contact with the rear tire or wheel. This increases the chance of a crash. It is recommended that you inspect the mounting points of the rear tail assembly at the rear of the sub frame for any signs of cracking.

You are receiving this letter because our records indicate that you have purchased one of the recalled motorcycles. It is possible that any of the motorcycles included in the recall may experience failure of the rear tail assembly. A loose or unsteady tail assembly can indicate a potential failure.

It is important that all recalled motorcycles are serviced in accordance with this recall notice as soon as possible. Please contact your nearest authorized Brammo Dealer no sooner than July 26th 2013. This component replacement will be performed without charge to the customer. To locate an Authorized Brammo Dealer, please reference the list below or visit the online dealer locator at www.Brammo.com.



Bartels 4141 Lincoln Blvd. Marina Del Rey, CA, CA 90292 Phone: 310-823-1112 www.labrammo.com	Scuderia West 69 Duboce Ave San Francisco, CA 94103 Phone: 415-621-7223 www.scuderiawest.com	San Diego BMW Motorcycles 5673 Kearny Villa Road San Diego, CA 92123 Phone: 858-560-2453 www.sdbmwmc.com
Euro Cycles of Tampa Bay 8509 Gunn Highway Odessa, FL 33556 Phone: 813-926-9937 www.eurocyclesoftampabay.com	Unique Superbikes 2693-2695 Biscayne Blvd Miami, Florida 33137 Phone: (786) 353-0550 www.uniquesbk.com	Polaris of Portland 250 SE Division Place Portland, OR 97202 Phone: 503-872-0000 www.polarisofportland.com
Eurosports 303 S. 3rd Street Route 309 Coopersburg, PA 18036 Phone: 610-282-9300 www.eurosports.net	Suburban Motors 139 Main St. Thiensville, WI 53092 Phone: 262.242.2464 www.suburbanharley.com	Lone Star BMW / Triumph 10600 North Lamar Blvd Austin, TX 78753 Phone: 512-451-7979 www.lonestarcycle.com
Foothills BMW 1435 Wadsworth Blvd. Lakewood, CO. 80214 Phone: 303.202-1400 www.foothillsmotorcycles.com		

An authorized Brammo dealer will replace the rear tail section assembly with a new version not susceptible to failure. This removal and replacement of the rear tail assembly will take about 30 minutes for your authorized dealer to perform. All work performed for this recall will be free of charge to the customer.

- 97724073 – Bracket, Tail
- 10886639 – Spacer, Tail

All replacement parts will be shipped to your Brammo dealer prior to July 26th 2013.

If you still have questions after receiving this letter or visiting the website and your Authorized Brammo dealer, please contact Brammo Inc. Service at 541-482-9555 ext. 337 between 9:00 am and 5:00 pm Pacific Standard Time, Monday-Friday.

Federal law requires any lessor who receives a notification of a determination of a safety-related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

If your servicing Brammo dealer fails or is unable to provide the service as described above without charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to www.safercar.gov.

Commitment to safety and quality are our highest priorities. Please accept our sincerest apology for any inconvenience this may cause you.

Sincerely,

Adam Lukoic

Adam Lukoic
 Service Manager
 Brammo Inc.