

RECEIVED

By Recall Management Division at 1:00 pm, Sep 12, 2013

13V-419
(3 pages)

LAKOTA CORP
- PO BOX 219 - 4 STOUTCO DRIVE - BRISTOL, IN 46507
PHONE: 574-848-1636 FAX: 574-848-1467

Part 573 Report

September 10, 2013

RE: Identification number EQ 13-006

This report serves as notification by **Lakota Trailers** to the National Highway Traffic Safety Administration (“NHTSA”) that a motor vehicle safety-related issue exists in certain travel trailer locks supplied by Fastec Industrial Corp., a division of WESCO Distribution, Inc., for installation in the doors of Recreational Vehicles (“RVs”). Additional information concerning the recalled locks can be found in Fastec’s Part 573 Report that was separately filed on July 11, 2013 with an assigned NHTSA Recall #13E039.

I. Manufacturer, Designated Agent, and Other Chain of Distribution Information

Filing Firm Name: **Lakota Trailers**
Address 1: PO Box 219, 4 Stoutco Drive
City: Bristol
State: IN
Postal Code: 46507
Email address: ajyoder@lakotatrailers.com
Telephone: 574-848-1636
Fax: 574-848-1467
Web Site: www.lakotatrailers.com

Contact Person: AJ Yoder
Title: Customer Service
Email address: ajyoder@lakotatrailers.com
Telephone: 574-848-1636
Fax: 574-848-1467

Importer/Distributor: Fastec Industrial Corp.
2219 Eddie Williams Rd
Johnson City, TN 37601

Manufacturer: Zhongshan Huafeng Locks Co., Ltd.
South of Yongning Industrial Avenue
Xiaolan Town, Zhongshan, Guangdong
People's Republic of China

II. Identification of the Recall Population and Its Size

Type of Equipment:

The product consists of certain travel trailer locks with a keyed paddle handle and deadbolt (the "locks") installed in the doors of RVs. Only FIC locks that have an integrated deadbolt are affected by this recall. The RVs potentially affected by the recall are as follows:

Brand: Lakota
Model Nos: 3HSLBP & 4HSLGN6
Model years: January 2006 – April 2013.
Body Style/Type: Bumper pull and Gooseneck Trailers

Total Product Sold:

Lakota Trailers sold a total of 2 trailers with an FIC deadbolt lock between January 1, 2006 and April 25, 2013. This total includes locks with any key code, not just the subset of 20 key codes that may be affected by the recall.

Current Inventory Estimates:

Lakota Trailers has reviewed its current inventory of trailers and **has no trailers in its inventory with any potentially affected locks.**

Percentage of Recall Population Estimated to be Affected:

Lakota Trailers believes that 2 **trailers** with an FIC deadbolt lock sold between January 2006 and April 2013 may potentially be affected.

III. Description of Issue and Type of Hazard

In or about August 2013, Fastec notified **Lakota Trailers** that Fastec intended to initiate a recall of the potentially affected locks due to a potential jamming issue with the deadbolt cylinder. If a lock is affected, the key may be able to be removed from the locked door when the

key in the deadbolt cylinder is in the horizontal 9 o'clock position, potentially jamming the deadbolt and potentially causing the red lever on the interior side of the lock to become inoperable. In that event, a person inside the travel trailer may not be able to unlock and open the main RV door, but he or she could still exit the trailer from the emergency exit.

IV. The Remedy Program and Its Schedule

Upon approval of the proposed recall and the recall announcement, **Lakota Trailers** will work with Fastec to notify consumers of the recall. **Lakota Trailers** estimates that it will issue consumer notifications in the fourth quarter of 2013. **Lakota Trailers** will coordinate the recall efforts with Fastec and will refer consumers to Fastec for free replacement of the cylinders in any affected locksets as described more fully in Fastec's Part 573 Report.