

RECEIVED

By Recall Management Division at 9:36 am, Sep 30, 2013



Automobili Lamborghini S.p.A.

Ms. Nancy Lummen Lewis,
Acting Associate Administration for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Ave SE
Washington DC 20590

Date: 09/30/2013

Subject: Notification of Voluntary Recall / 2007 – 2009 Model Year Lamborghini Gallardo

Dear Ms. Lewis:

This information is submitted in accordance with the requirements of Part 573 of Title 49 of the Code of Federal Regulations (49 CFR 573 (2012)).

573.6 (c)(1)

Manufacturer's Name

Manufacturer Automobili Lamborghini S.p.A.

Importer Automobili Lamborghini America LLC

The recalled vehicle is imported;

Corporate official
to be contacted

Name: Rene Sultzner.
Title: Head of After Sales Of
Automobili Lamborghini America
LLC
Phone +1-703-364-7042
Fax +1-703-364-7015
Email rene.sultzner@lamborghini.com

Designated agent: Lance Tunick
PO box 23078 Santa Fe NM87502.



573.6 (c)(2)

Identification of Vehicles

Make: Lamborghini

Line: Gallardo Coupè
Gallardo Spyder

Model Year: 2007, 2008, 2009

Month/Year
of manufacture Beginning October 2006
Ending February 2009

VIN Numbers of
Affected Vehicles Beginning ZHWGE12TX7LA04413
Ending ZHWGE54T99LA08928

573.6 (c)(3)

Number of vehicles Potentially Containing the Defect

Approximately 263 vehicles are affected by this recall in the United States.

573.6 (c)(4)

Percentage of Vehicles Actually Containing Defect

Lamborghini is unable to estimate the percentage of vehicles in the United States that are potentially subject to this defect.

573.6 (c)(5)

Description of Defect

On vehicles fitted with carbon ceramic brake discs, the stainless steel screws fixing the rotor to the metal bell may fail due to stress corrosion cracking, if the vehicle has been used in extreme salt environments.

The customer will experience a noise when a screw fails and the brake continues to be 100% effective. However, if the affected disc was to lose 8 of the 10 screws there would be a loss of braking. This may lead to a small increase in stopping distance and could lead to a crash.

Automobili Lamborghini S.p.A. is not aware of any vehicle losing greater than 3 screws worldwide. There have been no screw failures reported in the USA and this action is being undertaken as a precaution. There are no reports worldwide of accidents or injuries resulting from this condition.

573.6 (c)(6)

Basis for Determination

In the course of continuous product monitoring and internal tests, Automobili Lamborghini S.p.A. has determined that in rare cases, the stainless steel screws fixing the brake rotor to the metal bell may fail due to stress corrosion cracking if the vehicle has been used in extreme salt environments. There have been no claim of fires, accidents, or injury.

Date of determination: September 2013.



573.6 (c)(7) **Non-compliance Test Result**
Not applicable

573.6 (c)(8) **Proposed Remedial Program**
When sufficient screws are available of a material not susceptible to stress corrosion cracking, Automobili Lamborghini S.p.A. will notify all owners of affected vehicles and will instruct them to arrange for an appointment with an authorized Lamborghini dealer. Dealers will replace the screws on affected vehicles free of charge.

Dealer: On or before the week of October 11st
Owner: On or before the week of October 21st

573.6 (c)(10) **Submission of communications**
Drafts are attached.

573.6 (c)(11) **Proposed Owner Letter**
Draft is attached to be submitted to Agency for review and approval.

573.6 (c)(12) **Manufacturer's Recall Code**
Lamborghini has assigned the following code:

- L71X-R.01.13 Gallardo Coupè, Gallardo Super Leggera And Gallardo Spyder MY 2007 and 2008.
- L71X-R.02.13 Gallardo Coupè and Spyder My 2009.

In case of questions please contact:

Name	Alessandro Farneschi
Title	Head of After Sales
Telephone	+39 051 6817652
Fax	+39 051 6817709
Email	alessandro.farneschi@lamborghini.com

Yours sincerely,

Automobili Lamborghini S.p.A.

Maurizio Reggiani
Research and Development Director

Alessandro Farneschi
Head of After Sales



Automobili Lamborghini S.p.A.

FAX: 001 202 366 1767

4 pages

Ms. Nancy Lummen Lewis,
Acting Associate Administration for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Ave SE
Washington DC 20590

This information incl. all mentioned attachment will follow as letter

In the meanwhile I'm available for your questions

Alessandro Farneschi
Head Of After Sales

Email alessandro.farneschi@lamborghini.com
Telephone: +39 051 6817652
Fax: +39 051 6817709