

Cargo South, Inc.

Part 573 Report

Date: December 20 , 2013

This report serves as notification by Cargo South, Inc. to the National Highway Traffic Safety Administration (“NHTSA”) that a motor vehicle safety-related issue exists in certain travel trailer locks supplied by Fastec Industrial Corp., a division of WESCO Distribution, Inc., for installation in the doors of Recreational Vehicles (“RVs”). Additional information concerning the recalled locks can be found in Fastec’s Part 573 Report that was separately filed on July 11, 2013 with an assigned NHTSA Recall #13E039.

I. Manufacturer, Designated Agent, and Other Chain of Distribution Information

Filing Firm Name: **Cargo South, Inc.**
Address 1: 202 Industrial Drive
City: Ocilla
State: GA
Postal Code: 31774
Email address: cargosouthfhp@yahoo.com
Telephone: 229-468-5857
Fax: 229-468-5659

Contact Person: Alex Dix
Title: Secretary
Telephone: 229-425-8083

Importer/Distributor: Fastec Industrial Corp.
2219 Eddie Williams Rd
Johnson City, TN 37601

Manufacturer: Zhongshan Huafeng Locks Co., Ltd.
South of Yongning Industrial Avenue
Xiaolan Town, Zhongshan, Guangdong
People’s Republic of China

II. Identification of the Recall Population and Its Size

Type of Equipment:

The product consists of certain travel trailer locks with a keyed paddle handle and deadbolt (the “locks”) installed in the doors of RVs. Only FIC locks that have an integrated deadbolt are affected by this recall. The RVs potentially affected by the recall are as follows:

Brand:	Cargo South, Inc.
Model Nos:	Enclosed Trailers - Utility
Model years:	January 2006 – April 2013.
Body Style/Type:	Enclosed Trailers

Total Product Sold:

Cargo South, Inc. sold a total of 1,440 travel trailers with an FIC deadbolt lock between January 1, 2006 and April 25, 2013. This total includes locks with any key code, not just the subset of 20 key codes that may be affected by the recall.

Current Inventory Estimates:

Cargo South, Inc. has no current inventory of travel trailers and has no travel trailers in its inventory with any potentially affected locks.

Percentage of Recall Population Estimated to be Affected:

Cargo South, Inc. believes that some unknown subset of travel trailers with an FIC deadbolt lock sold between January 2006 and April 2013 may potentially be affected.

III. Description of Issue and Type of Hazard

In or about June/July 2013, Fastec notified Cargo South, Inc. that Fastec intended to initiate a recall of the potentially affected locks due to a potential jamming issue with the deadbolt cylinder. If a lock is affected, the key may be able to be removed from the locked door when the key in the deadbolt cylinder is in the horizontal 9 o'clock position, potentially jamming the deadbolt and potentially causing the red lever on the interior side of the lock to become inoperable.

IV. The Remedy Program and Its Schedule

Upon approval of the proposed recall and the recall announcement, **Cargo South, Inc.** will work with Fastec to notify consumers of the recall. **Cargo South, Inc.** estimates that it will issue consumer notifications in the first quarter of 2014. **Cargo South, Inc.** will coordinate the recall efforts with Fastec and will refer consumers to Fastec for free replacement of the cylinders in any affected locksets as described more fully in Fastec's Part 573 Report.