

RECEIVED

By Recall Management Division at 5:47 am, Dec 24, 2013

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000

NISSAN


December 23, 2013

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
Room W48-302
1200 New Jersey Ave., SE
Washington, D.C. 20590

Dear Madam:

The enclosed Noncompliance Information Report is being submitted in accordance with 49 CFR Part 573. Nissan plans to notify dealers on December 26, 2013 and begin notifying owners on January 21, 2013. We do not plan to put a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy as the subject vehicles are under warranty.

Very truly,


Donald Neff
Manager,
Technical Compliance

Encl.

NONCOMPLIANCE INFORMATION REPORT

1. Manufacturer:

Nissan North America, Inc.

2. Vehicles Potentially Involved:

2014 Model Year Nissan Titan King Cab and Crew Cab vehicles manufactured from August 27, 2013 to November 13, 2013. Vehicles manufactured after these dates are not affected.

3. Total Number of Vehicles Potentially Involved:

183 vehicles

4. Percentage of Vehicles Estimated to Actually Contain the Noncompliance:

100%

5. Description of the Noncompliance:

The vehicles fail to comply with S4.3 (a) of Federal Motor Vehicle Safety Standard (FMVSS) No. 110. Specifically, the Tire and Loading Information label on the affected vehicles overstate the maximum load and passenger carrying capacity for the vehicle. All other applicable FMVSS 110 requirements are met.

6. Basis for Determination of the Existence of a Noncompliance

During a routine load value check activity, Nissan found that the Tire and Loading Information label on a subject vehicle contained an incorrect value for the combined weight of occupants and cargo carrying capacity.

Nissan promptly initiated an investigation of the issue, which included a yard inspection at the Canton, Mississippi plant and a dealer inventory inspection, as well as a review of the applicable legal requirements.

December 18, 2013 - Based on the results of the plant and dealer inspections, Nissan determined that a small number of vehicles outside of its control contained a Tire and Loading Information label that did not meet the applicable requirements of FMVSS No. 110 and decided that a noncompliance existed.

7. Description of Corrective Action:

Nissan will supply customers with a new label and installation instructions on how to install the label in order to remedy the issue. The customer will also have the option of taking their vehicle to a Nissan dealer to have the new label installed if they are uncomfortable performing this action.

8. Copy of Notices:

Copies of all notices, if any, will be provided to NHTSA as they become available.