

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

December 20, 2013

Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215, Rm. W45-206)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

**Re: Defect Information Report – Supplemental Report No. #2
13V-539, FL-651, TBB Saf-T-Liner C2 Seat Track Rivets
Representative Owner Notice**

Ms. Lewis,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and a representative copy of the document distributed to owners.

(c)(8)(ii) Owners of 73 vehicles were notified on December 20, 2013.

(c)(10) A copy of communications sent to owners is attached.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Amy Martin, CAL-OSHA
Attachment

Daimler Trucks North America LLC

Daimler Trucks North America LLC
Thomas Built Buses
1408 Courtesy Road
High Point, NC 27260
336.889.4871 Phone

December 2013
FL651A-G
NHTSA #13V-539 (School Buses)
Transport Canada #13-379

IMPORTANT SAFETY RECALL **Subject: TBB Saf-T-Liner C2 Seat Track Rivets**

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This notice is sent to you in accordance with the Canadian Motor Vehicle Safety Act.

Daimler Trucks North America LLC (DTNA), on behalf of its wholly owned subsidiary, Thomas Built Buses (TBB) has decided that a defect which relates to motor vehicle safety exists on specific Thomas Built Buses Saf-T-Liner C2 School Bus vehicles manufactured July 9, 2013 through September 12, 2013, and equipped with track seating.

On certain buses, seats with seatbelts are attached to a seat track that is mounted to the floor. The rivets used to attach the seat track to the floor may not have been properly seated when installed. If the rivets are not properly seated, in the event of a crash, the seat belt anchorages may not perform as expected increasing the risk of injury.

The seat track mounting will be reinforced as needed.

To arrange for repairs, you should contact your local Thomas Built Bus dealer immediately. Thomas will remedy this defect without charge. The repair should take approximately 8 hours up to 32 hours depending on your vehicle, and will be performed at no charge to you. You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days.

If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement. For further information, please contact the Warranty Department at (336) 889-4871, 8:00 a.m. to 5:00 p.m. Eastern Time Monday through Friday. To find a dealer in your area please go to www.thomasbus.com.

If you have any questions about this recall, please contact the Warranty Department at (336) 889-4871, 8:00 a.m. to 5:00 p.m. Eastern Time, Monday through Friday. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. In Canada, you may contact Transport Canada-road safety, 80 rue Noel, Gatineau, Quebec J8Z 0A1 or call (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

THOMAS BUILT BUSES WARRANTY DEPARTMENT
Enclosure