

**Equipment Safety Recall Quarterly Report Information**  
**NHTSA Safety Recall Campaign Number: 13E-055**

Report Date: **January 30, 2013**

Calendar Quarter	<b>October 1 – December 31, 2013</b>
------------------	--------------------------------------

Manufacturer:

ILJIN Global Co. Ltd.  
c/o ILJIN USA Corporation  
28055 Haggerty Road  
Novi, MI 48377

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Kelly T. Grubaugh  
Director - Engineering & Quality Assurance  
ILJIN USA Corporation  
28055 Haggerty Road  
Novi, MI 48377  
248-848-1021 Office  
734-693-4546 Mobile  
Email: [kelly.t.grubaugh@ILJIN.com](mailto:kelly.t.grubaugh@ILJIN.com)

Subject equipment:

FEDERAL-MOGUL (MOOG) – Front wheel bearing 515082  
FEDERAL-MOGUL (MOOG) – Front wheel bearing 515083  
SKF USA – Front wheel bearing BR930639  
SKF USA – Front wheel bearing BR930658  
SKF USA – Front wheel bearing BR930695  
SKF USA – Front wheel bearing BR930722

1. NHTSA Safety Recall Campaign Number: 13E-055

Manufacturer's assigned campaign number (where applicable): None

2. (a) The date notification to purchasers began:

The approved owner recall notice was sent to SKF for distribution to purchasers on **December 9, 2013**.

The approved owner recall notice was sent to Federal-Mogul for distribution to purchasers on **January 9, 2014**.

(b) The date notification of purchasers was completed:

SKF and Federal-Mogul are in the process of identifying and notifying purchasers.

(c) The date notification to dealers and distributors began:

The original and amended Part 573 defect and noncompliance reports were sent to SKF and Federal-Mogul at the same time as they were submitted to NHTSA.

The approved recall notice was sent to SKF, who is ILJIN's distributor, on **December 9, 2013**.

The approved recall notice was sent to Federal-Mogul, who is ILJIN's distributor, on **January 9, 2014**.

(d) The date notification of dealers and distributors was completed:

The approved recall notice was sent to SKF, who is ILJIN's independent distributor, on **December 9, 2013**, with instructions to transmit a copy of the notice to SKF's dealers and retailers, as provided by 49 C.F.R. §577.7(c)(2)(iv).

The approved recall notice was sent to Federal-Mogul, who is ILJIN's independent distributor, on **January 9, 2014**, with instructions to transmit a copy of the notice to Federal-Mogul's dealers and retailers, as provided by 49 C.F.R. §577.7(c)(2)(iv).

3. The total number of items of equipment involved:

FEDERAL-MOGUL (MOOG) – Front wheel bearing 515082	200
FEDERAL-MOGUL (MOOG) – Front wheel bearing 515083	570
SKF USA – Front wheel bearing BR930639	792
SKF USA – Front wheel bearing BR930658	1,512
SKF USA – Front wheel bearing BR930695	11,468
SKF USA – Front wheel bearing BR930722	252
TOTAL	14,794

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 12,367

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: Not yet determined.

Theft: No reports of theft at this time.

Scrapping: Not yet determined.

Failure to receive a notification of the recall: Not yet determined.

Other reasons (specify below):

Total number of items of equipment unreachable for inspection:  
Not yet determined.

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 12,833

10,709 items were repaired before distribution by SKF or Federal-Mogul to their dealers, distributors, and retailers.

2,124 items were returned by dealers, distributors, and retailers to SKF and Federal-Mogul before sale to purchasers. 1,961 of the returned items have been repaired.