

Equipment Safety Recall Quarterly Report Information

Report Date: 2014-01-10

Calendar Quarter (circle one): January 1 – March 31  
April 1 – June 30  
July 1 – September 30  
October 1 – December 31

Manufacturer (name, address, phone): Öhlins Racing, Box 722,  
Instrumentvägen 8-10, SE-194 27 Upplands Väsby, Sweden

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Oskar Ahlgren, Öhlins Racing, Box 722,  
Instrumentvägen 8-10, SE 194 27 Upplands Väsby, Sweden

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Steering damper brackets sold on the aftermarket for models listed below.

Boxes framed with  contain information about the initial recall that was notified 2013-06-19.

Boxes framed with  contain information about the addition to the recall campaign.

|  |
|--|
| Type of equipment (e.g., tire, child restraint, headlamp): <u>Universal Steering damper kit for BMW S1000 RR</u>             |
| Part/Model number: <u>SD 033, SD 037, SD 038</u>   |
| Size and function (where applicable):  |
| Inclusive dates of manufacture (month and year): <u>2008-09 to 2013-10</u>   |
| Other information necessary to describe this equipment:  |
| Total number of these items of equipment:<br><u>SD 033: 666 items</u><br><u>SD 037: 25 items</u><br><u>SD 038: 110 items</u> |

1. NHTSA Safety Recall Campaign Number: 13E-034

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: Unknown as Öhlins sells to a distributor who sells to independent dealers who sells further to the end customer.

(b) The date notification of purchasers was completed: -

(c) The date notification to dealers and distributors began: 2013-07-02

(d) The date notification of dealers and distributors was completed: 2013-11-19

3. The total number of items of equipment involved: Initial: 801

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: Initial: 84

(b) Total number inspected, but determined NOT to require the remedy: N/A

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: \_\_\_\_\_

Theft: \_\_\_\_\_

Scrapping: \_\_\_\_\_

Failure to receive a notification of the recall: \_\_\_\_\_

Other reasons (specify below): \_\_\_\_\_

Unknown at this point of time.  
\_\_\_\_\_  
\_\_\_\_\_

Total number of items of equipment unreachable for inspection: Unknown at this point of time.

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 84

This report may be e-mailed to [RMD.ODI@dot.gov](mailto:RMD.ODI@dot.gov) or facsimiled to (202) 366-7882.