



MAZDA MOTOR CORPORATION

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan

TEL : +81-82-287-4591
FAX : +81-82-287-5219

April 25, 2014

Our Ref. No. FQ140425-01

Recall Management Division (NVS-215)
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Re: Submission of Quarterly Report for the First Quarter of 2014

In accordance with the provisions of Section 573.7, Part 573, Title 49, we enclose the quarterly report on the following Recall Campaign ID Number.

- | | | |
|-------------|--|--------------|
| (1) 12V-357 | 2001-2008 TRIBUTE Engine Cover Modification | (6th report) |
| (2) 13V-130 | 2003-2004 Mazda6 and 2004 RX-8 Front Passenger Air Bag | (4th report) |
| (3) 13V-425 | 2009-2013 Mazda6 Door Latch Mounting Screws | (2nd report) |

If there are any questions regarding this report, please contact David Robertson of Mazda North American Operations at (313) 594-7778.

Sincerely yours,

For Shunichi Fujiyama
Manager
Field Quality Group
Field Quality Department
Mazda Motor Corporation

Enclosed: Quarterly Report

cc: Mazda North American Operations Irvine Office
Mazda North American Operations Allen Park Office

ZOOM-ZOOM

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.7

Report Date: April 23, 2014Calendar Quarter: The First quarter of 2014Safety Recall Quarterly Report from January 1, 2014 through March 31, 2014Manufacturer: Mazda Motor CorporationRecall Subject: 2001-2008 Mazda Tribute Engine Cover Modification1. NHTSA Safety Recall Campaign Number: 12V-357Mazda Recall Campaign Code Number: #6812G

2. The date notification to purchasers began:

August 6, 2012

(Initial notification; interim repair)

September 13, 2012

(Final notification; permanent repair)

The date notification of purchasers was completed:

November 15, 2012

3. The Total Number of Items Involved:

217,420 units

Number of Items Returned from Inventory or Remedied Prior to Sale:

0 units

4. Total Number of Receiving Corrective Action:

88,009 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	88,009
Total	88,009

5. Items Determined to be Unreachable

Total Number Exported:

41 units

Total Number Stolen:

11 units

Total Number Scrapped:

8,068 units

Total Number Unable to Notify:

9,227 units

Total Number Otherwise Unreachable:

Vehicle sold, name/address not provided

1,222 units

Do not own a Mazda

125 units

Blank reply card returned

1,120 unitsTotal 2,467 units