



**RECEIVED**

*By Recall Management Division at 5:57 am, May 20, 2014*

May 19, 2014

Ms. Nancy Lewis  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Recall Management Division (NVS-215)  
1200 New Jersey Avenue, SE – Room W45-306  
Washington, DC 20590

Dear Ms. Lewis:

The following information is submitted pursuant to the requirements of 49 CFR 573.6 as it applies to a determination by General Motors to conduct a safety related recall involving certain 2015 model year Chevrolet Silverado HD and GMC Sierra HD model vehicles.

573.6(c)(1): Chevrolet and GMC Brands of General Motors Company.

573.6(c)(2)(3)(4): This information is shown on the attached sheet.

573.6(c)(5): General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2015 model year Chevrolet Silverado HD and GMC Sierra HD model vehicles equipped with a 220 Amp Generator (RPO KW5). These vehicles have a condition where the retention clips that attach a fuse block to the vehicle body can become loose, allowing the fuse block to move out of position. If this occurs, exposed conductors in the fuse block may contact the mounting studs or other metallic components, causing a short to ground event. This could result in an arcing condition, and combustible materials located nearby could ignite and result in an engine compartment fire.

573.6(c)(6): The issue was presented to the Field Performance Evaluation Review Committee on May 12, 2014, and on May 19, 2014, the Executive Field Action Decision Committee decided to conduct a safety recall. General Motors will be submitting a supplemental chronology within two weeks.

573.6(c)(8): Dealers are to inspect for proper retention, and if required, repair as directed.

General Motors will provide the dealer bulletin and anticipates owner letter mail dates when available.

Pursuant to 577.11, General Motors does not plan to provide notice about reimbursement to owners because all involved vehicles are covered under the new vehicle warranty.

573.6(c)(10): General Motors will provide the dealer bulletin and owner letter under separate cover.



573.6(c)(11): General Motors' assigned recall number is 14208.

Sincerely,

A handwritten signature in black ink, appearing to read "B. Latouf". The signature is fluid and cursive, with the first letter of each name being capitalized and prominent.

Brian Latouf, Director  
Field Product Investigations & Evaluations

Attachment

573.6(c)(2)(3)(4)

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR  
PLUS INCLUSIVE DATES OF MANUFACTURE

<u>MAKE</u>	<u>MODEL SERIES</u>	<u>MODEL YEAR</u>	<u>NUMBER INVOLVED</u>	<u>INCLUSIVE MANUFACTURING DATES (FROM) (TO)</u>		<u>DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.</u>	<u>EST. NO. W/CONDITION</u>
Chevrolet	C/K	2015	5	01/28/2014	02/05/2014	Silverado HD Crew	*
Chevrolet	C/K	2015	4	01/27/2014	02/27/2014	Silverado HD Crew LTZ	"
Chevrolet	C/K	2015	34	01/08/2014	02/16/2014	Silverado HD Ext	"
Chevrolet	C/K	2015	3	01/17/2014	01/23/2014	Silverado HD Ext LTZ	"
Chevrolet	C/K	2015	3	01/30/2014	02/14/2014	Silverado HD Reg	"
GMC	C/K	2015	8	01/09/2014	02/14/2014	Sierra HD Ext	"
GMC	C/K	2015	1	01/30/2014	01/30/2014	Sierra HD Reg	"
GM Total:			58				

\* All involved vehicles will be corrected as necessary.

573.6(c)(2)(iv): N/A

14208