

**RECEIVED**

By Recall Management Division at 11:28 am, Jun 04, 2014

**Toyota Motor Engineering & Manufacturing North America, Inc.**

Vehicle Safety & Compliance  
Liaison Office  
Mail Code: S-104  
19001 South Western Avenue  
Torrance, CA 90501

June 4, 2014

Ms. Nancy Lummen Lewis  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Attn: Recall Management Division (NVS-215)  
1200 New Jersey Ave, SE  
Washington, D.C. 20590

Re: Recall # 14V-273  
Certain Toyota Sienna Spare Tire Assembly  
Part 573, Defect Information Report

Dear Ms. Lewis:

In connection with the above referenced matter, this supplements Toyota's letter of May 22, 2014.

The affected vehicle VIN range and corresponding number of affected vehicles is indicated below:

Identification of Affected Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Sienna	2011	TMMI	KA3DC	BS001016 - BS006090	January 10, 2003 - December 4, 2010
			*K3DC	BS001251 - BS103835	
	2004 - 2010		*K**C	7S000022 - AS343709	
			ZA2*C	4S000020 - 6S587362	

Total Number of Involved Vehicles:

419,520 units

Should you have any questions about this report, please contact me directly.

Sincerely,

A handwritten signature in black ink, appearing to read 'D. Kim', with a long horizontal stroke extending to the right.

Daniel Kim  
Assistant Manager  
Toyota Motor Engineering & Manufacturing  
North America, Inc.

cc: J. Timian  
F. Borris