



**RECEIVED**

By Recall Mangement Division at 7:05 am, Jul 25, 2014

Date: July 23, 2014  
P.O. Box 6300 • Sioux City, IA 51106-6300  
Phone: 712-252-6500 • Toll Free: 800-798-2002 • Fax: 712-252-6510  
www.wilsontrailer.com • e-mail: sales@wilsontrailer.com

MS Nancy Lummen Lewis  
Administrator for Enforcement  
NHTSA-NVS-200 Rm W46-421  
1200 New Jersey Avenue, SE  
Washington, DC 20590

RE: Wilson Trailer Company 000058  
Notice of Possible Defect

Dear MS Lewis

REPORT TO NHTSA

1. Manufacturer's name: Wilson trailer Company
2. Vehicle Identification: Wilson Livestock and Grain trailers manufactured between October 8, 2013 and July 18, 2014 With SAF Holland CBX Series air ride suspensions.
3. Total Number of Vehicles Subject to Recall: 681 U.S. Trailers
4. Percentage of Trailers Estimated to be Defective: > 1%
5. Description of Defect: Pivot bolts on CBX Series suspension assemblies supplied to Wilson Trailer Company by SAF Holland have been determined to be defective. 11,259 pivot bolts are potentially defective, resulting from possible cracks at the interface of the bolt head to the body of the bolt. The presence of the crack could result in separation of the bolt head and failure of the pivot bolt on one side of the axle/ suspension, resulting in the trailer becoming misaligned behind the tractor which would be immediately apparent to the driver.
6. History of Events: Wilson Trailer Company was notified by mail by SAF Holland, our suspension supplier, that they have identified a defect in the pivot bolts used in certain CBX Series suspensions and have instituted a recall. Their recall number is 14E024.
7. Description of Remedy: Customer will be provided a letter from Wilson Trailer Company identifying where to locate the serial number of the suspension(s) and a range of suspension serial numbers deemed to contain the defective pivot bolts. Customer will notify Wilson Trailer Company of result and will be instructed to contact their dealer or authorized repair facility for replacement of the pivot bolts. Replacement of the pivot bolts will be provided at no cost to the customer. Customers will be notified of the recall by first class mail after receipt of the recall number.
8. Copies of Notices: Se enclosed copy of Safety Recall Notice, dealer letter, and customer letter.
9. Manufacturer's Campaign Number: 926P

Respectfully Submitted,

  
Clarence Dahl  
Technical Service & Claims Mgr.