

July 25, 2014

Subject: Safety Recall 514-F – RollTek Seat
NHTSA # 14V-283
EXPIRATION DATE: NONE
The VINs are listed on the back of this page

USA Customer
99 Customer Address
SOMETOWN, USA
US

210705

Dear Peterbilt Customer,

IMPORTANT SAFETY RECALL

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain vehicles manufactured between October 30, 2009 and May 21, 2014 with IMMI RollTek seats. Your vehicle has been identified as having been manufactured within this time period and may contain a defect. Due to a wiring defect in the electrical harness in the affected vehicles, the RollTek seat air bag warning indicator will not illuminate when no power is supplied to the RollTek Control Unit when the ignition key is in the (on) position and the airbag is disabled.

When there is no power to the RollTek Control Unit, the driver is not warned of a problem with the side air bag system and he or she may continue to operate the vehicle, thereby increasing the risk of injury or severity of injury to vehicle occupants in the event of a rollover.

<i>The problem is...</i>	Defective wiring to RollTek seat electronic control unit
<i>Correction...</i>	Install new wiring harness
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment


Peterbilt has initiated a recall to install a wiring harness in your truck. **Parts are expected to be available the week of July, 14 2014. Customers may schedule repairs any time after July 28, 2014, but are encouraged to confirm parts are available a few days prior to the appointment.** To find your nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take approximately 0.7 hours, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>. Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Doug Gunter
Director of Warranty