

October 8, 2014

IMPORTANT SAFETY RECALL

NHTSA VOLUNTARY SAFETY RECALL CAMPAIGN #14E-055

Dear Owner of Thermo King 1100W, 1500W and 2000W Inverters sold between May 15, 2014 and July 31, 2014 as an option with TriPac EVOLUTION and TriPac E:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Thermo King Corporation has decided that a defect which relates to motor vehicle safety exists in its **Thermo King 1100W, 1500W and 2000W Inverters sold between May 15, 2014 and July 31, 2014 as an option with TriPac EVOLUTION and TriPac E**. The inverters may spark or overheat, resulting in a potential fire.

Immediately turn off and discontinue use of the currently installed Thermo King inverter. Based upon the availability of alternative replacement inverters from Thermo King, your authorized Thermo King Dealer will provide you with the option of having a new replacement inverter installed in your vehicle, or you will be provided with a refund for the full purchase price of the original Thermo King inverter. The replacement of the inverter will be performed at no cost to you and will take approximately 0.5 hours. Please contact your authorized Thermo King Dealer on or after October 13, 2014 to schedule an appointment to address this inverter issue.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of the notice to the vehicle lessee within ten days.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE, Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-429-9153) or go to <http://www.safercar.gov>, if you believe that Thermo King has failed or is unable to remedy your equipment without charge.

Thermo King regrets any inconvenience this recall may cause you. If you have any questions regarding this recall, you may call Thermo King at **866-776-2708**.

Sincerely,

Thermo King Corporation