



November 13, 2014



FIAT 500L – P42 Knee Airbag Module **Knee Airbag Module Disposal Fee Reimbursement**

Dealer Service Instructions for Safety Recall P42/ NHTSA 14V-481(Knee Airbag Module) has been revised to include a Labor Operation Code for Knee Airbag Module disposal reimbursement.

Special Service Labor Operation (LOP) Code **95-42-42-01** is now available for Studios to be reimbursed for the proper disposal of Knee Airbag modules replaced in Safety Recall P42. Dealers will be reimbursed a flat fee of \$15.00 for each Knee Airbag Module replaced under this recall. *Note: Invoices documenting the proper Knee Airbag disposal must be retained in the event of an audit.*

If a previous P42 recall claim has been submitted and the airbag was properly disposed of, an “other” Type (O) Continuation claim can be submitted using Special Service LOP 95-42-42-01.

Please reference Warranty Information Center (WIC) article #2536 for additional claim processing information.

In addition, for published procedures/guidelines for handling and disposal of supplemental restraints such as airbags go to: *DealerCONNECT > Service Tab > TechCONNECT > Service Info (enter VIN) > Section 10- Restraints/Standard Procedure.*

Thank you for your continued support.