



NOTICE TO DAIMLER TRUCKS NORTH AMERICA LLC

***** IMPORTANT SAFETY RECALL *****

NHTSA Recall 14E-056

DTNA (Daimler Trucks North America LLC)
11550 Statesville Blvd.
Cleveland, NC 27013-8114

Dear DTNA:

This notice is being sent to you as a follow up to the original letter sent on or around October 20, 2014. Following discussions between DTNA and Agility, it has been determined that several of the systems identified as being part of the above recall did not contain motion hoses. The following system part numbers and vehicles will be removed from the recall:

<u>System Part Number</u>	<u>VIN(s)</u>
24708001	GG9183-GG919 GG9198-GG9200
24712001	GE1320 GJ3059
24708021	FU3884-FU3889 GF6349

No further action is required on your part regarding the above referenced vehicles.

The following system part numbers and vehicles are still identified as containing potentially defective equipment and remain part of the recall. Agility will work diligently with Ryder and Penske, whom DTNA sold the systems, in order to replace the defective hose assemblies in accordance with the recall.

<u>System Part Number</u>	<u>VIN(s)</u>
23714031 (LHS) and 23712021 (RHS)	1FUJGBD [REDACTED] 1FUJGBD [REDACTED] 1FUJGBD [REDACTED] 1FUJGBD [REDACTED] 1FUJGBD [REDACTED] 1FUJGBD [REDACTED]
23710031 (LHS) and 23708031 (RHS)	FW1713 FW1714 FW1715

FW1716
FW1717
FW1718
FW1719
FW1720

Please call Agility at (949) 267-7745 or send us an email at support@agilityfs.com if you have any questions or need further assistance.

Thank you for your attention to this important matter.

Sincerely,

Agility Fuel Systems

A handwritten signature in black ink, appearing to read 'Yoshio Coy', with a stylized, cursive script.

Yoshio Coy

Director of Product Support